

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

not Authorized
in
more 5
7/8/24
1/5 \$1600
the photo attached
3 days

VEHICLE No: SLF 2870T

1PC	REAR BUMPER	<i>grated</i>	\$654.20	✓
1PC	REAR BUMPER SIDE O/S	<i>cut/torn</i>	\$285.60	✓
1PC	REAR BUMPER REFLECTOR O/S	<i>^^</i>	\$151.00	X
1PC	TAILLAMP O/S	<i>^^</i>	\$520.80	X
1PC	REAR FENDER O/S	<i>^</i>	\$971.20	X
1PC	REAR FENDER OUTER PROTECTOR O/S	<i>grated</i>	\$288.60	✓
1PC	REAR FENDER UNDER CLOTH O/S	<i>torn</i>	\$241.50	✓
1PC	REAR SHOCK ABSORBER O/S	<i>^^</i>	\$299.80	X
1PC	REAR WHEEL HUB BEARING O/S	<i>^^</i>	\$520.00	X
			\$3,932.70	
			LESS 20%	\$3,146.16

S.NETT

1SET	REAR BUMPER CLIPS	<i>new</i>	\$50.00	✓
1SET	REAR FENDER UNDER CLOTH CLIPS O/S	<i>new</i>	\$50.00	✓
1PC	REAR SPORT RIM O/S	<i>R</i>	\$600.00	X
TO CEHCK WIRING			\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR			\$80.00	30
TO DISMANTLE & REFX REAR WINDSCREEN			<i>^^</i> \$150.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY			<i>^^</i> \$120.00	X
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM			<i>^^</i> \$180.00	X
TO SPRAY RUST PROOFING			<i>^^</i> \$50.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS			\$800.00	300
TO PUTTY & SPRAY PAINTING			\$800.00	400
TOTAL			\$6,076.16	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-1469.9
202
1175.92
100
750
2025.92
202
1620