



Your Ref : WQ.CY.4316.03.24

Date: 27th Aug 2024

Our Ref : CS/LAW24080124/Rvp3e2

M/s Winston Quek & Company

2 Havelock Road,
#06-06, Havelock II
Singapore 059763
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBJ 8204A
INSURED VEHICLE: GBK 4361A
ACCIDENT ON 30/01/2024**

Instruction was received to inspect the vehicle Reg. No. FBJ 8204A. The inspection was conducted on 08/08/2024 at the premises of M/s Dstreet Custom Enterprise Center, 20 Bukit Batok Crescent #07-13, Singapore 658080.

The following vehicle information was recorded:

Registration Number	: FBJ 8204A
Make/Model	: Harley Davidson 883 Roadster ABS XL883R
Year of Registration	: 2014
Body Colour	: Black
Chassis Number	: 5HD4CS2CXEC408594
Engine Capacity	: 883 cc
Speedometer Reading	: Not Available

The vehicle sustained damages at the front portion and n/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 10,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S 105.00)
Nett Liability	<u>S\$ 9,895.00</u> =====

Vehicle Inspected By:



MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor



K.K.LAU
*MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.