

Not Notion
L/Sy & 2600f

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD910H

AAD2408-011

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD910H

VF1ABL15AUC283392

200303878K

RENAULT

LATITUDE

1/8/2024

SKK9237L/ China

29/12/2017

06 AUG 2024

PART

LIST

- 1 BUMPER COVER FRT
- 1 BUMPER BRACKET KIT FRT RH
- 1 BUMPER RETAINER FRT RH
- 1 BUMPER FOG LAMP GRILLE RH
- 1 RADIATOR GRILLE FRAME
- 1 FRAME FULL SUPPORT PANEL
- 1 FENDER PANEL FRT RH
- 1 FENDER PANEL INNER FRT RH
- 1 WHEELARCH FRT RH
- 1 WIPER RESERVOIR
- 1 HEADLAMP RH

\$	Bu/cm	747.20	✓
\$	Sn	101.40	X
\$	cm	101.40	✓
\$	Sn	207.21	X
\$	Sn	686.00	X
\$	Sn	592.70	X
\$	Ry	437.10	✓
\$	n	838.40	X
\$	DIV	191.40	✓
\$	nd	179.60	✓
\$	mg cm	743.60	✓
\$		4,826.01	
10% \$		482.60	
\$		4,343.41	

Specical Nett

- 1 FRONT BUMPER CLIP
- 1 FENDER LINER CLIP

\$	na	66.00	✓
\$	na	65.00	✓

TOTAL	\$	131.00
TOTAL PARTS	\$	4,474.41

LABOUR

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 440f

Trans-cab Auto Services Pte Ltd**AAD2408-011**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD910H

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	400
To Rust-Proofing Of The Affected Areas.	\$	170.00	30
To check steering geometry and computer wheel alignment	\$	220.00	60
To Check Electrical Lighting Concerned.	\$	170.00	20
TOTAL	\$	6,560.00	

Over All Total	\$	15,377.82
-----------------------	-----------	------------------

(LUMP SUM)**Repair Days****06 DAYS***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: