



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref:	CS/TP24080127/Uvp3m4	
BLK 1 KAKI BUKIT AVE 6		Date:	19/08/2024	
#01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		Code:	TP149	
ON BEHALF OF AL CAR LEASING PTE. LTD.				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	-	Veh. Inspected	SMH 8369M	
Policy No.	-	Coverage	0	
Claim No.	-	Excess	\$0.00	
Assign From	-	Assign Date	08/08/2024	
2. Vehicle Details				
Make & Model	TOYOTA COROLLA ALTIS (A)	C.C	1598	
Engine No.	1ZRX432337	Year of Reg.	29/08/2014	
Chassis No.	MR053REH104513051	Colour	WHITE	
Odometer	487498 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	205/55R16	BEARWAY	6	
L/H Front Tyre	205/55R16	BEARWAY	6	
R/H Rear Tyre	205/55R16	ZEXTOUR	6	
L/H Rear Tyre	205/55R16	ZEXTOUR	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/08/2024	Inspection Date	08/08/2024	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				