

ASS. REC. BY:

REF:

AIG! 15/AIG24080128/Knp3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Prell. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

ESTIMATE RC AUTO

Not Authorized
Repair by paint
5 days
@ 6034-90

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722
Tel : 97619383 Email: rcauto5555@gmail.com
Reg. No. 53199168K

SKB 1913 T

Date: 15.08.2024

Quantity	Description/Particular	Unit Price	Amount
1 PC	REAR BOOTLID 1112.45	By 1207	75
1 PC	REAR BUMPER SPOILER lower 463	By 463	60
1 PC	REAR END PANEL 731.35	By 892	05
1 PC	REAR LAMP 768.10	CM 955	60
1 PC	REAR BOOTLID GANISH 925.60	my CM 1155	60
1 PC	REAR BUMPER	By 468	20
1 PC	REAR END PANEL GANISH	my 316	20
1 PC	REAR BOOTLID LAMP	CM 631	90
1 PC	REAR BUMPER TOWING COVER	Oct 26	80
1-2 PCS	REVERSE SENSOR@220	short 440	00
	Per buyer reinforcement By 369.00	TOTAL	6557 70
		LESS 25	4918 27
	TO REMOVE REAR WINDSCREEN	180	00
	TO RESPRAY AFFECTED PARTS	800	00
	TO REPLACE ABOVE PARTS	800	00
	TO CHECK WIRING	30	00
	ANTI RUST	50	00
		TOTAL	6778 75

Received the above goods in good order and condition

LKK Auto Consultants hence notify

the Repairer of the following:

- To survey before/after spray painting
- To replace damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary items must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature E.&O.E.

Date:

for

RC AUTO

Received by

Authorised Signature