

源摩哆廠

GUAN MOTOR WORKS

Business Regn No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 LLP 9742 6003

REPAIR ESTIMATE SMJ9750C

Not Worked
L1 Lamp &
Penny After Rain
5 days

No.	Qty	List Items	
1	1	Rear bumper ✓	\$ Bu 828.20 ✓
2	2	Rear bumper side reflector ✗	\$ Bu 163.60 ✗
3	2	Rear bumper side retainer ?	\$ 328.80 ?
4	2	Rear bumper corner retainer ?	\$ 181.20 ?
5	1 set	Rear bumper clips ✓ (Put as S/N items = \$30)	\$ Bu 60.00 ✓
6	1	Rear bumper inner reinforcement ? (More clear photos)	\$ Bu 598.20 ✓
7	2	Taillamp ✓ (RH side only)	\$ Bu 1,136.20 ✓
8	1	Rear boot lid ✓	\$ Bu 1,294.10 ✓
9	1	Rear boot top centre "TOYOTA" logo ✓	\$ Bu 58.70 ✓
10	1	Rear boot RH "COROLLA" emblem ✓	\$ Bu 45.60 ✓
11	1	Rear boot RH "ALTIS" emblem ✓	\$ Bu 47.73 ✓
12	1	Rear boot RH side lamp ✓	\$ Bu 528.20 ✓
13	2	Rear boot hinge ✗	\$ Bu 189.60 ✗
14	1 set	Rear boot inner trim clips ✗	\$ Bu 80.00 ✗
15	1	Rear boot weatherstrip ✓ (Put as S/N items)	\$ Bu 238.00 50% ✓
16	1	Rear boot top lock ✓	\$ Bu 522.40 ✓
17	1	Rear boot lower lock catch ✗	\$ Bu 37.80 ✗
18	1	Rear end panel ? Repair	\$ 1,008.40 ?
19	1	Rear end panel top garnish ✓	\$ Bu 327.80 ✓
			\$ 7,674.53
Less 25%			\$ 1,918.63
Total :			\$ 5,755.90

Special Nett Items		
20	1 set Rear reverse sensor ✓ 200	\$ Pd 300.00 200% ✓
21	1 set Rear end panel sealant ?	\$ 60.00 ?
Total :		\$ 360.00

Labour		
1	Labour Charges for remove/refit, cutting/welding and replacement of damages. ✓ 500	\$ 1,000.00 ?
2	To putty and spray Spray Paintings charges. ✓ 600	\$ 1,000.00 600
3	To check wirings and lightings. ✓	\$ 40.00 200
4	To remove, refit rear bumper reverse sensors. ✓	\$ 80.00 500
5	To remove, refit rear upholstery & attachments. ✓	\$ 120.00 600
6	To remove, refit rear boot lid fittings. ✓	\$ 80.00 500
7	To supply and apply anti-rust treatment ?	\$ 80.00 ?
Total :		\$ 2,400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Parts and Labour : \$ 8,515.90