

源摩哆廠

GUAN MOTOR WORKS

Business Regn No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 LVP: 9742 6003

REPAIR ESTIMATE SMJ9750C

Not Noted

L1 Imp B

Heavy After Rain

5 days

No.	Qty	List Items	
1	1	Rear bumper	\$ Bu 828.20 ✓
2	2	Rear bumper side reflector	\$ Bu 163.60 X
3	2	Rear bumper side retainer	\$ 328.80 ?
4	2	Rear bumper corner retainer	\$ 181.20 ?
5	1 set	Rear bumper clips	\$ Bu 60.00 ✓
6	1	Rear bumper inner reinforcement	\$ Bu 598.20 ✓
7	2	Taillamp	old car \$ 1,136.20 4
8	1	Rear boot lid	\$ Bu 1,294.10 ✓
9	1	Rear boot top centre "TOYOTA" logo	\$ Bu 58.70 ✓
10	1	Rear boot RH "COROLLA" emblem	\$ Bu 45.60 ✓
11	1	Rear boot RH "ALTIS" emblem	\$ Bu 47.73 ✓
12	1	Rear boot RH side lamp	\$ Bu 528.20 ✓
13	2	Rear boot hinge	\$ Bu 189.60 X
14	1 set	Rear boot inner trim clips	\$ Bu 80.00 X
15	1	Rear boot weatherstrip	\$ Bu 238.00 50% ✓
16	1	Rear boot top lock	\$ Bu 522.40 ✓
17	1	Rear boot lower lock catch	\$ Bu 37.80 X
18	1	Rear end panel	\$ 1,008.40 ?
19	1	Rear end panel top garnish	\$ Bu 327.80 ✓
			\$ 7,674.53
Less 25%			\$ 1,918.63
Total :			\$ 5,755.90

	Special Nett Items	
20	1 set Rear reverse sensor	\$ Pd 300.00 200% ✓
21	1 set Rear end panel sealant	\$ 60.00 ?
Total :		\$ 360.00

	Labour	
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,000.00 ?
2	To putty and spray Spray Paintings charges.	\$ 1,000.00 60% ✓
3	To check wirings and lightings.	\$ 40.00 20% ✓
4	To remove, refit rear bumper reverse sensors.	\$ 80.00 50% ✓
5	To remove, refit rear upholstery & attachments.	\$ 120.00 60% ✓
6	To remove, refit rear boot lid fittings.	\$ 80.00 50% ✓
7	To supply and apply anti-rust treatment	\$ 80.00 ?
Total :		\$ 2,400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Parts and Labour : \$ 8,515.90