



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2503854

INV Date 19/06/2025

Reference CD/LPC24080133/Kma3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKW 89T
Insured Veh. GBH 1311E
Claim No. 24/24/24/VC05/029660
Policy No. Z24VC05022387
Accident Date 06/08/2024
Inspection Date 16/09/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CD/LPC24080133/Kma3q2(N)	
			Date: 19/06/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 1311E	Veh. Inspected	SKW 89T
	Policy No.	Z24VC05022387	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/029660	Excess (\$)	0.00
	Assign From	ERIC WOO	Assign Date	16/09/2024
2. Vehicle Particulars & Condition				
	Make & Model	PORSCHE PANAMERA (A)	c.c	2995
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	WP0ZZZ97ZLL102360	Colour	METALLIC BLUE
	Odometer	91734 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/45 R19	MICHELIN	8 mm
	L/H Front Tyre	255/45 R19	MICHELIN	8 mm
	R/H Rear Tyre	295/40 R19	MICHELIN	7 mm
	L/H Rear Tyre	295/40 R19	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/08/2024	Inspection Date	16/09/2024
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 89T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BENT	6,155.52	6,155.52
1	REAR BUMPER	CRACKED	4,127.56	4,127.56
1	REAR BUMPER LOWER SPOILER	DENTED / CUT	1,783.52	1,783.52
1	REAR BUMPER REFLECTOR LH	CRACKED	151.56	151.56
1	REAR PANAMERA EMBLEM	NECESSARY	413.84	413.84
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	480.00	-
	LESS 10% DISCOUNT		-1,311.20	-1,263.20
			11,800.80	11,368.80
	<u>SPECIAL NETT ITEMS</u>			
1	SEALANT (SN)	NECESSARY	40.00	40.00
			40.00	40.00
	<u>LABOUR</u>			
	TO REMOVE +REFIX REAR WINDSCREEN.		350.00	250.00
	TO REMOVE +RENEW PARTS.		650.00	500.00
	TO SPRAY PAINT.		800.00	600.00
			1,800.00	1,350.00
	GRAND TOTAL		13,640.80	12,758.80
	RECOMMENDED COST OF REPAIRS			12,758.80

Report Ref No. CD/LPC24080133/Kma3q2(N)

MARKET VALUE: \$387,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$147,395.00=NETT VALUE: \$239,605.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKW 89T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



PHOTOGRAPHS FOR VEHICLE NO. : SKW 89T



PHOTOGRAPHS FOR VEHICLE NO. : SKW 89T







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SKW 89T





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SKW 89T

