



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF24080135/Kqh3m4(N)
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	03/02/2025
HEMMANT ROAD SINGAPORE 438675			
ATTN: YAP RAY KAI JOEL		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 3069E	Veh. Inspected	SFB 9027H
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2024/036(CF)	Excess (\$)	0.00
Assign From	YAP RAY KAI JOEL	Assign Date	07/08/2024
2. Vehicle Particulars & Condition			
Make & Model	BMW X3 (A)	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	WBAPC72070WG60464	Colour	BLACK
Odometer	219502 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/50R18	MICHELIN	5 mm
L/H Front Tyre	235/50R18	MICHELIN	5 mm
R/H Rear Tyre	235/50R18	MICHELIN	4 mm
L/H Rear Tyre	235/50R18	MICHELIN	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/07/2024	Inspection Date	20/01/2025
Survey held at	176 SIN MING DRIVE #01-11, SINGAPORE 575721		
Repairer	ABWIN SERVICE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	