

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road
Springleaf Tower #16-00
Singapore 079909

Tel: 63896111
Attn: Motor Claim Department

Fax: 6221033

Your Ref No: TP 0824-8179
Claim Type: Third Party
Accident Date: 06 August 2024
TP Veh Reg No: GBB3103H

*Not Authorized
in
mean
5/514
1/5 H 6700
whispering
5-Long*

Estimate No: **EST1511623**
Date: 07 Aug 2024
Policy No: PNPV2023-00003816
Veh Reg No: SJS7022Y
Make/Model: TOYOTA PREVIA AERAS
2.4 CVT MR
Chassis No: JTEGD56M607164883
Engine No: 2AZ1A82114
Reg. Date: 21 Aug 2018

Estimate Repair Cost to Vehicle No: SJS7022Y

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR BUMPER	890.60	1 PC	890.60	
2 REAR BUMPER SIDE RETAINER (INNER) - LH/RH	87.00	2 PC	174.00	X
3 REAR BUMPER SIDE RETAINER (OUTER) - LH/RH	78.60	2 PC	157.20	X
4 REAR BUMPER CLIPS	5.50	10 PC	55.00	
5 REAR BUMPER FOAM	107.60	1 PC	107.60	X
6 REAR END PANEL (OUTER)	1,126.10	1 PC	1,126.10	
7 REAR END PANEL TOP GARNISH	380.50	1 PC	380.50	
8 TAILGATE	2,617.30	1 PC	2,617.30	
9 TAILGATE GLASS MOULDING	37.60	1 PC	37.60	
10 TAILGATE "TOYOTA" WORDINGS	65.00	1 PC	65.00	
11 TAILGATE TOYOTA LOGO	72.20	1 PC	72.20	
12 TAILGATE "PREVIA" WORDINGS	78.00	1 PC	78.00	
13 TAILGATE LOWER OUTER CHROME GARNISH	311.80	1 PC	311.80	
14 TAILGATE UPPER OUTER CENTER GARNISH	457.70	1 PC	457.70	
15 TAILGATE LAMP - LH/RH	949.70	2 PC	1,899.40	1 PC
16 TAILGATE WEATHERSTRIP	504.40	1 PC	504.40	
17 TAILGATE TOP LOCK	665.50	1 PC	665.50	
18 TAILGATE LOWER LOCK STRIKER	65.60	1 PC	65.60	X
19 TAILGATE NUMBER PLATE LAMP - LH/RH	165.60	2 PC	331.20	X
20 TAILGATE LOCK SWITCH OPENER	243.20	1 PC	243.20	X
21 TAILGATE INNER TRIM	680.70	1 PC	680.70	
22 REAR WIPER BLADE	67.90	1 PC	67.90	X
23 REAR WIPER ARM	108.90	1 PC	108.90	X
24 TAIL LAMP - LH/RH	729.60	2 PC	1,459.20	X
			12,556.60	
			Less 25%	-3,138.80
				9,417.80
Special Net				
25 REAR NUMBER PLATE WITH CASING	35.00	1 PC	35.00	X
26 SEALANT Rear windscreen	20.00	2 PC	40.00	
27 SPONGE TAPE Rear windscreen	20.00	1 PC	20.00	
28 REVERSE CAMERA	350.00	1 PC	350.00	X
29 REAR BUMPER PARKING SENSOR (4PC SET)	400.00	1 PC	400.00	X
				845.00
Labour				
30 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PORTIONS-	900.00	1 JOB	900.00	600
31 TO RESPRAY PAINT ON ACCIDENT PORTIONS-	900.00	1 JOB	900.00	800
32 TO CHECK WIRING-	30.00	1 JOB	30.00	20
33 TO REMOVE, REFIT REAR GLASS-	150.00	1 JOB	150.00	120
34 TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	150.00	1 JOB	150.00	60

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

35	TO REMOVE, REPLACE REAR BUMPER SENSOR-	80.00	1 JOB	80.00	30
36	TO TUFFKOTE-	90.00	1 JOB	90.00	50
37	TO TRANSFER TAILGATE FITTINGS-	100.00	1 JOB	100.00	60
					2,400.00

Total	12,662.80
Add GST @ 9%	1,139.65
Total Amount Payable SGD	13,802.45

SINGAPORE DOLLAR THIRTEEN THOUSAND EIGHT HUNDRED TWO AND CENTS FORTY FIVE ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8469.08
217
6775

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE