

ASS. REC. BY:

REF:

CS/FCI24080138/Knh3

Kenneth

ASSIGNMENT

GBC 25825

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

EH not ready

16/8 L1 Rpt @ 1600h. Calm (Red. \$809.10, 33%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Prints

Others

TOTAL

Veh No:

SALE 7150

Yr Regn:

07, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV200

C.C.

1598

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

32459

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1YAAM 208 0002018

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

185/80R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

4

mm

Rear

R/Bal.

P

mm

L/Bal.

4

mm

L/Bal.

P

mm

D.O.A.

5/18/24

D.O.I.

12/8/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

Not Authorized
11 Sep @ 1600h
Recovery After Party
4 days

GBC 2562 S

Date : 15.08.2024

Quantity	Description/Particular	Unit Price	Amount	
	REAR BUMPER <i>Bulnel</i>	NETT	524	80
	REAR LAMP <i>Bro</i>	NETT	299	30
	REAR BUMPER RETAINER <i>diy</i>	NETT	35	00
		TOTAL	859	10
	LOWER LID	<i>cm</i>	350	00
	LABOUR CHARGES TO REPAIR		400	00
	<i>Spray Painting</i>		<i>800</i>	<i>550</i>
			1609	10

Received the above goods in good order and condition

2409 1

for

RC AUTO

Received by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signature