

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

23-08-24

Date Of Accident : 07/08/2024

OUR REF : GBH 8747K/T/24

MOMENTS LOFT LOGISTICS PTE LTD

1 Kaki Bukit Road

#05-03/04

Singapore 415934

ESTIMATE BILL ON VEH. NO. : GBH 8747K

VEH. MODEL : TOYOTA HIACE

CHASSIS NO : JTFHT02P000245070

LIST ITEM

Front Door - RH

R 1,712.45 X

Front Door Outer Handle - RH

cu7 274.45 /

Front Door Center Pillar

sp/suf 681.90 /

Front Door Window Glass Outer Moulding

cu7 172.55 /

Sliding Door Outer Handle RH

cu7 161.35 /

Sliding Door - RH

R 1,718.25 X

Side Mirror - RH

cu7 974.40 /

Front Door Window Glass - RH

cu7 561.60 /

Side Mirror Control Switch

mlt/hxtor 316.40 /

6,573.35

Less Discount 25%:

1,643.34

4,930.01

SPECIAL NETT ITEM

Front Door R.O.C Sticker - RH

net 25.00 /

Front Door Window Glass Solar Film

net 180.00 X

Body Advertisement Sticker - RH

net 2,200.00 1800

Not Authorized
an
morans
8/8/24
2/5 & 4300
take photo after rep-
6 days

Like morans
Date In/Out: 07/08/24 to 16/08/24

LABOUR CHARGE

To Check Side Mirror Wiring.

80.00 20

To Respray Affected Areas.

750.00 600

To Renew Damaged Parts, Straighten and Repair Aligned All Parts.

850.00 600

9,095.01

GST 9%: 818.55

TOTAL AMOUNT: 9,913.56

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p. 314765
252
2356.99
1825
1220
5401.99
202
4371