



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMG 9565L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
10	FRT BUMPER CLIP	NECESSARY	\$20.00	\$20.00
1	LAMP ASSY-FRONT TURN SIGNAL, LH	NOT NECESSARY	\$165.00	\$0.00
1	BRACKET-FR BUMPER SIDE, LH	NOT NECESSARY	\$14.00	\$0.00
1	COVER-FR BUMPER	NOT NECESSARY	\$573.00	\$0.00
1	MOULDING-FRONT BUMPER, LH	NOT NECESSARY	\$29.00	\$0.00
1	GRILLE-FRONT BUMPER SIDE, LH	NOT NECESSARY	\$34.00	\$0.00
1	LIP ASSY-FRONT BUMPER	NOT NECESSARY	\$76.00	\$0.00
1	LAMP ASSY-HEAD, LH	SCRATCHED	\$1,205.00	\$1,205.00
	LESS 20.00% DISCOUNT		(\$423.20)	(\$245.00)
			\$1,692.80	\$980.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$40.00	\$20.00
			\$40.00	\$20.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CARRY OUT ACCIDENT BODY REPAIR - FRT BUMPER / SUPPORT PANEL		\$840.00	\$420.00
	COMPLETE PUTTY AND SPRAY PAINT ALL AFFECTED AREA - FRT BUMPER / FRT BUMPER LIP		\$1,140.00	\$760.00
	TO REALIGN FRT HEADLAMP		\$40.00	\$40.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AFTER ACCIDENT REPAIR		\$180.00	\$180.00
	TO PERFORM PREPROGRAMME AFTER ACCIDENT REPAIR		\$180.00	\$180.00
	TO REPAIR FRONT BUMPER		\$210.00	\$210.00
	TO REPAIR FRONT LHS FENDER PANEL		\$210.00	\$210.00
			\$2,800.00	\$2,000.00

GRAND TOTAL			\$4,532.80	\$3,000.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,000.00

Report Ref No: CS/FCI24080141/Rqh3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.