



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24080142/Unh3
75 BRAS BASAH ROAD	Date:	27/08/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 886C	Veh. Inspected	PD 1343T
Policy No.	-	Coverage	0
Claim No.	MT/1289747-002	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	08/08/2024

### 2. Vehicle Details

Make & Model	TOYOTA HIACE COMMUTER GL 2.8 (A)	C.C	2754
Engine No.	1GD9161387	Year of Reg.	15/08/2023
Chassis No.	GDH2232005698	Colour	WHITE
Odometer	63581 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/80R15	ECOPIA	7
L/H Front Tyre	195/80R15	ECOPIA	7
R/H Rear Tyre	195/80R15	BRIDGESTONE	7
L/H Rear Tyre	195/80R15	BRIDGESTONE	7

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	06/08/2024	Inspection Date	19/08/2024 (11:04)
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days