

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOB. Y@KAKI BUKIT
SINGAPORE 417883
TEL: 92327457

TO	: NTUC	DATE	: 12/8/2024
VEHICLE NO	: SMQ6449G (2019)		
VEHICLE MODEL	: KIA CERATO	Veron.	
CHASSIS NO	: KNAF1416ML5058017		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>torn</i>	1	\$ 633.50	\$ 633.50
2	FRONT BUMPER SIDE HOLDER <i>damaged</i>	1	\$ 31.40	\$ 31.40
3	FRONT BUMPER SIGNAL LAMP <i>crack</i>	1	\$ 189.50	\$ 189.50
4	FRONT BUMPER SIGNAL LAMP GARNISH <i>Del'd</i>	1	\$ 74.90	\$ 74.90
5	FRONT BUMPER SIGNAL LAMP GARNISH <i>Del'd</i>	1	\$ 419.40	\$ 419.40
6	FRONT BUMPER REINFORCEMENT <i>Del'd</i>	1	\$ 94.80	\$ 94.80
7	FRONT BUMPER SPONGE <i>torn</i>	1	\$ 69.10	\$ 69.10
8	FRONT BUMPER SIDE AIR DUCT <i>Del'd</i>	1	\$ 326.70	\$ 326.70
9	FRONT BUMPER LOWER GARNISH <i>Del'd</i>	1	\$ 303.40	\$ 303.40
10	FRONT BUMPER FOG LAMP <i>gap</i>	1	\$ 68.40	\$ 68.40
11	FRONT BUMPER FOG LAMP BRACKET <i>gap</i>	1	\$ 119.60	\$ 119.60
12	FRONT BUMPER LOWER STIFFENER <i>new</i>	1	\$ 328.60	\$ 328.60
13	FRONT GRILLE <i>gap</i>	1	\$ 41.40	\$ 41.40
14	FRONT GRILLE LOGO <i>gap</i>	1	\$ 1,855.90	\$ 1,855.90
15	HEADLAMP <i>crack</i>	1	\$ 41.90	\$ 41.90
16	HEADLAMP LOWER BRACKET <i>new</i>	1	\$ 691.50	\$ 691.50
17	FRONT SUPPORT PANEL <i>new</i>	1	\$ 430.80	\$ 430.80
18	FRONT FENDER <i>new</i>	1	\$ 195.10	\$ 195.10
19	FRONT FENDER INNER SHIELD <i>new</i>	1	\$ 439.40	\$ 439.40
20	FRONT LOWER ARM <i>gap</i>	1	\$ 436.90	\$ 436.90
21	FRONT KNUCKLE ARM <i>gap</i>	1	\$ 310.40	\$ 310.40
22	FRONT WHEEL HUB C/W BEARING <i>new</i>	1	\$ 328.60	\$ 328.60
23	FRONT SHOCK ABSORBER	1	\$ 328.60	\$ 328.60

TOTAL PRICE: \$ 7,431.20
LESS 10% \$ 743.12
SUB TOTAL PRICE: \$ 6,688.08

373710

3363.39

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	FRONT GRILLE CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
3	FRONT FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
4	COOLANT <i>new</i>	1	\$ 50.00	\$ 50.00
5	FRONT WHEEL RIM <i>crack</i>	1	\$ 800.00	\$ 800.00
6	FRONT TYRE <i>new</i>	1	\$ 280.00	\$ 280.00
TOTAL :				\$ 1,210.00

480

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 800.00	600	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	150.00	40	
5	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	\$ 120.00	X	
6	TO REMOVE RADIATOR & TO TOP UP COOLANT	\$ 120.00	X	
7	TO REMOVE FRONT UNDERCARRIAGE	\$ 350.00	X	
8	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80	
TOTAL:		\$ 2,940.00		

ESTIMATE REPORT

TOTAL PARTS COST:	\$	7,898.08
TOTAL LABOUR COST:	\$	2,940.00
TOTAL REPAIR COST:	\$	10,838.08

1150

Total: 4993.39

L/S: HK ✓
05 Days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CHV22R NO: 121800003032

APRICE NO: 2015 0113 7

VCCB2AL DYAL: 30021034

WVKE \ MODT: 1000111000

ESTIMATE

1ST: 01/11/2014 01/11/2014 01/11/2014 01/11/2014

YU001A @ KAKI BUKU

1 KAKI BUKU AVENUE 2 BTK C 401-01 \ 01-34 21001000 01/11/2014

HVA WENO 2014 PAINTING WORKSHOP