



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authorized

15 August 2024

REG NO. : SMG 3706 L
MAKE/MODEL : HONDA VEZEL

like
maras
8/8/24
2/5 \$ 5100
Average. Average
6 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding <i>del</i>	\$ 80.60 121.80 ✓
1	Rear tailgate <i>Body 100</i>	\$ 1099.00 1,287.60 ✓
2	Rear tailgate dampers <i>11</i>	\$ 331.60 X
1	Rear tailgate inner trim board <i>del/cro</i>	\$ 225.00 ✓
1	Rear tailgate inner pull pocket <i>11</i>	\$ 32.00 X
2	Rear tailgate lamps <i>n/s cro o/s n1</i>	\$ 280.40 570.00 1/2 C
1	Rear tailgate lock <i>but</i>	\$ 180.60 269.50 ✓
1	Rear tailgate logo <i>del</i>	\$ 40.30 ✓
1	Rear tailgate outer garnish <i>cro</i>	\$ 185.50 ✓
1	Rear tailgate rubber <i>11</i>	\$ 180.90 227.00 ✓
1	Rear tailgate "VEZEL" emblem <i>del</i>	\$ 56.20 ✓
2	Rear taillamps <i>n/s cro o/s n1</i>	\$ 520.40 1,390.00 1/2 C
1	Rear end panel <i>11/3ent</i>	\$ 517.00 585.80 ✓
1	Rear end panel inner garnish <i>11</i>	\$ 160.50 ✓
1	Rear keyless sensor (1 set) <i>su</i>	\$ 189.50 X
1	Rear bumper <i>11</i>	\$ 566.40 950.60 ✓
2	Rear bumper - side <i>n/s but o/s n1</i>	\$ 225.30 450.60 1/2 C
2	Rear bumper brackets <i>11</i>	\$ 97.00 X
1	Rear bumper lower under cover <i>del/cro</i>	\$ 325.00 ✓
2	Rear bumper reflectors <i>11</i>	\$ 303.80 X
2	Rear bumper side retainers <i>11</i>	\$ 101.80 X
1	Rear floor board <i>11</i>	\$ 187.60 X
1	Rear floor panel <i>Tools sponge Torn</i>	\$ 425.80 1,145.70 ✓
1	Rear exhaust silencer <i>11</i>	\$ 840.30 X
2	Rear exhaust mountings <i>11</i>	\$ 49.00 X
2	Rear fender wheel arch garnishes <i>n/s Torn o/s n1</i>	\$ 280.60 601.40 1/2 C
2	Rear number plate lamps <i>11</i>	\$ 130.00 X
		\$ 10,855.10
	Less 20%	\$ 2,171.02
		\$ 8,684.08

SPECIAL NETT ITEMS

1	Rear windscreen sealant	all	\$	80.00	40
1	Rear bumper clip (1 set)	all	\$	80.00	30
1	Rear reverse sensor (1 set)	malfunction	\$	350.00	200
1	Rear reverse sensor buzzer	CNS	\$	150.00	60
1	Rear number plate with holder	AA	\$	50.00	X
				\$	710.00

S/N**LABOUR CHARGES**

1	To remove, replaced damaged lamps and check up rear wiring.		\$	80.00	20
2	To remove and refit inner garnishes.		\$	120.00	60
3	To remove and refit rear reverse sensor.	replace	\$	120.00	30
4	To transfer rear tailgate mechanism and wiring assembly.		\$	80.00	50
5	To remove and refit rear windscreen glass.		\$	180.00	120
6	To apply undercoating.		\$	150.00	60
7	Panel beating.		\$	1,800.00	600
8	To re-spray painting on the affected areas.		\$	1,600.00	800
				\$	4,130.00

GRAND TOTAL :**\$ 13,524.08**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-5349-50
212
4279-60
330
1820
6429-60
202
5143.