



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNE 715D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	BUCKLED	\$565.20	\$565.20
1	REAR BUMPER RETAINER (L/H)	SERVICEABLE	\$65.00	\$0.00
1	REAR BOOTLID	BENT	\$852.90	\$852.90
1	REAR BOOTLID EMBLEM -TOYOTA LOGO	NECESSARY	\$75.00	\$75.00
1	REAR BOOTLID EMBLEM -VIOS	NECESSARY	\$45.00	\$45.00
1	REAR BUMPER BEAM	BENT	\$360.10	\$316.61
1	SET REVERSE SENSOR	SERVICEABLE	\$450.00	\$0.00
	LESS 25.00% DISCOUNT		(\$603.30)	(\$463.68)
			\$1,809.90	\$1,391.03

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	SPRAY PAINTING		\$500.00	\$450.00
	TO RENEW ABOVE PARTS		\$450.00	\$400.00
			\$950.00	\$850.00

GRAND TOTAL		\$2,759.90	\$2,241.03
	RECOMMENDED COST OF REPAIRS		\$2,241.03
Report Ref No: CS/LIP24080149/Kqh3e2			

MARKET VALUE: \$110,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$56,069.00=NETT VALUE: \$53,931.00

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.