

ESTIMATE RC AUTO

Not Authorised
Runway B4 painting
4 days

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722
Tel : 97619383 Email: rcauto5555@gmail.com
Reg. No. 53199168K

2241-03

SNE 715 D

Date : 15.08.2024

Quantity	Description/Particular	Unit Price	Amount	
1PC	REAR BUMPER	565	20	✓
1 PC	REAR BUMPER RETAINER(L/H)	65	00	X
1 PC	REAR BOOTLID	852	90	✓
1 PC	REAR BOOTLID EMBLEM-TOYOTA LOGO	75	00	✓
1 PC	REAR BOOTLID EMBLEM -VIOS	45	00	✓
1 PC	REAR BUMPER BEAM 316-60	360	10	✓
1 SET	REVERSE SENSOR	450	00	X
		TOTAL	2413	20
		LESS 25	1809	90
				450/
	SPRAY PAINTING		500	00
	TO RENEW ABOVE PARTS	400/	450	00
			2759	90

Received the above goods in good order and condition

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

for

RC AUTO

Received by

E.O.E
Acknowledged by Repairer
Signature:

Authorised Signature