

ASS. REC. BY:

REF:

09/11/8 24080149/Kgh3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

Res.: Yes or No

Lum Sum:

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / SIRIm / STD A/RIm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Est NOT ready

16/8

2241.03 Cash (Red 518.87, 19%)

Date/Time, File Pass to?

1) 19/8 19/8

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) TP
2241.03Days Of Repair: 4Resurvey No. of Trlp: 2

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee:

Transportation

S + RS. \$

Fees

Others

TOTAL

ESTIMATE

RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722
Tel : 97619383 Email: rcauto5555@gmail.com
Reg. No. 53199168K

Not Authorised
Runway B4 paint
4 days

2241-03

Date : 15.08.2024

SNE 715 D

Quantity	Description/Particular	Unit Price	Amount	
		Per	565	20
1PC	REAR BUMPER	Per	65	00
1 PC	REAR BUMPER RETAINER(L/H)	Per	852	90
1 PC	REAR BOOTLID	Per	75	00
1 PC	REAR BOOTLID EMBLEM-TOYOTA LOGO	Per	45	00
1 PC	REAR BOOTLID EMBLEM -VIOS	Per	360	10
1 PC	REAR BUMPER BEAM 316-60	Per	450	00
1 SET	REVERSE SENSOR			
		TOTAL	2413	20
		LESS 25	1809	90
				450/-
			500	00
	SPRAY PAINTING	400/-	450	00
	TO RENEW ABOVE PARTS			
			2759	90

Received the above goods in good order and condition

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

for RC AUTO

Received by

Acknowledged by Repairer
Signature:

Authorised Signature