

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

Not Authorized
 in
 means
 8/8/24
 2/5 \$ 9000/
 Take photo with cap -
 S. Long S.

VEHICLE No: YP 4102H

1PC	FRONT BUMPER	1215.30	Dis	\$1,615.00	✓
1PC	FRONT BUMPER BRACKET N/S	366.50	3enf	\$520.00	✓
1SET	FRONT BUMPER CLIPS		neu	\$50.00	✓
1PC	FRONT BUMPER FOG LAMP N/S	399.20	5-20	\$485.00	✓
1PC	FRONT BUMPER FOG LAMP COVER N/S		Dis	\$118.00	✓
1PC	HEADLAMP N/S	1288.50	cre	\$1,650.00	✓
1PC	FRONT CORNER PANEL GARNISH N/S		11	\$745.00	X
1PC	FRONT GRILLE	820.00	Cre	\$990.00	✓
1PC	FRONT MIRROR BRACKET N/S		11	\$295.00	X
1PC	FRONT PANEL		2	\$2,450.00	X
1PC	FRONT DOOR N/S	2266.50	4005.00	\$3,205.00	✓
1PC	FRONT DOOR OUTER PILLAR N/S		1	\$2,115.00	X
1PC	FRONT DOOR INNER PILLAR N/S		1	\$1,051.00	X
1PC	FRONT DOOR INNER LOCK N/S		11	\$450.00	X
1PC	FRONT DOOR INNER TRIM BOARD N/S	422.80	De/Torn	\$585.00	✓
1PC	FRONT DOOR INNER RUBBER N/S		Y16m	\$188.00	✓
1PC	FRONT DOOR HINGE N/S		See	\$105.00	X
1PC	FRONT STEP GARNISH N/S	335.50	Cre	\$650.00	✓
1PC	AIR CON CONDENSER	1488.20	Dis	\$1,550.00	✓
1PC	AIR CON FAN ASSY MOTOR	668.00	Cre/gm	\$850.00	✓
1PC	AIR CON CONDENSER BRACKET		1	\$320.00	X
1PC	AIR CON PIPE		See	\$258.00	X
1PC	FRONT WHEEL ARCH PANEL N/S	522.30	Bottom	\$565.00	✓
				\$20,810.00	
				LESS 10%	\$18,729.00

S.NETT

1SET	FRONT DOOR CORPORATE STICKER N/S	neu	\$700.00	250 S/N
1SET	FRONT VIEW CAM	Damaged	\$650.00	X
				\$50.00 20
				\$120.00 50
				\$120.00 100
				\$300.00 X
				\$100.00 50

TO RESET & REPROGRAMME SYSTEM
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

✓✓ \$180.00 X
\$1,250.00 800
\$1,680.00 900
TOTAL \$23,879.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-1014680
102
9132-12
250
1920