

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

not Authorized
in
meas
8/8/24
2/5 \$ 8200/
take photo of the car
S. Long

VEHICLE No: YP 4102H

1PC	FRONT BUMPER	1100	1215.30	Dis	\$1,615.00	✓
1PC	FRONT BUMPER BRACKET N/S		366.50	Benf	\$520.00	✓
1SET	FRONT BUMPER CLIPS			neu	\$50.00	✓ 30 S/W
1PC	FRONT BUMPER FOG LAMP N/S		399.20	S-20	\$485.00	✓
1PC	FRONT BUMPER FOG LAMP COVER N/S			Pis	\$118.00	✓
1PC	HEADLAMP N/S		1288.50	cre	\$1,650.00	✓
1PC	FRONT CORNER PANEL GARNISH N/S			11	\$745.00	X
1PC	FRONT GRILLE		820.00	11	\$990.00	X
1PC	FRONT MIRROR BRACKET N/S			11	\$295.00	X
1PC	FRONT PANEL			12	\$2,450.00	X
1PC	FRONT DOOR N/S	2100	2266.50	4005.00	\$3,205.00	✓
1PC	FRONT DOOR OUTER PILLAR N/S			1	\$2,115.00	X
1PC	FRONT DOOR INNER PILLAR N/S			1	\$1,051.00	X
1PC	FRONT DOOR INNER LOCK N/S			11	\$450.00	X
1PC	FRONT DOOR INNER TRIM BOARD N/S		422.80	de/Tom	\$585.00	✓
1PC	FRONT DOOR INNER RUBBER N/S			Yim	\$188.00	✓
1PC	FRONT DOOR HINGE N/S			see	\$105.00	X
1PC	FRONT STEP GARNISH N/S		335.50	neu	\$650.00	✓
1PC	AIR CON CONDENSER		1488.20	Dis	\$1,550.00	✓
1PC	AIR CON FAN ASSY MOTOR		660.00	Org/ym	\$850.00	✓
1PC	AIR CON CONDENSER BRACKET			1	\$320.00	X
1PC	AIR CON PIPE			see	\$258.00	X
1PC	FRONT WHEEL ARCH PANEL N/S		522.30	Benf/om	\$565.00	✓
					\$20,810.00	
					LESS 10%	\$18,729.00

S.NETT

1SET	FRONT DOOR CORPORATE STICKER N/S		neu	\$700.00	250 S/W
1SET	FRONT VIEW CAM		Dange n/c	\$650.00	X
				\$50.00	20
				\$120.00	50
				\$120.00	100
				\$300.00	X
				\$100.00	50

TO RESET & REPROGRAMME SYSTEM
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

	11	\$180.00	X
		\$1,250.00	800
		\$1,680.00	900
TOTAL		\$23,879.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

7-1014680
 102
 9130.12
 250
 1920

11302.12

2-8995
 102
 8095.50
 280
 1920
 10295.5
 8230