

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24080154/UMA3Q2**Date:** 17/10/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7240018562
Claimant Vehicle No : SLZ8343D **Insured Vehicle No :** SNP6606M
 Date of Loss: 10/08/2024 Nature of Claim: TP Claim No: 0951214919SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ8343D**
 Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B1419543
 Reg. Date: 21/05/2018 (Man. Year: 2018) Chassis No: GK31316829
 Colour: Silver Odometer: 40787 km
 Engine Capacity: 1317 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,278.86	2,183.84	3,095.02	58.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,330.00	1,870.00	58.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,478.86	3,513.84	4,965.02	58.56
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	8,478.86	2,800.00	5,678.86	66.98
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		33.18		
Nett Liability (S\$)		3,233.18		
Global Sum Settlement (S\$)		3,200.00		

INSPECTION

Date of Assignment: 12/08/2024
 Date Inspected: 12/08/2024 Inspected At: Zoom Autowerks Pte Ltd (HQ)
 15 Kaki Bukit Road 4, #01-53
 Singapore 417808
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Badly Dented	1,046.90 FL	*980.50 FL
2	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	131.60 FL	*- FL
3	1		*FRONT DOOR INNER BOARD	Deformed / Torn	662.50 FL	*422.30 FL
4	1		*FRONT DOOR LOCK	Damaged	305.50 FL	*241.50 FL
5	1		*FRONT DOOR OUTER HANDLE	Not Necessary	136.50 FL	*- FL
6	1		*FRONT DOOR REGULATOR COME WITH MOTOR	Not Necessary	440.40 FL	*- FL
7	1		*FRONT DOOR RUBBER	Not Necessary	165.50 FL	*- FL
8	1		*CENTRE PILLAR -LH	Repair	1,119.80 FL	*- FL
9	1		*ROCKER PANEL -LH	Repair	598.75 FL	*- FL
10	1		*REAR DOOR -LH	Dented / Bent	1,046.90 FL	*960.50 FL
11	1		*REAR DOOR CHECKER	Not Necessary	21.20 FL	*- FL
12	1		*REAR DOOR GLASS OUTER MOULDING	Not Necessary	61.20 FL	*- FL
13	2		*REAR DOOR HINGES	Not Necessary	161.20 FL	*- FL
14	1		*REAR DOOR INNER BOARD	Not Necessary	235.12 FL	*- FL
15	1		*REAR DOOR RUBBER	Not Necessary	165.50 FL	*- FL
16	1		*SET FRONT DOOR BLACK TAPE	Necessary	120.00 FS	*50.00 FS
17	1		*SET REAR DOOR BLACK TAPE	Necessary	120.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,538.57	2,704.80
- List Item Discount on L Items 20.00/20.00% (S\$)	1,259.71	520.96

Total Parts (S\$)	5,278.86	2,183.84
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS TRANSFER ALL FITTINGS TO NEW DOOR	New	400.00	120.00
2	TO APPLY UNDERCOATING	New	100.00	60.00
3	PANEL BEATING	New	1,400.00	500.00
4	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,300.00	650.00
Gross Labour Cost (\$\$)			3,200.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >