

ASS. REC. BY:

REF:

002/

CS/UOI24080155/Knp3e2

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20 + 1.71

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

22/8 21 Rm 86800k Car
(red, \$2856, 29%)

Veh No:

EK 333Y

Yr Regn:

09, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Vell for

C.C

Wagon 2494

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

45149

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTNGI-30H 808023845

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

7/8/24

D.O.I.

12/8/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S for body & WC

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prel. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. \$

Fees

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

VIN'S

Estimated Cost of Repair

Attention To : **United Overseas Insurance**
146 Robinson Road,
#02-01, UOI Building,
Singapore 068909

Claim Details

Case Ref. No. : OD/082024/7586
Date : 08-08-2024
Accident Date : 07-08-2024

Vehicle Details

Make & Model : TOYOTA VELLFIRE ELEGANCE
MOONROOF (AUTO)
Chassis No : JTNGF3DH808023845
Registration No : EK333Y

S/N	Description	Qty	Amount (S\$)	
1	FRONT BUMPER	1.00	Net/1m \$420.00	✓
2	FRONT BUMPER LH SIDE RETAINER	1.00	Net \$70.00	✓
3	FRONT BUMPER CLIPS	10.00	Net \$20.00	✓
4	FRONT LH FENDER	1.00	Net \$650.00	✓
5	FRONT LH FENDER GLASS WITH MOULDING	1.00	Net \$250.00	✓
6	FRONT LH FENDER INNER SHIELD	1.00	Net \$150.00	X
7	FRONT LH FENDER INNER SHIELD CLIPS	10.00	Net \$20.00	✓
8	FRONT LH FENDER LOWER PROTECTOR	1.00	Net/1m \$150.00	✓
9	FRONT LH SPORT RIM	1.00	Net \$1,500.00	✓
10	FRONT LH SHOCK ABSORBER	1.00	Net \$280.00	2
11	FRONT LH KNUCKLE ARM	1.00	Net \$310.00	2
12	FRONT LH WHEEL BEARING	1.00	Net \$290.00	2
13	FRONT LH LOWER ARM	1.00	Net \$220.00	2
14	FRONT LH STABILIZER LINK	1.00	Net \$110.00	X
15	LH SIDE MIRROR HOUSING	1.00	Net \$850.00	✓
16	LH SIDE MIRROR COVER	1.00	Net \$70.00	X
17	FRONT LH DOOR	1.00	Net \$1,100.00	✓
			\$6,460.00	
			Margin: 10%	
			\$646.00	
			\$7,106.00	
18	FENDER GLASS GUM	1.00	Net \$60.00	401m
19	FRONT LH TYRE	1.00	Net \$280.00	X
20	TO REMOVE AND REFIX LH FENDER GLASS	1.00	\$120.00	601
21	TO CHECK WHEEL ALIGNMENT	1.00	\$150.00	601
22	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	1.00	\$280.00	201
23	TO REPAIR DAMAGES	1.00	\$780.00	601
24	TO SPRAY PAINTING	1.00	\$880.00	801

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vin's Motor Pte Ltd

160 Sin Ming Drive

#03-03 Sin Ming Autocity

Singapore 575722

Tel : 6453 2121 Fax : 6459 9795

GST Registration No. 199906067G

Not Notified
After
Repair

Ex @ 1500 750

21 Lmp @ 6800 6 days

VIN S

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Subtotal w/o GST:

\$9,656.00

Issued by Mohamad Hakim Bin Anuar

This is a computer-generated document. No signature is required.