



Estimated Cost of Repair

Attention To : **United Overseas Insurance**
146 Robinson Road,
#02-01, UOI Building,
Singapore 068909

Claim Details

Case Ref. No. : OD/082024/7586
Date : 08-08-2024
Accident Date : 07-08-2024

Vehicle Details

Make & Model : TOYOTA VELLFIRE ELEGANCE
MOONROOF (AUTO)
Chassis No : JTNGF3DH808023845
Registration No : EK333Y

S/N	Description	Qty	Amount (\$\$)
1	FRONT BUMPER	1.00	\$420.00
2	FRONT BUMPER LH SIDE RETAINER	1.00	\$70.00
3	FRONT BUMPER CLIPS	10.00	\$20.00
4	FRONT LH FENDER	1.00	\$650.00
5	FRONT LH FENDER GLASS WITH MOULDING	1.00	\$250.00
6	FRONT LH FENDER INNER SHIELD	1.00	\$150.00
7	FRONT LH FENDER INNER SHIELD CLIPS	10.00	\$20.00
8	FRONT LH FENDER LOWER PROTECTOR	1.00	\$150.00
9	FRONT LH SPORT RIM	1.00	\$1,500.00
10	FRONT LH SHOCK ABSORBER	1.00	\$280.00
11	FRONT LH KNUCKLE ARM	1.00	\$310.00
12	FRONT LH WHEEL BEARING	1.00	\$290.00
13	FRONT LH LOWER ARM	1.00	\$220.00
14	FRONT LH STABILIZER LINK	1.00	\$110.00
15	LH SIDE MIRROR HOUSING	1.00	\$850.00
16	LH SIDE MIRROR COVER	1.00	\$70.00
17	FRONT LH DOOR	1.00	\$1,100.00
			<hr/>
			\$6,460.00
Margin: 10%			\$646.00
			<hr/>
			\$7,106.00
18	FENDER GLASS GUM	1.00	\$60.00
19	FRONT LH TYRE	1.00	\$280.00
20	TO REMOVE AND REFIX LH FENDER GLASS	1.00	\$120.00
21	TO CHECK WHEEL ALIGNMENT	1.00	\$150.00
22	TO REMOVE AND REFIX FRONT UNDERCARIAGE	1.00	\$280.00
23	TO REPAIR DAMAGES	1.00	\$780.00
24	TO SPRAY PAINTING	1.00	\$880.00



Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Subtotal w/o GST:	\$9,656.00
--------------------------	-------------------

Issued by Mohamad Hakim Bin Anuar

This is a computer-generated document. No signature is required.