

NOT AUTHORIZED
LPR \$ 2200/-

Trans-cab Auto Services Pte Ltd

AAD2408-032

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5379P

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

13 AUG 2024

SHC5379P

JTDKB3FU903093761

200303878K

TOYOTA

PRIUS GEN 4

7/8/2024

SNH4292P / III

25/2/2021

	PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	R 1,641.36	X
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	Sm 243.81	X
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$	Sm 493.40	X
1	WEATHERSTRIP, FRONT DOOR, LH	\$	Sm 292.32	X
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	M 139.86	X
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	M 123.06	X
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	na 16.91	X
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	na 55.02	X
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	na 33.29	X
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	Sm 1,161.83	X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	Sm 300.62	X
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	R 1,634.33	✓
1	GLASS SUB-ASSY, REAR DOOR, LH	\$	Sm 518.07	X
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	\$	Sm 243.81	X
1	HANDLE ASSY, REAR DOOR OUTSIDE, LH	\$	Sm 123.06	X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	Sm 369.60	X
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	M 109.62	X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	M 124.74	X
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	na 27.62	—
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	na 44.00	—
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	na 19.43	—
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	M 756.74	X
1	PANEL SUB-ASSY, QUARTER, LH	\$	M 1,099.46	X
1	LINER, REAR WHEEL HOUSE, LH	\$	Sm 176.09	X
TOTAL		\$	9,748.05	

Trans-cab Auto Services Pte Ltd

AAD2408-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5379P

25%	\$	2,437.01
	\$	<u>7,311.03</u>

Special Nett

1SET DOOR TRIM CLIP	\$	<i>na</i>	70.00	X
1SET DOOR WEATHERSTRIP CLIP	\$	<i>na</i>	65.00	X
1 DOOR STICKER TRANSCAB	\$	<i>na</i>	100.00	<i>60W</i>
1 DOOR STICKER TEL NO.	\$	<i>na</i>	100.00	<i>60W</i>
1SET FENDER CLIP	\$	<i>na</i>	65.00	X
1 FENDER LINER CLIP	\$	<i>na</i>	65.00	X
TOTAL	\$		465.00	
TOTAL PARTS	\$		2,300.00	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>301</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>400</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>800</i>
To reinstall rear bumper parking sensor.	\$	<i>na</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5379P

AAD2408-

To remove and refit of rear fender fittings, attachment and perform water seepage test.

	\$	<i>nn</i> 170.00 X
TOTAL	\$	4,720.00

Over All Total	\$	14,331.03
-----------------------	----	------------------

(PART-BY-PART) Repair Days

07 Days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: