

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA7512T

MAKE HYUNDAI

MODEL KONA

Steve (LKK)

12/8/24, 12.30 pm

W L N, P/P

DATE: 08.08.24

MVA JUMANI

DOA: 08.08.24

ECICS

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR BUMPER ASSY UPPER / BR			\$1,020.00	1015 /
1	REAR BUMPER ASSY LOWER / BR (Skid plate)			-\$668.82	510.39 /
1	REAR BUMPER BEAM / BR			\$582.00	/
	REAR BUMPER STAY LH/RH ? x nn		\$55.00	\$110.00	/
1	PANEL ASSY - TAIL GATE / DD			\$2,164.00	/
1	EMBLEM - HYBRID / ne			\$47.00	/
1	EMBLEM - KONA / ne			\$97.00	/
1	EMBLEM - SYMBOL MARK / ne			-\$42.00	72 /
1	LATCH ASSY - TAIL GATE -X BR			\$278.00	/
1	HANDLE ASSY - TAIL GATE ? x nn			\$125.00	/
1	REAR BUMPER COVER SIDE LH x R			\$245.00	/
1	GARNISH - TAIL GATE ? BR			\$325.00	/
1	REAR WINDSCREEN GLASS x nn			\$609.00	/
1	REAR END PANEL ? DD			-\$294.00	729 /
1	REAR NUMBER PLATE LAMP LH/RH ? BR		\$71.00	\$142.00	71 /
1	TAILLAMP ASSY LH / LUT			-\$717.00	953 /
	REAR BUMPER SIDE BRACKET LH ? x nn			\$32.00	/
1	REAR BUMPER COVER LH x nn			\$245.00	/
1	REAR FOG LAMP x nn			\$163.00	/
	SUB TOTAL		6843.39	\$7,905.82	
	LESS 20%		-20%	\$1,581.16	
	DISCOUNTED TOTAL		5474.71	\$6,324.66	
			+		
			89.60 (supp) =	5564.31	
	BOOTILD COMFORT LOG / ne			\$30.00	NET /
	BOOTILD COMFORT TEL.NOS LOGO / ne			\$30.00	NET /
	BOOTLID APPS LOGO / ne			\$40.00	NET /
	WINDSCREEN SEALANT / ne			\$46.00	NET /
	REAR NUMBER PLATE / BR			\$55.00	NET /
	DIS 10%				
	SUB TOTAL			\$201.00	201 /
	Labour Charge				
	PANEL BEATING		760 /	\$1,200.00	/
	SPRAY PAINT		560 /	\$900.00	/
	REMOVE / REFIX REVERSE SENSOR		20 /	\$50.00	/
	REMOVE/REFIX REAR WINDSCREEN GLASS			\$120.00	/
	CHECK WIRING		30 /	\$50.00	/
	TUFF KOTE		20 /	\$50.00	/
	TOTAL LABOUR			\$2,370.00	1510

ESTIMATE TOTAL		\$8,895.66
LIST PRICE TO BE CONFIRM		
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.		

P/P - 7275.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305600205
REGN NO : SHA7512T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : KONA
DATE OF REGN : 28.06.2024
DATE/TIME IN : 08.08.2024 12:4
ACCIDENT DATE : 08.08.2024

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0107-2346-G	PANEL ASSY-BACK	1	729.00	20.00	583.20	/
0015 04-01-0107-2226-G	LAMP ASSY-LICENSE PLATE	1	71.00	20.00	56.80	/
0016 04-01-0107-2380-G	LATCH ASSY-TAIL GATE	1	278.00	20.00	222.40	/
0017 09-01-0107-2284-G	ANTENNA ASSY-SMARTKEY	1	112.00	20.00	89.60	/ supp broken
0018 04-01-0107-2595-G	TRIM ASSY-RR TRANSVERSE	1	325.00	20.00	260.00	/

SUB-TOTAL : 5,765.31

JOB NATURE

0000 L	PANEL BEAT (SHA7512T)TP	760.00	/
0001 SP	SPRAYPAINT CHARGE	560.00	/
0002 L	REMOVE/REFIX REVERSE SENSOR	20.00	/
0003 L	REMOVE/REFIX RR WINDSCREEN	120.00	/