

(08/11/13) Wef

ASS. REC. BY: Marcus

REF:

CS/CT/24080164/Uah3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: PC 1057Rat Workshop m/s stytech

of _____

Insured: SNL 9432x

Policy No.: _____

Claims No.: _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**Bal. or Market Value: 460k.

IDAC Accident Rpt: _____

Consistent?: **Yes** or No

GIA / PR Seen: _____

Consistent?: **Yes** or NoEst. Repairs: 10 daysRes.: **Yes** or NoLum Sum: 20 %3 Val.: **Yes** or No**CA / REV / REP. / 24 HRS**Vehicle: **IN / OUT**

Date: _____

Person Contacted: LTA 510496Veh No: PC1057RYr Regn: 02/07/18Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or _____

Make: Toyotac.c. 2754Colour: WhiteA/C: **Insured / Std / NI / NA**Sp. Reading: 278255T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: GDH2232000355Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt** orBrake: **Inorder / Jammed / Leaked / Burnt** orModi: **Nil / S/Rim / STD A/Rim** orTyre Size: **F:** 195-215**R:** _____**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO** or AGilis

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 07/08/2xD.O.I. 08/08/2x

Survey held at _____

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** orThe **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time

Action / Instruction

21/8/24 4/5 @ 8600 Dep 10k
inward w. 1st on
(Red. \$ 9929.80, 53%)

Date/Time, File Pass to?

☐: **Preli. Report**

1)

☐: **Final Report**

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

S + RS, \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	585D
Vehicle Details	
Vehicle No.:	PC1051R
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 2.8 AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1GD8281677
Chassis No.:	GDH2232000355
Maximum Power Output:	-
Open Market Value:	\$43,640.00
Original Registration Date:	02 Jul 2018
First Registration Date:	02 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$2,182.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jul 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$26,953.00
COE Rebate Amount:	\$10,496.00
Total Rebate Amount:	\$10,496.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 09 Aug 2024

OK

Vehicle:

PC1051R

Make & Model:

TOYOTA HIACE

Chassis No:

GDH223-2000355

Not Authorized
meras
8/8/24
4/c 8600
telephone H...
10 days

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Left Side Mirror			\$ 1,482.90	R X
2	Rear Boot			\$ 2,696.80	Body on
3	Rear Boot Glass Sealant			\$ 60.00 SN	new 40 s/n
4	Rear Boot "HIACE" Wording			\$ 58.80	new
5	Rear Boot "70km/h" Sticker			\$ 10.00 SN	new s/n
6	Rear Boot "Emblem"			\$ 68.50	new X
7	Rear Boot "GL" Wording			\$ 56.80	new
8	Rear Boot Lock			\$ 195.20	Damage/In
9	Rear Boot Inner Stopper (Right)			\$ 89.50	new
10	Rear Boot Inner Rubber Guide (Right)			\$ 42.50	new
11	Right Rear Fender			\$ 1,917.50	Body on/suc
12	Right Rear Fender Glass Sealant			\$ 50.00 SN	new 40 s/n
13	Right Rear Center Fender Glass Sealant			\$ 40.00 SN	new X
14	Right Rear Center Joint Sealant			\$ 60.00 SN	new 50 s/n
15	Right Taillamp		412.50	\$ 487.50	new
16	Right Taillamp Clip Holder	2	\$18.00	\$ 36.00	new X
17	Right Taillamp Panel			\$ 528.50	Body on
18	Right Rear Corner Panel Garnish			\$ 128.40	Torn
19	Right Rear Corner Panel Retainer			\$ 62.50	new
20	Rear Bumper			\$ 781.40	new
21	Rear Bumper Clips			\$ 30.00 SN	new/s/n
22	Rear Bumper Retainer (Left & Right)	2	\$88.50	\$ 177.00	old/cro 1pc
23	Rear Bumper Reverse Sensor			\$ 200.00 SN	new X

252

24	Rear End Panel (Outer)			\$ 985.80	Body 20 ✓
25	Rear End Panel (Inner)			\$ 1,250.60	R X
26	Right Rear Air Duct			\$ 86.70	DIS ✓
27	Whether Stripe			\$ 289.80	Tw ✓
28	Right Rear Inner Fender Trim Board		241.0	\$ 1,321.50	24/cne ✓
29	Right Rear Inner Fender Panel			\$ 894.70	R X
30	Rear Floor Panel Stay			\$ 186.80	n 2 X
31	Exhaust Pipe			\$ 757.80	Sub/7m ✓
32	Exhaust Pipe Mounting			\$ 98.60	n 2 X
33	Right Rear Tyre			\$ 200.00 SN	cut 802 s/n 160 s/n
34			252		
35					

Labour

1	Transfer Rear Boot			\$ 200.00	60
2	Transfer Rear Boot Glass			\$ 150.00	100
3	Remove & Refix Rear Fender Glass			\$ 120.00	100
4	Remove & Refix Center Fender Glass			\$ 80.00	n 2 X
5	Remove & Refix Inner Seats & Floor Board			\$ 300.00	100
6	Check Wiring			\$ 100.00	20
7	Anti Rust Proof			\$ 100.00	80
8	Panel Beating			\$ 1,800.00	1400
9	Putty & Spray Paint			\$ 1,800.00	1100
			18529.80		

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #01-03
Kaki Bukit Autohub Singapore 417921
Tel: 6444 8125 Fax: 6445 3310
GST Reg. No.: 201601539K
Co. Reg. No.: 201601539K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-10020-1
252
7575.08
330
2960
10805.08
222
8644