

CS/CTI24080165/Anh3e2 (SNH 9842U)

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / TP RES / OD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W _____

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its

repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNH9842U Yr Regn: 2022, Dec

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 116i C.D. 1499

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 44570 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA7K120307L61660

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Survey held at Bitrost 13/08/24

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Chin

MV: 150K

PV: 101.6K

Nett: 48.4K

COE Expiry: _____

Estimate given during: Yes ☒ No ☐

1st Survey: Yes ☒ No ☐

We will be re-advising our principal a cost of repair of LS \$4,700.00 with 3 days of repair

(red, \$9472.39, 66%)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (\$

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Report Format:

Report Format: A.P.P. / P.P.

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SNH9842U

Make & Model: BMW 116i

Chassis number: WBA7K120307L61660

No.	Description of spare parts	Qty	Amount S\$
1	Front bumper (M-sport) <i>Del'd</i>	1	\$ 1,185.79
2	Front bumper clips <i>in</i>	1set	\$ 80.00
3	Front bumper centre emblem <i>in</i>	1	\$ 120.50
4	Front bumper lower spoiler <i>lt</i>	1	\$ 744.80
5	Front bumper RH corner side parking sensor <i>2 new</i>	1	\$ 391.05
6	Front bumper RH side parking sensor <i>for 2nd</i>	1	\$ 391.05
7	Front bumper RH centre parking sensor <i>for 2nd</i>	1	\$ 391.05
8	Front bumper parking sensor holders <i>in</i>	6	\$ 78.00
9	Front bumper parking sensor rubber seal <i>new</i>	6	\$ 36.00
10	Front bumper towing cover <i>new</i>	1	\$ 71.03
11	Front bumper RH fog lamp <i>ASP in</i>	1	\$ 631.30
12	Front bumper RH fog lamp cover <i>crack'd</i>	1	\$ 120.30
13	Front bumper RH daylight <i>crack'd</i>	1	\$ 711.38
14	Front bumper RH daylight cover <i>new</i>	1	\$ 157.90
15	Front bumper reinforcement <i>new</i>	1	\$ 558.21
16	RH headlamp assy <i>crack'd</i>	1	\$ 2,502.55
17	Front RH sport rim	1	\$ 1,093.10
18	Front RH wheel bearing	1	\$ 511.28
19	Front RH shock absorber <i>ASP</i>	1	\$ 432.86
20	Front RH lower arm	1	\$ 498.60
21	Front RH knuckle arm <i>Nec</i>	1	\$ 602.58
22	Front RH tie rod end	1	\$ 177.40

\$ 11,486.73
 Parts less 5% \$ 574.34
 Total: \$ 10,912.39

No.	Special Nett Items	Qty	Amount S\$
1	Front RH tyre <i>2 ASP</i>	1	\$ 500.00
2	Brake fluid <i>new</i>	1	\$ 70.00

Total: \$ 570.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,400.00
2	Spray painting on affected areas and panels	\$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 70.00
5	Re-coding and reprogram headlamps assy	\$ 550.00
6	Remove and replace front bumper parking sensors to assist repair (6 sensors)	\$ 120.00
7	Test drive and adjust wheel alignment system	\$ 120.00
8	Remove and replace front undercarriage parts to assist repair	\$ 550.00

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

Total: \$ 2,690.00

Spare Parts: \$ 10,912.39
Special Nett: \$ 570.00
Labour: \$ 2,690.00

Total: \$ 14,172.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Adrian C
x/s 13/08/24
037 days