

REPRINTED BY THE AUTHOR

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SNH9842U

Make & Model: BMW 116i

Chassis number: WBA7K120307L61660

No.	Description of spare parts	Qty	Amount S\$
1	Front bumper (M-sport) <i>Delnd</i>	1	\$ 1,185.79
2	Front bumper clips <i>in</i>	1set	\$ 80.00
3	Front bumper centre emblem <i>in</i>	1	\$ 120.50
4	Front bumper lower spoiler <i>lt</i>	1	\$ 744.80
5	Front bumper RH corner side parking sensor <i>2 new</i>	1	\$ 391.05
6	Front bumper RH side parking sensor <i>for 2nd</i>	1	\$ 391.05
7	Front bumper RH centre parking sensor <i>for 2nd</i>	1	\$ 391.05
8	Front bumper parking sensor holders <i>in</i>	6	\$ 78.00
9	Front bumper parking sensor rubber seal <i>new</i>	6	\$ 36.00
10	Front bumper towing cover <i>new</i>	1	\$ 71.03
11	Front bumper RH fog lamp <i>Asp in</i>	1	\$ 631.30
12	Front bumper RH fog lamp cover <i>crackd</i>	1	\$ 120.30
13	Front bumper RH daylight <i>crackd</i>	1	\$ 711.38
14	Front bumper RH daylight cover <i>new</i>	1	\$ 157.90
15	Front bumper reinforcement <i>new</i>	1	\$ 558.21
16	RH headlamp assy <i>crackd</i>	1	\$ 2,502.55
17	Front RH sport rim	1	\$ 1,093.10
18	Front RH wheel bearing	1	\$ 511.28
19	Front RH shock absorber <i>Asp</i>	1	\$ 432.86
20	Front RH lower arm	1	\$ 498.60
21	Front RH knuckle arm <i>Nec</i>	1	\$ 602.58
22	Front RH tie rod end	1	\$ 177.40

\$ 11,486.73
 Parts less 5% \$ 574.34
 Total: \$ 10,912.39

No.	Special Nett Items	Qty	Amount S\$
1	Front RH tyre <i>2 new</i>	1	\$ 500.00
2	Brake fluid <i>new</i>	1	\$ 70.00

Total: \$ 570.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,400.00
2	Spray painting on affected areas and panels	\$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	\$ 70.00
5	Re-coding and reprogram headlamps assy	\$ 550.00
6	Remove and replace front bumper parking sensors to assist repair (6 sensors)	\$ 120.00
7	Test drive and adjust wheel alignment system	\$ 120.00
8	Remove and replace front undercarriage parts to assist repair	\$ 550.00

Agreed Amount: _____ (Part by Part / Lump sum) Total: \$ 2,690.00

Working days: _____

Spare Parts: \$ 10,912.39
Special Nett: \$ 570.00
Labour: \$ 2,690.00

Total: \$ 14,172.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Adrian C
x/s 13/08/24
037 days