

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	MS INCOME INSURANCE LTD		Ref:	CS/INC24080166/Uqh3
	75 BRAS BASAH R		Date:	11/09/2024
	INCOME CENTRE	SINGAPORE 189557		INC
			Code:	
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SNP 4847Y	Veh. Inspected	SMS 755B
	Policy No.	- MT/4000570.000	Coverage	0
	Claim No.	MT/1289570-002	Excess	\$0.00
	Assign From	EILEEN LEE	Assign Date	12/08/2024
2. Vehicle Details				
	Make & Model	TOYOTA NOAH HYBRID (A)	C.C	1797
	Engine No.	2ZR2Y93258	Year of Reg.	21/06/2024
	Chassis No.	ZWR900166109	Colour	BLACK
	Odometer	18045 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	215/50R17	MICHELIN	8
	L/H Front Tyre	215/50R17	MICHELIN	8
	R/H Rear Tyre	215/50R17	MICHELIN	8
	L/H Rear Tyre	215/50R17	MICHELIN	8
4.	Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
DAMAGES SEE DETAILS.				
5.	General Information			
	Accident Date	03/08/2024	Inspection Date	05/09/2024 (11:31)
	Survey held at	LEANG AUTOMOTIVE	· ·	,
		BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT		
		SINGAPORE 417883		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				