

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

7 Aug 2024

Estimate No. : b1 70753
Date Estimated : 05/08/2024
Prepared By : Tee Hong Da

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Ho Kok Sun (He Guoshan)
Apt Blk 988C Buangkok Green
#04-81

Singapore 533988

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ5887X	WBA7K120607L71101	10/10/2023	116i Hatch	9966

DESCRIPTION

To replace rear right passenger door

To respray rear right passenger door

To transfer lock mechanism from old to new door including
conduct check on new door power window system for proper
function. (1 door).

Sundries.

Repair
By 9am 10/8
3 days
16/08/24
Reg after repair

	VALUE
850	1,275.00
885	1,038.00
177	531.00
nec ✓ ?	40.00

Total Labour 1: 2,884.00

DESCRIPTION

REAR RH DOOR *repair*

QTY	PRIC	VALUE
1	1,242.80	XR 1,242.80

Total Parts : 1,242.80

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	2,884.00
Parts	:	1,242.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	371.41
Grand Total	:	4,498.21

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **