



Final Report

Estimate No. : **b1 71212**
Date Estimated : **17/09/2024**
Prepared By : **Tee Hong Da**

Page No. :

- **ESTIMATE REPAIR FOR** -
Ho Kok Sun (He Guoshan)
Apt Blk 988C Buangkok Green
#04-81

Singapore 533988

- **ACCOUNT - 219**
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SLZ5887X	WBA7K120607L71101	10/10/2023	116i Hatch	16451

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good the rear RH door include carrying out other necessary repairs caused by the accident	850.00		850.00
To respray rear RH door	885.00		885.00
To check electrical wiring system at the RH section for proper function	177.00		177.00
Sundries	40.00		40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
NO PARTS				

SUPPLEMENTARY ITEMS

Total Labour :	1,952.00
Total Parts :	
Total Labour & Parts (before GST) :	1,952.00
Deduction for Excess :	
Total Repair Costs less Excess:	1,952.00
GST @9%:	175.68
Grand Total :	2,127.68

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W