

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 86861024

ANDIKA PUTRA HIDAYAHTULLAH BIN SUHAIMI

NO 322A SUMANG WALK

#07-905 PUNGGOL BAYVIEW

SINGAPORE 821322

TEL : FAX :

PH : 86861024

ATTN :

ESTIMATE BILL

Number : EB00006555

Date : 12/8/2024

Case No : AD00014900

Vehicle No : SLP7296R

Chassis : YV1FS28C0H2441110

Year of Mfr 2017

Policy No 5133912156-01

Model : VOLVO S60 T2 A/T

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT FENDER LH <i>body</i>	1.0	1,865.84	0	1,865.84
2	FRONT FENDER INNER SHIELD LH <i>ym</i>	1.0	423.13	0	423.13
3	BONNET HINGE LH <i>17</i>	1.0	285.00	0	285.00
4	BONNET HINGE RH <i>17</i>	1.0	285.00	0	285.00
5	FRONT BUMPER SIDE RETAINER LH <i>17</i>	1.0	133.83	0	133.83
6	FRONT BUMPER REINFORCEMENT <i>17</i>	1.0	1,690.82	0	1,690.82
7	HEADLAMP LH <i>17</i>	1.0	1,705.20	0	1,705.20
8	HEADLAMP BRACKET LH <i>17</i>	1.0	133.87	0	133.87
9	FRONT WHEEL RIM LH <i>wasud</i>	1.0	1,166.47	0	1,166.47
10	FRONT KNUCKLE ARM LH <i>17</i>	1.0	2,018.39	0	2,018.39
11	FRONT SHOCK ABSORBER LH <i>17</i>	1.0	2,319.54	0	2,319.54
12	FRONT LOWER ARM LH <i>17</i>	1.0	1,181.49	0	1,181.49
13	FRONT WHEEL BEARING LH <i>17</i>	1.0	886.66	0	886.66
14	FRONT ABS SENSOR LH <i>17</i>	1.0	430.50	0	430.50
15	FRONT BALL JOINT LH <i>17</i>	1.0	496.40	0	496.40
16	FRONT BUMPER <i>cur/torn</i>	1.0	1,800.00	0	1,800.00
List Price - Parts Sub Total					16,822.14
17	FRONT TYRE LH <i>su</i>	1.0	480.00	0	480.00
Special Nett Price - Parts Sub Total					480.00
Parts Total					17,302.14
18	BONNET - REPAIR <i>12</i>	1.0			
19	FRONT DOOR LH - REPAIR <i>12</i>	1.0			
20	FRONT WHEEL HOUSING LH - REPAIR <i>17</i>	1.0			
21	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	800.00
22	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
23	TO REMOVE & REFIT UNDERCARRIAGE	1.0	350.00	0	350.00
24	WIRING	1.0	40.00	0	40.00
25	ANTI-RUST COATING	1.0	100.00	0	100.00
Labour 1 Sub Total					2,490.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

2-5039.6
52
478.62
1250
6036.2
302
4225.

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 86861024
ANDIKA PUTRA HIDAYAHTULLAH BIN SUHAIMI
NO 322A SUMANG WALK
#07-905 PUNGGOL BAYVIEW
SINGAPORE 821322
TEL : FAX :
PH : 86861024
ATTN :

ESTIMATE BILL

Number : EB00006555
Date : 12/8/2024
Case No : AD00014900
Vehicle No : SLP7296R
Chassis : YV1FS28C0H2441110
Year of Mfr : 2017
Policy No : 5133912156-01
Model : VOLVO S60 T2 A/T

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
	<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
SINGAPORE DOLLARS : TWENTY-ONE THOUSAND FIVE HUNDRED SEVENTY-THREE AND CENTS FORTY-THREE ONLY			Less Excess		0.00
			SUBTOTAL		19,792.14
			GST 9.00%		1,781.29
			TOTAL		21,573.43

Date of accident : 08/08/2024 07:05 AM. Place : ALONG ANG MO KIO AVENUE 4

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE