

ASS. REC. BY:

REF:

MS61

CS/MSH 24080170/Knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

8120k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNH 1972E Yr Regn: 10. 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

C.C

Wagon 1496

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

148530

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GPT

2206883

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kapsen

Front

Rear

R/Bal.

3

mm

R/Bal.

4

mm

L/Bal.

3

mm

L/Bal.

4

mm

D.O.A.

5/8/24

D.O.I.

13/8/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

EN NOT ready

2018

11 Rmp @ 1800. Cahr (Red. \$ 5800.20, 761.)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

Repair Estimate

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Not Authorized
 11 Amp & 1800p
 Repair After Pain
 4 days

Make/Model: HONDA SHUTTLE
 Engine/Chassis No.: GP72206883
 Date of accident: 05.08.24
 Damaged area: N/S

Date: 13/08/2024

Claim Type: TP

VRN: SNH1972E

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door n/s <i>898.60</i>	<i>By</i> 1	\$ 1,357.00	\$ 1,357.00
2	Front door top hinge n/s	<i>R</i> 1	\$ 187.00	\$ 187.00
3	Front door lower hinge n/s <i>65.30</i>	<i>Dir</i> 1	\$ 176.00	\$ 176.00
4	Front door inner trim board n/s	<i>PL</i> 1	\$ 583.00	\$ 583.00
5	Front door outer handle n/s	<i>PL</i> 1	\$ 296.00	\$ 296.00
6	Front door outer handle lock sensor n/s	<i>PL</i> 1	\$ 195.00	\$ 195.00
7	Front door lock n/s	<i>R</i> 1	\$ 285.00	\$ 285.00
8	Front door weatherstrip n/s	<i>PL</i> 1	\$ 183.00	\$ 183.00
9	Front door window regulator n/s	<i>PL</i> 1	\$ 336.00	\$ 336.00
10	Front door window motor n/s	<i>PL</i> 1	\$ 281.00	\$ 281.00
11	Front door window outer channel n/s	<i>PL</i> 1	\$ 153.00	\$ 153.00
12	Front fender n/s <i>425.90</i>	<i>By</i> 1	\$ 884.00	\$ 884.00
13	Front fender cowling n/s <i>142.60</i>	<i>Dir</i> 1	\$ 197.00	\$ 197.00
14	Front fender "HYBRID" emblem n/s	<i>PL</i> 1	\$ 56.00	\$ 56.00
Subtotal				\$ 5,169.00
List discount				20.00%
Total				\$ 4,135.20

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door inner trim board clips n/s <i>na</i>	10	\$ 5.50	\$ 55.00
2	Front steel wheel n/s	<i>PL</i> 1	\$ 350.00	\$ 350.00
3	Front hub cover n/s	<i>PL</i> 1	\$ 180.00	\$ 180.00
4	Front tyre n/s	<i>PL</i> 1	\$ 280.00	\$ 280.00
5	Sundries	<i>na</i> 1	\$ 50.00	\$ 50.00
Total				\$ 915.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00

400p

Repair Estimate

2	To disconnect n/s front door wire harness of electrical components to facilitate repairs, reconnect and check functions of power windows.	0.25	\$	50.00
3	To remove and refit n/s front door components to replace n/s front door, check alignment.	1	\$	200.00
4	Supply spray paint material and necessary items to respray affected area / panel.	5	\$	1,000.00
5	To rust proof all affected portions after repair.	0.5	\$	100.00
Total labour			\$	2,550.00

201

601

4401

601

Estimate Grand Total			\$	7,600.20
----------------------	--	--	----	----------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: