

Repair Estimate

Not Authorised
 11 Amp & 1800p
 Running After Pain
 4 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA SHUTTLE

Engine/Chassis No.: GP72206883

Date of accident: 05.08.24

Damaged area: N/S

Date: 13/08/2024

Claim Type: TP

VRN: SNH1972E

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door n/s <i>898.60</i>	<i>By</i> 1	\$ 1,357.00	\$ 1,357.00
2	Front door top hinge n/s	<i>1</i> 1	\$ 187.00	\$ 187.00
3	Front door lower hinge n/s <i>65.30</i>	<i>Bit</i> 1	\$ 176.00	\$ 176.00
4	Front door inner trim board n/s	<i>1</i> 1	\$ 583.00	\$ 583.00
5	Front door outer handle n/s	<i>1</i> 1	\$ 296.00	\$ 296.00
6	Front door outer handle lock sensor n/s	<i>1</i> 1	\$ 195.00	\$ 195.00
7	Front door lock n/s	<i>1</i> 1	\$ 285.00	\$ 285.00
8	Front door weatherstrip n/s	<i>1</i> 1	\$ 183.00	\$ 183.00
9	Front door window regulator n/s	<i>1</i> 1	\$ 336.00	\$ 336.00
10	Front door window motor n/s	<i>1</i> 1	\$ 281.00	\$ 281.00
11	Front door window outer channel n/s	<i>1</i> 1	\$ 153.00	\$ 153.00
12	Front fender n/s <i>425.90</i>	<i>By</i> 1	\$ 884.00	\$ 884.00
13	Front fender cowling n/s <i>142.60</i>	<i>Bit</i> 1	\$ 197.00	\$ 197.00
14	Front fender "HYBRID" emblem n/s	<i>1</i> 1	\$ 56.00	\$ 56.00
Subtotal				\$ 5,169.00
List discount				20.00%
Total				\$ 4,135.20

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front door inner trim board clips n/s <i>NA</i>	10	\$ 5.50	\$ 55.00
2	Front steel wheel n/s	<i>1</i> 1	\$ 350.00	\$ 350.00
3	Front hub cover n/s	<i>1</i> 1	\$ 180.00	\$ 180.00
4	Front tyre n/s	<i>1</i> 1	\$ 280.00	\$ 280.00
5	Sundries	<i>1</i> 1	\$ 50.00	\$ 50.00
Total				\$ 915.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00

Repair Estimate

2	To disconnect n/s front door wire harness of electrical components to facilitate repairs, reconnect and check functions of power windows.	0.25	\$	50.00
3	To remove and refit n/s front door components to replace n/s front door, check alignment.	1	\$	200.00
4	Supply spray paint material and necessary items to respray affected area / panel.	5	\$	1,000.00
5	To rust proof all affected portions after repair.	0.5	\$	100.00
Total labour			\$	2,550.00

201

601

4401

601

Estimate Grand Total			\$	7,600.20
-----------------------------	--	--	-----------	-----------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: