

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 20/02/2014

TP Veh Reg No: XB5471X

Estimate No: ES1490345/YISHUN

Date: 23-Feb 2014

Policy No: DB329311995

Veh Reg No: XB7335T

Make/Model: MITSUBISHI FV517

Chasis No: FV517JD2RDEB

Engine No: 6D24312773

Reg. Date: 10/10/2001

Estimate Repair Cost to Vehicle No :XB7335T

Description	U/Price	Quantity	List Price	Amount
			S\$	SS
List Price				
1 FRONT BUMPER	1,455.41	1 PC	Bt 1,455.41	—
2 FRONT BUMPER RH BRACKET	323.78	1 PC	Bt 323.78	—
3 FRONT BUMPER RH PROTECTOR	95.00	1 PC	D.V 95.00	—
4 FRONT BUMPER RH LAMP	423.32	1 PC	Bv 423.32	—
5 FRT BUMPER RH LAMP GARNISH	146.27	1 PC	CM 146.27	—
6 FRONT BUMPER RH SIDE PAD	132.79	1 PC	CM 132.79	—
7 FRONT BUMPER RH CENTRE GRILLE	108.68	1 PC	D.V 108.68	—
8 FRONT BUMPER RH LAMP HOUSING	65.60	1 PC	CM 65.60	—
9 FRONT RH STEP TRAY	343.12	1 PC	Bv 343.12	—
10 FRONT RH STEP TRAY SIDE GARNISH	268.68	1 PC	Bt 268.68	—
11 FRONT RH STEP TRAY HOUSING LOWER	192.54	1 PC	Bt 192.54	—
12 FRONT RH STEP TRAY BRACKET	772.23	1 PC	Bt 772.23	—
13 FRONT RH STEP TRAY BAR	527.12	1 PC	Bt 527.12	—
14 RH TOP STEP TRAY	343.12	1 PCS	CM 343.12	—
15 RH TOP STEP TRAY SIDE GARNISH	316.85	1 PCS	CM 316.85	—
16 FRONT RH SIDE LAMP	167.63	1 PC	Bv 167.63	—
17 FRONT RH SIDE RIM Side lamp Rim	241.22	1 PC	mi 241.22	—
18 FRONT GRILLE	551.31	1 PC	551.31	?
19 FRONT RH CORNAL PANEL	845.18	1 PC	Bt 845.18	—
20 RH HEAD LAMP	653.20	1 PC	653.20	?
21 FRONT PANEL EMBLEM (MITSUBISHI)	298.15	1 PC	na 298.15	—
22 FRONT PANEL LOGO	57.30	1 PC	na 57.30	—
23 FRONT RH DOOR	5,883.87	1 PC	Bt 5,883.87	—
24 FRONT WINDSCREEN GLASS	2,620.67	1 PC	ext 2,620.67	—
25 FRONT WINDSCREEN GLASS RUBBER	589.98	1 PC	na 589.98	508.98
26 FRONT RH SIDE MIRROR	538.94	1 PC	Bv 538.94	—
27 FRONT RH SIDE MIRROR SQUARE	190.00	1 PC	mi 190.00	—
28 FRONT RH SIDE MIRROR ROUND	125.34	1 PC	mi 125.34	—
29 FRONT RH SIDE MIRROR BRACKET	195.67	1 PC	Bt 195.67	—
30 FRONT RH WINDSCREEN PILLAR	2,040.10	1 PC	Bt 2,040.10	—
31 GEAR BOX OIL COOLER	1,971.30	1 PCS	Bt/pr 1,971.30	—
			22,484.37	
	Less 25%		5,621.09	16,863.28

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY

#27-02 AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 20/02/2014

TP Veh Reg No: XB5471X

Estimate No: ES1490345/YISHUN

Date: 25 Feb 2014

Policy No: DB329311995

Veh Reg No: XB7335T

Make/Model: MITSUBISHI FV517

Chasis No: FV517JD2RDEB

Engine No: 6D24312773

Reg. Date: 10/10/2001

Estimate Repair Cost to Vehicle No :XB7335T

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
32 TOWING	150.00	1 LA	150.00	1200
33 REMOVE AND REFIX FRONT WINDSCREEN GLASS	120.00	1 LA	120.00	✓
34 REMOVE AND REFIX DASH BOARD, METER ASSY & CHECK WIRING	250.00	1 LA	250.00	2200
35 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS & SIDE LAMPS, SIDE MIRROR ASSY, STEP ASSY & BRACKETS, CORNAL PANEL, FRT RH DOOR & ATTACHMENT. TO CUTTING, WELDING FRT RH W/SCREEN PILLAR. KNOCK & REPAIR FRT RH FLOOR BOARD & DOOR, RR SIDE PANEL & REALIGN THE SAME	2,000.00	1 LA	2,000.00	15000
36 REMOVE & REFIX GEAR BOX OIL COOLER, BRAKE, AIR-TANK & CHECK GEAR BOX & BRAKE SYSTEM	280.00	1 LA	280.00	1800
37 PUTTY & RESPRAY ON FRT RH W/SCREEN PILLAR, FRT RH DOOR, DOOR REAR SIDE PANEL, FRT PANEL, CORNAL PANEL, FLOOR BOARD, FRT BUMPER & AFFECTED AREAS	1,200.00	1 LA	1,200.00	10000
38 REMOVE & REFIX FRT RH DOOR GLASS & CHECK CENTRE LOCKING & POWER MIRROR	60.00	1 LA	60.00	✓
39 RUSTPROOFING	100.00	1 LA	100.00	900
			4,160.00	4,160.00

Total S\$ 21,023.28

Add GST @ 7% 1,471.63

Total Amount Payable S\$ 22,494.91

- Not Authorised*
- LKK Auto Consultants Pte Ltd
- Resurvey before/after Spray Painting.
 - Damaged parts to Display when Re-inspection.
 - Parts prices subject to confirmation.
 - Third Party Survey without prejudice.
 - No illegal modification is allowed.
- 21 May 07*

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE