

Guo Qianf.

UKK

01/07/14

* Requir wheel Alignment
repat before the replace
the under carriage.and will pay for the
fees \$120.

ASPEC CARCARE CENTRE
176 SIN MING DRIVE
#04-17 SIN MING AUTOCARE
SINGAPORE 575721
TEL: 64516985 FAX: 68540685

FACSIMILE TRANSMITTAL SHEET

TO: Motor Claims Department	FROM: Terrence Lim
COMPANY: AIG Insurance Pte Ltd	DATE: 01-Jul-14
FAX NUMBER: 68357416	TOTAL NO. OF PAGES INCLUDING COVER:
PHONE NUMBER: 64193000	SENDER'S REFERENCE NUMBER: SJE2169P
RE: Estimate repair cost of SJE2169P	YOUR REF NUMBER: SKF2972U

☐ URGENT ☐ FOR REVIEW ☐ PLEASE COMMENT ☒ PLEASE REPLY ☐ PLEASE RECYCLE

Dear Sir/Madam,

Vehicle No : SJE2169P
Make & Model : Hyundai/ Advante
Date of accident : 28/06/2014

We are pleased to quote you the repair cost for above-mentioned vehicle:

QTY	PARTS DESCRIPTION	UNIT PRICE	TOTAL
1	Rear bumper ?		423.20
1	Rear bumper side retainer (RH) ✓		35.30
1	Rear right door ✓		856.10
1	Rear right door handle ✓		78.50
1	Rear fender (RH) X Repair.		562.80
1	Sport rim ✓		356.80
1	185/65/R15 tyre ✓ (60%)		200.00
1	Rear right Shock absorber ?		256.90
1	Rear right knuckle ?		254.70
1	Rear right knuckle bearing ?		121.10
1	Rear right lower arm ?		269.50
1	Rear right upper arm ?		211.20
	Parts before discount		3626.10
	Parts percentage discount 15%		543.92
	Parts Total		3082.18

LABOUR CHARGES & MISC			
1	Labour to dismantle, panel beat, replace rear bumper, rear fender, door all necessary parts		1000.00
2	To putty and spray paint		800.00
3	To provide undercoating		60.00
4	To dismantle and install rear right under carriage		250.00
5	To perform wheel alignment		60.00
Labour Total			2170.00
Labour & Parts Total			5252.18

400
600
✓
?
✓

Terrence Lim
Aspec Carcare Centre

5 Days.

lump sum repair.

01/7/14.

Guo Qiang. 8288 0282.

Marcus - or - Guo Qiang @ lkk auto.com