

MBM WHEELPOWER PTE LTD

Your Ref: SFK36T
Our Ref: SKJ369D


To: First Capital Insurance Ltd

CC Motor Claims Dept

Email

Fax

FINALISE FOR VEHICLE NO. : SKJ369D



Date: 12.9.2014
From: Gary Wong
Fax: 6452 5333
Contact: 8138 7188
Make / Model: Bentley Flying Spur
Chassis No.: SCBBH53W7DC079107
Engine No.: CKH013161
Accident Date: 14.7.2014

DESCRIPTION	PART NO.	QTY	LIST PRICE
Rear boot lid	3W5 827 025 A	1	\$ 15,099.00
Rear boot lid weatherstrip	3W5 827 705 A	1	\$ 685.00
Rear boot lid lock with mirco switch latch	3W5 827 501 F	1	\$ 1,125.00
Rear boot lid lock end plate	3W5 827 517 B	1	\$ 126.00
Rear boot lid hinge LH	3W5 827 301 A	1	\$ 1,785.00
Rear boot lid hinge RH	3W5 827 302 A	1	\$ 1,785.00
Rear boot lid inner logo	3W0 853 630 J	1	\$ 1,407.00
Rear boot lid inner push button switch	3W5 959 831 B	1	\$ 378.00
Tail lamp with chrome LH	3W5 945 095 L	1	\$ 4,455.00
Tail lamp with chrome RH	3W5 945 096 L	1	\$ 4,455.00
Rear bumper	3W5 807 417 AD	1	\$ 7,875.00
Rear bumper retainer LH	3W5 807 375 B	1	\$ 336.00
Rear bumper retainer RH	3W5 807 376 B	1	\$ 336.00
Rear bumper retainer center	3W5 807 862 H	1	\$ 725.00
Rear bumper reinforcement	3W5 807 305 H	1	\$ 1,743.00
Rear bumper sponge	3W5 807 251 B	1	\$ 495.00
Rear bumper reverse camera cover	3W5 807 210 B	1	\$ 460.00
Rear bumper chrome moulding LH	3W5 807 811 F	1	\$ 895.00
Rear bumper chrome moulding RH	3W5 807 812 F	1	\$ 895.00
Rear bumper reverse sensor bracket	3W0 919 485	2	\$ 180.00
Rear bumper reverse lamp LH	3W0 941 071 A	1	\$ 714.00
Rear bumper reverse lamp RH	3W0 941 072 A	1	\$ 714.00

Rear bumper plate number lamp	1J6 943 021 B	2	\$	<i>220</i>	220.00	✓
Rear bumper speed nut	N 909 591 01	10	\$	<i>45</i>	45.00	✓
Rear end panel - upper	3W5 813 307 C	1		Repair		
Rear end panel - lower	3W5 813 301 A	1		Repair		
Rear end panel top garnish	3W5 863 459 K	1	\$	<i>861</i>	861.00	✓

Special Nett

Reverse sensor	4H0 919 275 A	4	\$	<i>400</i>	1,600.00	✓
Rear bumper number plate		1	\$	<i>100</i>	100.00	✓

LABOUR


To remove & install damage area	\$	<i>1400</i>	1,800.00
To rust proofing damage area	\$	<i>720</i>	100.00
To check wiring and lighting	\$	<i>80</i>	40.00
To remove & install reverse sensor	\$	<i>120</i>	60.00
To remove & install rear boot lid inner component to facilitate repair	\$	<i>180</i>	180.00
To remove & install rear upholstery to facilitate repair	\$	<i>180</i>	100.00
To re-align exhaust tail pipe	\$	<i>60</i>	60.00
To reset ECU system	\$	<i>250</i>	250.00
To spray painting on affected area	\$	<i>1000</i>	1,000.00

Total:	\$	<i>5264</i>	53,084.00
Supplementary item:	\$	5624	3,560.00
Total:	\$	<i>5624</i>	56,644.00
7% GST:	\$		3,965.08
Grand Total:	\$		60,609.08

MBM WHEELPOWER PTE LTD

Your Ref: SFK36T

Our Ref: SKJ369D



To: First Capital Insurance Ltd

CC Motor Claims Dept

Email

Fax

Date: 12.9.2014

From: Gary Wong

Fax: 6452 5333

Contact: 8138 7188

Make / Model: Bentley Flying Spur

Chassis No.: SCBBH53W7DC079107

Engine No.: CKH013161

Accident Date: 14.7.2014

SUPPLEMENTARY FOR VEHICLE NO. : SKJ369D

DESCRIPTION

Air suspension ECU

QTY

1

LIST PRICE

\$ 3,560.00

Total: \$ 3,560.00

7% GST: \$ 249.20

Grand Total: \$ 3,809.20

mbm wheelpower pte ltd

2 kung chong road singapore 159140

t 64583198 f 64586018

Company Registration Number : 200204110W

GST Reg No: M90368446L