


MBM WHEELPOWER PTE LTD



mbm wheelpower

Your Ref: SFK36T

Our Ref: SKJ369D

To: First Capital Insurance Ltd

CC Motor Claims Dept

Email

Fax

Date: 15.7.2014

From: Gary Wong

Fax: 6452 5333

Contact: 8138 7188

Make / Model: Bentley Flying Spur

Chassis No.: SCBBH53W7DC079107

Engine No.: CKH013161

Accident Date: 14.7.2014

ESTIMATE FOR VEHICLE NO. : SKJ369D

DESCRIPTION	PART NO.	QTY	LIST PRICE
Rear boot lid	3W5 827 025 A	1	15099.
Rear boot lid weatherstrip	3W5 827 705 A	1	625.
Rear boot lid lock with mirco switch latch	3W5 827 501 F	1	1125
Rear boot lid lock end plate	3W5 827 517 B	1	126.
Rear boot lid lock cable releasing	3W5 827 531 B	1	7X
Rear boot lid hinge LH	3W5 827 301 A	1	1785
Rear boot lid hinge RH	3W5 827 302 A	1	1785
Rear boot lid damper	3W5 827 550 B	2	7X
Rear boot lid drive unit	3W5 827 852 B	1	7X
Rear boot lid inner garnish trim LH	3W5 863 667 G	1	7X
Rear boot lid inner garnish trim RH	3W5 863 668 G	1	7X
Rear boot lid inner logo	3W0 853 630 J	1	1807
Rear boot lid inner push button switch	3W5 959 831 B	1	378
Tail lamp with chrome LH	3W5 945 095 L	1	4455
Tail lamp with chrome RH	3W5 945 096 L	1	4455
Third brake lamp	3W5 945 097 B	1	7X
Rear bumper	3W5 807 417 AD	1	7875.
Rear bumper retainer LH	3W5 807 375 B	1	336
Rear bumper retainer RH	3W5 807 376 B	1	336
Rear bumper retainer center	3W5 807 862 H	1	725.
Rear bumper reinforcement	3W5 807 305 H	1	1743
Rear bumper sponge	3W5 807 251 B	1	495
Rear bumper sponge cover	3W5 807 795	1	7X
Rear bumper impact padding LH	3W5 807 357 B	1	7X
Rear bumper impact padding RH	3W5 807 358 B	1	7X

mbm wheelpower pte ltd

2 kung chong road s159140

t 64583198 f 64586018

Company Registration Number : 200204110W

Rear bumper spoiler - upper	3W5 807 433
Rear bumper spoiler - lower	3W5 807 100
Rear bumper reverse camera cover	3W5 807 210 B
Rear bumper chrome moulding LH	3W5 807 811 F
Rear bumper chrome moulding RH	3W5 807 812 F
Rear bumper reverse sensor bracket	3W0 919 485
Rear bumper reverse lamp LH	3W0 941 071 A
Rear bumper reverse lamp RH	3W0 941 072 A
Rear bumper plate number lamp	1J6 943 021 B
Rear bumper speed nut	N 909 591 01
Rear end panel top strut impact beam - top	3W5 813 625
Rear end panel top strut impact beam - bottom	3W5 813 525 A
Rear end panel - upper	3W5 813 307 C
Rear end panel - lower	3W5 813 301 A
Rear end panel top garnish	3W5 863 459 K
Spare wheel compartment well	3W5 803 261 F
Spare wheel compartment well bolt	4A0 803 899 G
Exhaust chrome tip LH	3W0 253 681 H
Exhaust chrome tip RH	3W0 253 682 H

1 > m
 1 x m
 1 ? 460 m
 1 m - 895
 1 m - 895
 2 m - 180
 1 m - 714
 1 m - 714
 2 m - 210
 10 m - 45
 1 ? x m
 1 x m
 1 x m
 1 x m
 1 x m
 1 x m
 1 x m
 1 x m
 1 x m
 1 x m

Special Nett

Reverse sensor	4H0 919 275 A
Rear bumper number plate	

4 1600
 1 \$ 100.00

LABOUR

To remove & install damage area	\$ 2,000.00
To rust proofing damage area	\$ 120.00
To check wiring and lighting	\$ 80.00
To remove & install reverse sensor	\$ 120.00
To remove & install rear boot lid inner component to facilitate repair	\$ 250.00
To remove & install rear upholstery to facilitate repair	\$ 180.00
To re-align exhaust tail pipe	\$ 80.00
To reset ECU system	\$ 350.00
To spray painting on affected area	\$ 1,200.00

Total: \$ 4,480.00
 7% GST: \$ 313.60
Grand Total: \$ 4,793.60

Please survey the vehicle at No. 2 Kung Chong Road S(159140)

(Kindly contact us @ 8138 7188)

Not Audit
 2/1/14
 Tel: 62562581

Ref: 67414108

12/7/14

mbm wheelpower pte ltd

2 kung chong road s159140

t 64583198 f 64586018

Company Registration Number : 200204110W