



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: FY 14/15/0024
Our Ref: CC2/MIDA14015461/Rz

8/1/2018

HQ-Transport Command
Kranji Camp 3
151 Chua Chu Kang Way
Singapore 688248

Attn : MWO Vennu

Dear Sir,

ACCIDENT INVOLVING VEHICLES MID 46043 & SDZ 858H ON 01/8/2014

We refer to the above matter.

Please be informed that we had received the claim from M/s Munich Automobile Pte Ltd acting on behalf of third party. Although civilian car was being surveyed by our surveyor, TP's repairer did not initiate their claim till date.

As there is no further development, as per approval we shall proceed to close file at our end.

Our note of charges are enclosed for your necessary action.

Yours faithfully

Zayer
Claims Section
DID: 6841 2409
Fax: 6741 4108
Email: zayer@lkkauto.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MINISTRY OF DEFENCE

Ref : CC2/MIDA14015461/Rzq2

HQ TRANSPORT COMMAND

KRANJI CAMP 3

151 CHO A CHU KANG WAYSINGAPORE 688248

Date : 05-01-2018



Code : MIDA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	MID 46043	Veh. Inspected	SDZ 858H
Policy No.		Coverage (\$)	0.00
Claim No.	FY14/15/0024	Excess (\$)	0.00
Assign From		Assign Date	13/08/2014

2. Vehicle Particulars & Condition

Make & Model	BMW 730	c.c	2996
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WBAHN22000DE97508	Colour	BLACK
Odometer	146126	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/50 R18	DUNLOP	7 mm
L/H Front Tyre	245/50 R18	DUNLOP	7 mm
R/H Rear Tyre	245/50 R18	DUNLOP	7 mm
L/H Rear Tyre	245/50 R18	DUNLOP	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/08/2014	Inspection Date	13/08/2014
Survey held at	MUNICH AUTOMOBILES PTD LTD 30 TEBAN GARDENS CRESCENT SINGAPORE 608927		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDZ 858H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER PANEL (SN)	DENTED	1,406.10	1,406.10
1	SUPPORT (SN)	* CHECK	18.60	-
1	HEAT INSULAT (SN)	* CHECK	37.30	-
1	COVER (SN)	* CHECK	15.15	-
1	SHOCK ABSORB (SN)	* CHECK	73.70	-
1	COVER (SN)	* CHECK	68.15	-
1	COVER (SN)	* CHECK	68.15	-
1	SUPPORT (SN)	* CHECK	18.60	-
1	SET OF CABLE (SN)	* CHECK	108.20	-
1	TAIL LIGHT F (SN)	* CHECK	28.55	-
1	REAR LIGHT I (SN)	NOT NECESSARY	345.10	-
4	PDC SENSOR @\$307.95 (SN)	* CHECK	1,231.80	-
1	A010636D NUT (SN)	NECESSARY	0.75	0.75
6	A010646B NUT @\$0.90 (SN)	NECESSARY	5.40	5.40
11	SP03119 RIVET @\$0.50 (SN)	NECESSARY	5.50	5.50
			3,431.05	1,417.75
<u>LABOUR</u>				
	REPLACING ONE REAR BUMPER PANEL .		143.00	143.00
	REPLACING AND RE-SECURING REAR PDC SENSOR WIRE HARNESS.		198.00	198.00
	REPLACING ALL 4 PDC SENSOR (REAR).	* CHECK	110.00	-
	REPLACING REAR BUMPER SUPPORT PANEL.	* CHECK	330.00	-
	PAITING ONE REAR BUMPER PANEL .		748.00	748.00
	RE-CALABRATING REAR PDC SENSORS (AFTER REPLACEMENT).	* CHECK	132.00	-
			-	-
			-	-
			-	-
			1,661.00	1,089.00
GRAND TOTAL			5,092.05	2,506.75

Report Ref No. CC2/MIDA14015461/Rzq2



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2240.20 NETT)			2,506.75
--	--	--	----------

Report Ref No. CC2/MIDA14015461/Rzq2

LOW CHOW CHUEN

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (65) 62563561 FAX: (65) 62564315

Your Ref: FY 14/15/0024
Our Ref: CC2/MIDA14015461/Rz

5/9/2017

HQ-Transport Command
Kranji Camp 3
151 Chua Chu Kang Way
Singapore 688248

Attn : MWO Vennu

Dear Sir,

ACCIDENT INVOLVING VEHICLES MID 46043 & SDZ 858H ON 01/8/2014

We refer to the above matter.

Please be informed that we had received the claim from M/s Munich Automobile Pte Ltd acting on behalf of third party. Although civilian car was being surveyed by our surveyor, TP's repairer did not initiate their claim till date.

FYI, we also did not receive SAF, Police Report till date. As there is no further development we shall proceed to close file at our end.


Your approval please.

Yours faithfully


Zayer
Claims Section
DID: 6841 2409
Fax: 6741 4108
Email: zayer@lkkauto.com

*Please close this case.
We do not have the
Doc to support this case.
2014, long time*

APPROVED

 5/9/17
S1510466Z
1WO VENU SIO T SUPPIAH
TA INVESTIGATION WO
HQ TRANSPORT



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDZ 858H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

