

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

COMPANY / GST REG. NO: 201316380R

7.91 A x A

JLX 8681

[illegible]

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 2-7

TP/AYA

ESTIMATE

JLX 8681

				Proton	Exora
1pc	Rear Bumper	draw ✓		\$	
3pc	Rear Bumper Side Retainer	draw ✓		\$	
1set	Rear Bumper Clip	use ✓		\$	
1pc	Rear Bumper Top Step Guard	use ✓		\$	
1pc	Rear Bumper Top Beam	draw ✓		\$	
1pc	Rear Bumper Reinforcement	draw ✓		\$	
1pc	Rear Bumper Sponge	draw ✓		\$	
2pc	Rear Bumper Reflector	draw ✓ ACG, AVE		\$	
1pc	End Panel Outer	draw ✓		\$	
1pc	End Panel Inner	draw ✓		\$	
1pc	End Panel Top Trim	draw ✓		\$	
1set	End Panel Top Trim Clip	use ✓		\$	
1pc	Rear Floor Panel	draw ✓		\$	
2pc	Rear Chassis Frame Member	draw X		\$	
2pc	Rear Air Vane	X		\$	
2pc	Rear Fender Inner Trim	draw ✓		\$	
2set	Rear Fender Inner Trim Clip	use ✓		\$	
2pc	Rear Fender Inner Shield	draw ✓		\$	
2set	Rear Fender Inner Shield Clip	use ✓		\$	
2pc	Tail Lamp	draw ✓		\$	
2pc	Tail Lamp Inner Sealer	X		\$	
2set	Tail Lamp Clip	X		\$	
2pc	Tail Lamp Panel	X		\$	
2pc	Tail Lamp Bottom Corner Panel	draw X		\$	
1pc	Rear Bumper Towing Cover	draw ✓		\$	

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

COMPANY / GST REG. NO: 201316380R

JLX 8681

ESTIMATE

Problem Extra

[illegible]

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 4 - 7

JLY 8681

TP/AXA

ESTIMATE

Proton Exora

	1pc	Bonnet	huc	✓	\$
	2pc	Bonnet Side Rubber	huc	✓	\$
	1pc	Bonnet Inner Rubber	huc	✓	\$
	1pc	Bonnet Inner Lock	huc	✓	\$
	1pc	Bonnet Lock Cable		✓	\$
	2pc	Bonnet Hinge		✓	\$
	1pc	Front Bumper	huc	✓	\$
	2pc	Front Bumper Side Retainer	huc	✓	\$
	1pc	Front Bumper Clip	huc	✓	\$
	1pc	Front Bumper Reinforcement	huc	✓	\$
	1pc	Front Bumper Sponge	huc	✓	\$
	1pc	Front Bumper No Plate Base Garnish	huc	✓	\$
	1pc	Front Bumper Lower Grille		8	\$
	2pc	Front Bumper Fog Lamp	huc	✓	\$
	2pc	Front Bumper Fog Lamp Cover		✓	\$
	1pc	Engine Under Cover		✓	\$
	1pc	Engine Under Cover Clip		✓	\$
	1pc	Front Grille	huc	✓	\$
	1pc	Front Grille Chrome Moulding	huc	✓	\$
	1pc	Front Grille Badge	huc	✓	\$
	1pc	Front Grille Clip	huc	✓	\$
	2pc	Head Lamp	HSCVC 087	✓	\$
	2pc	Head Lamp Lower Retainer	huc	✓	\$
	2pc	Head Lamp Clip	huc	✓	\$
					\$

Photo

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

COMPANY / GST REG. NO: 201316380R

Page 5-7

ESTIMATE

SLX 8681

[illegible]

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 6-7

TP AXA

ESTIMATE

JLx 8681

Proton Exchange

[illegible]

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

COMPANY / GST REG. NO: 201316300R

TP/AKa

3LX 8681

Special Note

Proton Excess

		Special	Price	
1pc	Rear w/Screen Sealant		\$ 60	40
1pc	Rear No-Plate w/cover		\$ 70	X
1pc	Reverse Camera	avh	\$ 450	350
1pc	Reverse Sensor	shunt	\$ 250	220
1pc	Body Panel Join Sealant		\$ 120	80
1pc	Rear Floor Panel Insulator Pad		\$ 150	120
1pc	Front No-Plate w/cover		\$ 70	40
1pc	Rockler Coolant		\$ 40	
			\$	
		Not Authorised	\$	
		HS Repair	\$ -	
	Labour	13 w/days	\$ 2600	2000-
1	Panel Beating	After Paint Done	\$ 2400	2000
2	Spray Painting	28/10/2011	\$ 180	100
3	Anti Rust	1st Auto	\$ 100	60
4	Check Wiring		\$ 70	60
5	Towing Fee		\$ 140	120
6	Remove and Install Rear w/Screen		\$ 90	60
7	Remove and Install Tail Gate Bar		\$ 120	80
8	Remove and Install Carpet and Seat		\$ 90	80
9	Remove and Install Reverse Camera		\$ 90	60
10	Remove and Install Reverse Sensor		\$ 250	120
11	Remove and Install Center and Rear Exhaust		\$ 260	100
12	Remove and Install Rear Under Carriage		\$ 90	80
13	To Check Four Wheel Alignment		\$ 320	250
14	To Jack and Alignment Chassis Frame Member		\$ 150	120
15	Remove and Install Air Con			