

INS. CASE OWNER:

GALHA

CC 6 /AIG140 22149

1/11/14 y3 9

LKK:

IDAC:

ASSIGNMENT

Surveyor:

MCF

DOI:

26-11-14

Date / Time:

26-11-14

Registered in Merimen:

27-11-14

Pre-assign / CCU / FTE



Insured Vehicle No.:

SIM 6500E

Claim No.:

7118.53713159

Name of Insured:

Tan Yuh Hui

Policy No.:

2100180424

Insured Tel No.:

HP: 9620 2397

Make / Model:

Toyota

Excess Sec II :SS

D.O.A: 24-11-14

Place of Accident:

CTE (Tuds city) R4 EXT TO KKH

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO Insured Liability:

% Final ? Yes / No

SIM 6500E

SJP 84844

SGT 5543D



INSRS:

WSP:

Tel:

Liability: OL

RMKS:



INSRS:

WSP: EM-1

Tel:

Liability: TP

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

2-12

Kc-

FOR CSO ONLY:

Is driver the owner? (YES / NO)

If NO, Driver Name / Age:

Driver's Own Vehicle Number:

Insurance Company:

STAGE

DATE / PIC

Finalisation:

Email AIG for OI GIA:

Apt letter to OI:

Call OI:

After call ltr to OI:

Type Report:

Prepare Invoice:

Others:

Documentation Check List: Handler Typist

OI Apt Ltr:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

LTA / GIA:

Medical Bill:

Approval Email: PHOTOCOPY

Payment Breakdown Form:

Others: TP O/L

03/12/14 6:30PM

04/12/14 11:59AM

08/12/14 11:09AM

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

21-12-14

Surveyor:

MHA

ASSIGNMENT

From: _____ Date: 1/12

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s EM1

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SSP 84845 Yr Regn: APR / 09Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /4 Truck / Trailer or _____Make: Toy c.c. 1496Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 119902 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: N2T260-3028056Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/50R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONFront 7 mm Rear 7 mmR/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 24/1/2012 D.O.I. 26/1/2012

Survey held at _____

Des. of Damages: FR / REAR / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	FINISHED COR U9 @ 18,000.00 WITH 14 WORKING DAYS
	CRED: @ 19,472.90 (52%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, \$ _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)

☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG14022149/M1h2y3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 27-11-2014	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJU 6500E	Veh. Inspected	SJP 8484G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/11/2014
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	24/11/2014	Inspection Date	26/11/2014
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

CLEAR (AUTO CLAIM PD & BI TECHNICAL REPORT)

File Handler :

File Reference Number:

Insured Version of Accident:

Third Party Version of Accident:

Liability Assessment:

Police Investigation Result: No

Exposure:

OD:

Reserves / Settled

: /

PD:

Reserves / Settled

: /

BI:

Reserves / Settled

: /

TOTAL

Reserves / Settled

: /

Management Alert : Yes/No –

Major Loss Report : Yes/No –

Suspected Fraud: Yes / No -

If "Yes", please attach Red Flag Checklist.

US Citizen: Yes/No -

If "Yes", provide the following data:

1. First Name:
2. Last Name:
3. Passport Number:
4. Social Security Number:

Coverage:

1. Name Driver Policy In order: Yes / No.

If "No", please provide details:

2. Policy Effective Dates:
3. Date of Loss:
4. Coverage Provided: Comp / TPFT / TP only
5. Breach of Policy T & C: Yes / No.

If "Yes", please comment:

REFER TO MERIMEN

Independent Evidence: Yes / No
Insured Engaged: Yes / No. -
Investigation Firm Appointed:
Surveyor/Re-surveyor Appointed: LKK
<u>Claim Advice on Feature:</u> Make/Model/Year: TP Survey Report (SR): Days Recommended for Repairs: TP Workshop Name: Workshop Quantum: COR = \$ LOR/U = \$ SR Fees = \$ LTA/GIA/TP search Fee = \$ Legal cost & Incidentals = \$ Total = \$ Global Sum = \$
Claims Examiner's Comments:
<u>Claim Advice on Feature: C (TPBI)</u> <u>Bodily Injuries / Quantum:</u> Claimant's Name: Gender/ Age: Occupation/Salary: Hospital / Clinic Medical Report obtained from: Doctor's Clinical Observation: Doctor's Diagnosis: Medical Leave Period: Further Follow Up: Injury Quantum: General Damages = <i>(specify injuries/damages)</i> Special Damages = <i>(specify damages)</i> Disbursements = Costs & incidentals = Total =
Recovery / Subrogation:
Reason WOS Issued:
File Handler's Recommendations:
Action Plan:
Comments:

VIC

SJP 8484G

Toyota Premio

TIP ALL ASIA PACIFIC.

List Pg 1 — 3606.30
Pg 2 — 6933.40
Pg 3 — 2686.00
Pg 4 — 6121.00
Pg 5 — 4709.90

24056.60

- 25% — 18042.45

S/N — 950

Labour — 5180

24172.45

- 20% — 19337.96

\$ 18K

14 w/days

OK Confirmed.

18,272

my calculation

* Agree with 14 w/days

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 1 of 6

TP/AIG

ESTIMATE

SJP 8484 G

Toyota Premio N2T200

1pc	Boot Lid	1A	✓	\$ 825.00
1pc	Boot Lid Bodge	NRC	✓	\$ 62.00
1pc	Boot Lid Emblem (Premio)	NRC	✓	\$ 62.00
1pc	Boot Lid Emblem (F)	NRC	✓	\$ 58.00
1pc	Boot Lid Outer Chrome Moulding	dis	✓	\$ 272.80
1set	Boot Lid Outer Chrome Moulding clip	NRC	✓	\$ 30.00
2pc	Boot Lid N.O. plate Lamp	SSMC	✗	\$ 170.00
1pc	Boot Lid Opener switch	QHOA	✓	\$ 135.50
2pc	Boot Lid Lamp	ovg @321	✓	\$ 642.00
2pc	Boot Lid Lamp Inner Sealer	NRC @30	✓	\$ 60.00
2set	Boot Lid Lamp clip	NRC @25	✓	\$ 50.00
2pc	Boot Lid Stopper	NRC @18	✓	\$ 36.00
1pc	Boot Lid Inner Lock	1A	✓	\$ 395.00
1pc	Boot Lid Lock Cable	N/A.	✗	\$ 85.00
1pc	Boot Lid Lock Catch	1A	✓	\$ 46.20
1pc	Boot Lid w/strip	dis	✓	\$ 185.00
1pc	Boot Lid Insulator	dis	✓	\$ 429.80
1set	Boot Lid Insulator clip	NRC	✓	\$ 40.00
2pc	Boot Lid Hinge	R @125	✓	\$ 250.00
2pc	Boot Lid Hinge Cover	NRC @80	✗	\$ 160.00
2set	Boot Lid Hinge Cover clip	N/A @20	✗	\$ 40.00
				\$
				\$
				\$
				\$

40

20

2

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 6

T/A/G

ESTIMATE

5588484 G

Toyota Premio NZT260

1pc	Rear Bumper	del	✓	\$ 1431.60
2pc	Rear Bumper Side Retainer	dis @95	✓	\$ 190.00
1set	Rear Bumper Clip	u/c	✓	\$ 50.00
2pc	Rear Bumper Dampers	W @82	✓	\$ 164.00
1pc	End Panel	bt	✓	\$ 265.00
1pc	End Panel Top Trim	dis	✓	\$ 189.20
1set	End Panel Top Trim Clip	u/c	✓	\$ 30.00
1pc	Spare Tyre Panel	bul	✓	\$ 975.50
1pc	Spare Tyre Panel Top Board	dis	✓	\$ 478.20
1pc	Spare Tyre Top Sponge Tray	NAP	X	\$ 172.20
1pc	Spare Tyre Wheel Nut	bt	✓	\$ 56.20
2pc	Rear Chassis Frame Member	@687.20	X	\$ 1374.40
1pc	Rear Key Antenne sensor	cu9	✓	\$ 192.50
1pc	Rear Fender AT	bt	✓	\$ 1100.00
2pc	Rear Fender Inner Trim	@568	✓	\$ 1136.00
2set	Rear Fender Inner Trim Clip	@30	✓	\$ 60.00
2pc	Rear Fender Inner shield	@92	X	\$ 184.00
2set	Rear Fender Inner shield clip	@25	X	\$ 50.00
1pc	Rear Wipeween Moulding		✓	\$ 175.00
1pc	Rear Wipeween Inner seal		✓	\$ 50.00
				\$
				\$
				\$
				\$
				\$

60
24C

R

dis

40

2pc

2pc

u/c

u/c

COMPANY / GST REG. NO: 201316380R

Page 3-6

TR AG

ESTIMATE

5JP 8484 G

Toyota Premio XIT 260

[illegible]

Date:

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 6-6

Not Authorised
N/S Repair
After paint Photo
14 m/s day 3
26/11/2017 LK (MVP)
T/AIG

SJP 8484 G

ESTIMATE

Special Net

Toyota Premio N31260

1p	Rear No Plate w/cover (Special) N/S	\$ 150	200
1p	Reverse Camera	\$ 450	350 ✓
1set	Reverse Sensor DM	\$ 250	220
1p	Rear w/screen Sealant N-	\$ 60	40
1set	Body Panel Joint Sealant N-	\$ 120	80
1set	Rear Floor Panel Insulator Pad N-	\$ 150	✓
1p	Radiator Coolant N-	\$ 40	-
1p	Front No Plate w/cover (Special) N/S	\$ 150	200
		\$	
	Labour	\$	
1	Panel Beating	\$ 2800	2200
2	Spray Painting	\$ 2400	1800
3	Anti Rust	\$ 180	100
4	Check Wiring	\$ 100	60
5	Towing Fee	\$ 70	60 ✓
6	Remove and Install Rear w/screen	\$ 140	120
7	Remove and Install Carpet and Seat	\$ 150	80
8	Remove and Install Reverse Camera	\$ 150	80
9	Remove and Install Reverse Sensor	\$ 90	60
10	Remove and Install Rear Exhaust	\$ 120	80
11	Remove and Install Petrol Tank	\$ 120	80 X
12	Remove and Install Air Con	\$ 150	120
13	To Jack and Alignment Chassis Frame Member	\$ 320	280
14	Remove and Install Rear Door Part	\$ 90	60
		\$	

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 1 of 6

TP/ALG

SJP 8484 G

ESTIMATE

Toyota Premio NZT200

1pc	Boot Lid	✓	\$
1pc	Boot Lid Bodge	✓	\$
1pc	Boot Lid Emblem (Premio)	✓	\$
1pc	Boot Lid Emblem (F)	✓	\$
1pc	Boot Lid Outer Chrome Moulding	✓	\$
1set	Boot Lid Outer Chrome Moulding clip	✓	\$
2pc	Boot Lid NO. Plate Lamp	?	\$
1pc	Boot Lid Opener switch	?	\$
2pc	Boot Lid Lamp	—	\$
2pc	Boot Lid Lamp Inner Sealer	—	\$
2set	Boot Lid Lamp clip	—	\$
2pc	Boot Lid Stopper	✗	\$
1pc	Boot Lid Inner Lock	✓	\$
1pc	Boot Lid Lock Cable	✗	\$
1pc	Boot Lid Lock Catch	✓	\$
1pc	Boot Lid w/strip	✓	\$
1pc	Boot Lid Insulator	✓ ✗	\$
1set	Boot Lid Insulator clip	—	\$
2pc	Boot Lid Hinge	✗	\$
2pc	Boot Lid Hinge Cover	✗	\$
2set	Boot Lid Hinge Cover clip	✗	\$
			\$
			\$
			\$
			\$

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 2-6

T/A/G

ESTIMATE

SJ9 8484 G

Toyota Premio NZT260

	1pc	Rear Bumper	/	S
	2pc	Rear Bumper Side Retainer	/	S
	1set	Rear Bumper Clip	/	S
	2pc	Rear Bumper Dumper	✓	S
	1pc	End Panel	/	S
	1pc	End Panel Top Trim	/	S
	1set	End Panel Top Trim Clip	/	S
	1pc	Spare Tyre Panel	✓	S
	1pc	Spare Tyre Panel Top Board	✓	S
	1pc	Spare Tyre Top Sponge Tray	X	S
	1pc	Spare Tyre Wheel Nut	✓	S
	2pc	Rear Chassis Frame Member	X	S
	1pc	Rear Key Antenne sensor	?	S
	1pc	Rear Fender Rt	✓	S
	2pc	Rear Fender Inner Trim	?	S
	2set	Rear Fender Inner Trim Clip	/	S
	2pc	Rear Fender Inner shield	X	S
	2set	Rear Fender Inner shield Clip	X	S
	1pc	Rear Wipers Moulding	✓	S
	1pc	Rear Wipers Inner seal	✓	S
				S
				S
				S
				S
				S

[illegible]

COMPANY / GST REG. NO: 201316380R

Page 5-6

53P 8484 G

TP/AG

ESTIMATE

Toyota Premio NZT260

[illegible]

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 6-6

Not Authorised
HS Repur
After paint Photo
14 w/day
26/11/2014 LEE MTH
TIA AG

SJP 8484 G

ESTIMATE

Special Net

Toyota Premio NZ1260

	1p	Rear No Plate w/cover (Special) SU	\$ 150	350
	1p	Reverse Camera	\$ 450	350?
	1set	Reverse Sensor	\$ 250	220
	1p	Rear w/screen Sealant	\$ 60	40
	1set	Body Panel Joint Sealant	\$ 120	80
	1set	Rear Floor Panel Insulator Pad HU	\$ 150	✓
	1p	Radiator Coolant	\$ 40	-
	1p	Front No Plate w/cover (Special) SU	\$ 150	350
			\$	
		Labour	\$	
	1	Panel Beating	\$ 2800	2200
	2	Spray Painting	\$ 2400	1800
	3	Anti Rust	\$ 180	100
	4	Check Wiring	\$ 100	60
	5	Towing Fee	\$ 70	60
	6	Remove and Install Rear w/screen	\$ 140	120
	7	Remove and Install Carpet and Seat	\$ 150	80
	8	Remove and Install Reverse Camera	\$ 150	80
	9	Remove and Install Reverse Sensor	\$ 90	60
	10	Remove and Install Rear Exhaust	\$ 120	80
	11	Remove and Install Petrol Tank	\$ 120	80
	12	Remove and Install Air Con	\$ 150	120
	13	To Jack and Alignment Chassis Frame Member	\$ 320	280
	14	Remove and Install Rear Door Part	\$ 90	60
			\$	

Vic (LKKAuto)

From: Chia Sin Muk <em1autopteltd@gmail.com>
Sent: Wednesday, 23 May, 2018 10:41 AM
To: Vic (LKKAuto)
Cc: Admin A
Subject: Re: RE : LOD accident vehicle involving SJP 8484G & SJU 6500E ON 24.11.2014

WITHOUT PREJUDICE

Dear All,

Agree on your offer of 20,400.

Kindly arrange DV to us.

Thanks & Best Regards,

Nicole, on behalf of,

Chia Sin Muk (Mr)

m: (65) 9666 6556 | **o:** (65) 6452 3298 | **f:** (65) 6457 5776

EM-1 Auto Pte Ltd

Blk 8 #01-68 Sin Ming Rd Industrial Estate Sector C Singapore 575643

Co. / GST Registration Number: 201316380R

Important: This email is confidential and may be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.

On 21 May 2018 at 17:18, Vic (LKKAuto) <vicalpeh@lkkauto.com> wrote:

Your Ref: SJP 8484G

WITHOUT PREJUDICE

Our Ref: CC6/AIG14022149/M1ha3

Dear Nicole / Mr Chia,

ACCIDENT INVOLVING VEHICLES SJU 6500E / SJP 8484G / OTHERS ON 24/11/2014

We refer to the above matter.

On a without prejudice basis, purely for an amicable settlement and without admission of liability to our Insured's part, we have our principal's mandate and we propose a global sum (all in) of **\$20,400.00** to settle your client's claim.

If agreeable, kindly furnish us the duly signed DV and all relevant documents e.g. LOD and final Repair Invoice for payment processing.

The above amount is to be made payable to **EM-1 AUTO PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTO
CONSULTANTS
PTE LTD

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9139687D



Name

KONG WEN BIN

孔 汶 彬

Race

JAVANESE

Date of Birth

22-10-1991

Sex

M

Country of birth

SINGAPORE

S9139687D

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S9139687D

Name

KONG WEN BIN

Birth Date: 22 Oct 1991

Issue Date: 25 Jun 2011



22-10-2010

0105km

CTE -> City

before Balestier exit

Line 3

K: SJP 848TG

S: SJU 6500E

1715273



NRIC No. S9139687D



Date of issue

25-06-2011

Address

APT BLK 634 YISHUN STREET 61
#10-58
SINGAPORE 760634

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars < 3000kg with < 47 passengers, exclusive of the driver; and other motor vehicles < 2500kg 26 Oct 2010

NF 429A



EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

M/S AIG Asia Pacific Insurance Pte. Ltd.

Motor Claim Department

AIG Building

78 Shenton Way

#07-16

Singapore 079120

Proforma Invoice : 115/PI00884/3762TP

Date : 20-Jul-2015

Attn : VIC ALPEH

Date of Accident : 24-Nov-2014
Our Client's Vehicle Number : SJP 8484G
Vehicle Make / Model : TOYOTA PREMIO
Our Client / Owner Name : LIM SIOK NOI

NO.	DESCRIPTION	AMOUNT (SGD)
1	Lump Sum Repair Cost	18,000.00 SR
2	Loss of Rental (11 days x \$ 120.00)	1,320.00 SR
3	LTA Fee	5.35 ES
	----- Last Item -----	
	SUB-TOTAL (at this time)	19,325.35
	Subject to 7% GST	1,352.40

GRAND TOTAL **SGD 20,677.75**
(at this time)

SGD (Twenty Thousand Six Hundred Seventy-Seven And
Cents Seventy-Five only)



Authorised Signature and Company Stamp

Print Received Message

This mail is associated with :

***SJP8484G (7118537131SG)**
[SJU6500E]

TP
LIM SIOK NOI
Nov 24 2014 7:00AM
[Tan Yah Hui (Chen Yahui)]
Em-1 Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 09/05/2018 10:19 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$20442.35) - SJP8484G - Claim Handler: Syed-Yusoff, Saliha

Approved:20442.35:***Subject to Final Repair Bill, Rental Bill/Invoice & LTA Bill received



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG14022149/M1h2y3

09 DECEMBER 2014

TAN YAH HUI
35 PUNGGOL FIELD
#16-27
SINGAPORE 828818

Dear Sir/Madam,

ACCIDENT INVOLVING SJU 6500E / SJP 8484G / OTHERS ON 24/11/2014

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.


Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,


Vic Alpeh Sanghila
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Lim Siok Noi ("the third party claimant")
of _____ (address),
owner of SJP8484G (vehicle no.) hereby authorize
EMI-1 AUTO PTE LTD
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJP8484G that was
damaged pursuant to the accident which occurred on 24/11/14 (date) along
CTE towards City (location)
involving vehicle no/s SJU6500E ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 23 day of May (month) 20 16 (year)

Lim Siok Noi
Signed by "the third party claimant"

 
Signed by "the workshop"

LETTER OF AUTHORISATION

ACCIDENT INVOLVING (any vehicle) SJP8484G and SJU6500E,
ON 24-11-14 ALONG CTE towards City

I, Lim Siok Noi, NRIC No. / Company Reg. No.
S1585528B of (address) BLK 634 Yishun St 61 #10-58

Postal Code 760634, the registered owner (or authorised agent) of motor vehicle registration number
SJP8484G hereby authorise your workshop EM-1 Auto Pte Ltd (Company/GST REG.No. : 201316380R)

Blk 8 #01-68 Sector C Sin Ming Industrial Estate Singapore 575643 to :-

1. Begin or commence repairs to my/our motor vehicle;
2. Start or initiate third party claims for damages incurred by me against third party(ies) responsible for the accident.
3. To instruct EM-1 Auto Pte Ltd on my/our behalf to negotiate a settlement with the third party and/ or his insurers as you deem fit.
4. To appoint vehicle surveyor on my/our behalf to determine reasonable costs of repair and period of repair.
5. To act on my/our behalf for any documents mailed to EM-1 Auto Pte Ltd by the third party and/or his insurers for the claim of my vehicle, if I am not contactable.

I am prepared to attend at my/our solicitors' office or to attend Court in connection with my/our claim, if necessary, I shall give my full co-operation and support for the claim for cost of repair and loss of use and shall keep you informed of any correspondences and/or summons that I may receive due to this action before agreeing to pay up or receive any monies due to this claim.

I authorise you to claim for the period of loss of use as specified by the motor surveyor or such shorter period due to accelerated work. I further authorise you to accelerate the repair period with overtime work and additional resource, I will pay you a reasonable amount to reflect the additional period of time to shorten. I, further authorize that the monies to be made payable to EM-1 Auto Pte Ltd.

I agree to keep you informed of any document(s), including cheques, mailed to me by third party and/or his insurers before taking any action. I also will not bank in any cheques issued by third party insurance and/or his insurers without the approval of EM-1 Auto Pte Ltd, and should I get approval from EM-1 Auto Pte Ltd to bank in the said cheques, I agree to pay EM-1 Auto Pte Ltd the full settlement amount as stated on the cheques within 5 working days.

Should my/our claim be partly successful or unsuccessful or cannot be proceeded with and/or if any judgement or settlement is not honoured or satisfied by third party, I/We:

1. Agree to pay you the sum of monies (as agreed) or as certified by the surveyor appointed, being the costs of repairs, survey fees and/or any other expenses reasonably incurred by you on my/our behalf. You may use the recovered amount from my claim for loss of us to partially offset the difference.
2. Agree to pay you such increased cost for additional resources and overtime work to shorten the period of repair.
3. Will pay for any shortfall that may result in the settlement amount.

In the event that EM-1 Auto Pte Ltd or the Repairer is compelled to enforce this undertaking, I/We agree that I/we shall pay on a full indemnity basis, the legal costs incurred by EM-1 Auto Pte Ltd or the Repairer.

Signature: *Lim Siok Noi*

Company Stamp:
(if applicable)

Name:

NRIC No:

Contact No:

Date:

Lim Siok Noi

S1585528B

90035259

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, EM-1 AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$20,400.00 (Global Sum – all in for vehicle no. SJP 8484G that was damaged pursuant to the accident which occurred on 24/11/2014 (date) along CTE TOWARDS CITY (location) involving vehicle no/s SJU 6500E. This is pursuant to the inspection conducted on 26/11/2014 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LIM SIOK NOI ("the third party claimant") of vehicle no. SJP 8484G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJP 8484G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 23 (day) of May (month) **2018** (year)



MCF

Signed by appointed surveyor



Signed by "the workshop" (with chop)

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

TAX INVOICE

M/S LIM SIOK NOI

Invoice No : 18/00113/3762TP

Date : 23-May-2018

AIG Asia Pacific Insurance Pte. Ltd.

Motor Claim Department

AIG Building

78 Shenton Way

#07-16

Singapore 079120

Tel No : 68412096

Fax No : 67414108

Attn : Vic Alpeh

Date of Accident : 24-Nov-2014

Our Client's Vehicle Number : SJP 8484G

Vehicle Make / Model : TOYOTA PREMIO

Your Insurer : SJU 6500E

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost	18,000.00	1,260.00	19,260.00 SR

SGD (Nineteen Thousand Two Hundred Sixty only)

GRAND TOTAL

19,260.00

Subject to 7% GST

1,260.00



Authorised Signature and Company Stamp

Date : 12/12/2014

 To : EM-I Auto Pte Ltd
 Blk 8, #01-68 Sin Ming Rd
 Sin Ming Industrial Estate Sector C
 Singapore 575643

Tax Invoice No : S1964/14

 A/c : Lim Siok Noi
 SJP8484G
 S1585528B

 Contract No : -
 Rental Agreement No : ST/18168
 Contract Period : 24/11/14 - 05/12/14
 Payment Terms : CASH
 Payment Period : 24/11/14 - 05/12/14
 Payment Due Date : 12/12/2014

Vehicle No.	Driver	Model	Item	Amount
SKB6570R	Kong Wen Bin	Mit.Lancer	Rental Charges 11 days @ \$120 per day	\$ 1,320.00

 Total : \$ 1,320.00
 GST 7% : \$ 92.40
 Amount Payable : \$ 1,412.40

Billing Enquires

 Contact : Joleen Tan
 Tel. No. : 6743 6266
 Fax No. : 6746 8420

for Fulco Leasing Pte Ltd



Authorized Signature

Cheques should be crossed and made payable to "Fulco Leasing Pte Ltd"

>>>>>

<<<<<<

 Please detach and return with
 your remittance to :

Fulco Leasing Pte Ltd
 22 Ubi Road 4, Fulco Building
 Singapore 408617

 Invoice No : S1964/14
 Vehicle No : SKB6570R
 Due date : 12/12/2014

Amount Payable : \$ 1,412.40


Cash/Cheque :

SJP 8484G.
Toyota Premio.

22 Ubi Road 4, Fulco Building S'pore 408617
Tel: (65) 6743 6266 Fax: (65) 6746 8420

EMI

RENTAL AGREEMENT No.ST/18168

Hirer Particulars -				Veh. No. SKB 6570R		Replace Veh. No.	
Name LIM SIOK NOI.		Address		Make / Model Mt. Lancer		Auto/Manual	
Mobile		Tel (Office)		Date/Time Out 24/11/2014 0920hrs.		KM Out	
NRIC/Passport S1585528B.		Occupation		Date/Time In 05/12/2014 1400hrs.		KM In	
Employer				Estimated Date/Time Return			
				Rental Charges -		\$S	
						\$S	
Authorised Driver's Particulars -							
Name KONG WEN BIN		Address BLK 634 YISHUN STREET 61 #10-58		Hours 11		@	
NRIC/Passport S9129687D.		Nationality		Days 120		Per Hour	
Date of Birth 22-10-1991		Occupation		Weeks		Per Day 1320	
D/Licence No. S9139687D.		Pass Date 26-10-2010		Months		Per Week	
Expiry Date		Country of Issue		Per Month			
Tel (Res)		Tel (Office)		Optional Charges -			
				Delivery @		Per Trip	
				Collection @		Per Trip	
				M'sia Surcharge @		Per Day	
				PAI @		Per Day	
(A) - ACCIDENTS (D) - DENTS (S) - SCRATCHES				Others			
 FRONT  LEFT  RIGHT  REAR				Sub-Total			
				Add 7% GST 92.40			
				(A) Estimated Total Rental 1412.40			
Extension -							
Extension Rental				x			
M'sia Surcharge				x			
				x			
Others -							
				Sub-Total			
				Add 7% GST			
				(B) Extension/others Total			
				(A) + (B) Grand Total Rental Charges			
Physical Damage Excess				Less Prepayment			
Singapore - Own Damage S\$2,000.00				Balance Due			
Singapore - 3rd Party Damage S\$2,000.00							
Malaysia (if applicable) S\$8,000.00							
For Driver aged below 24 or above 65 or Less than 2 yrs driving experience regardless of age. S\$3,000.00 (Additional)							
Hirer's Acknowledgement				Mode of Payment :			
				Cash/Nets/Cheque/VISA/MC Card No.			
				Deposit			
				Amount			
				Remarks:			
				Received by			
IMPORTANT NOTE:				The hirer hereby read and understood all terms and conditions stated on this page and overleaf :			
1. Only drivers registered with FULCO Leasing Pte Ltd (the Owner) are authorised to drive the Vehicle. Should the Vehicle is damaged or stolen while being driven by unauthorised drivers, the Hirer is liable for the full cost of repair or the value of the Vehicle if the Vehicle is being stolen & other losses suffered by the Owner. 2. The Hirer shall not permit the Vehicle to be used for purposes which conflict with the Law in connection with theft, drug pedaling or trafficking, smuggling or any other criminal action. Should the Vehicle is confiscated by the Government under such circumstances, the Hirer shall indemnify the Owner the value of the Vehicle plus all cost and expenses incurred.				for Fulco Leasing Pte Ltd			
				 Hirer Signature/Co's Stamp/Date  Authorised Signature/Date			

Text size + -



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time: 24 Nov 2014 / 09:58:28

Receipt Date/Time: 24 Nov 2014 / 09:58:28

Tax Invoice/Receipt

Receipt No.: ITNET-00000-141124-000212

Previous Receipt No.:

S/N Item Description/**Business Transaction Reference
No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
--	---------------------------------	---------------------------------------

As at 24 Nov 2014/07:05:00

INSURANCE CO. AIG ASIA PACIFIC INSURANCE PTE. LTD.

- 1 Insurance Enquiry - SJU6500E
Enquiry Fee
20141124095646382155

5.00	0.35	5.35
------	------	------

Sub-Total	5.00	0.35	5.35
------------------	------	------	------

Total Before Rounding	5.00	0.35	5.35
------------------------------	------	------	------

Rounding Difference			0.00
----------------------------	--	--	------

Total Amount Payable			5.35
-----------------------------	--	--	------

Paid By

20141124095701556	Direct Debit: eNETS Debit (Internet Banking)	5.35
-------------------	---	------

Total			5.35
--------------	--	--	------

Cash Change			0.00
--------------------	--	--	------

Tendered Amount			5.35
------------------------	--	--	------

Excess Refundable Amount			0.00
---------------------------------	--	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Nov 2014 13:37 Edit Reg		26 Nov 2014 00:00 Edit Adj Rpt	S\$18,000.00 Edit Estimates	S\$18,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Tan Yah Hui (Chen Yahui), ID: S7610698C		
Main Claimant:	LIM SIOK NOI, ID: S1585528B		
Vehicle Reg. No.:	SJP8484G	Date of Loss:	24/11/2014 07:00 - :59 [67 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7118537131SG	Policy/Cover Note No.:	2100180424 (Comprehensive) Coverage: 21/12/2013 - 20/12/2014
Vehicle Reg. No. (Insured):	SJU6500E	Policy No. (Claimant):	5055185099-02
		Excess:	
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, S75643 Sin Ming - Tel: 64523298		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 08/12/2014]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- AIG_SG (09/05/2018): Alert - Adj Mandate Approved (S\$20442.35) - SJP8484G - Claim Handler: Syed-Yusoff...
- AIG_SG (13/03/2018): Alert - Adj Mandate Maintained - SJP8484G - Claim Handler: Syed-Yusoff, Saliha
- AIG_SG (06/01/2016): Alert - Adj Mandate Maintained - SJP8484G - Claim Handler: Syed-Yusoff, Saliha

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJP8484G (7118537131SG)
[SJU6500E]
TP
LIM SIOK NOI
Nov 24 2014 7:00AM
[Tan Yah Hui (Chen Yahui)]
Em-1 Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Letters/Correspondences														1 per page		☐	☒
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	(Draft)		Third Party Express Settlement – Payment Breakdown											1		Edit	
Photos/Images														3 per page		☐	☒
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	02/12/14 11:40		General View											1		Load JPG ☒	
2	02/12/14 11:40		General View											1		Load JPG ☒	
3	02/12/14 11:40		General View											1		Load JPG ☒	
4	02/12/14 11:40		General View											1		Load JPG ☒	
5	02/12/14 11:40		General View											1		Load JPG ☒	
6	02/12/14 11:40		General View											1		Load JPG ☒	
7	02/12/14 11:40		General View											1		Load JPG ☒	
8	02/12/14 11:40		General View											1		Load JPG ☒	
9	02/12/14 11:40		General View											1		Load JPG ☒	
10	02/12/14 11:40		General View											1		Load JPG ☒	
11	02/12/14 11:40		General View											1		Load JPG ☒	
12	02/12/14 11:40		General View											1		Load JPG ☒	
13	02/12/14 11:40		General View											1		Load JPG ☒	
14	02/12/14 11:40		General View											1		Load JPG ☒	
15	02/12/14 11:40		General View											1		Load JPG ☒	
16	02/12/14 11:40		General View											1		Load JPG ☒	
17	02/12/14 11:40		General View											1		Load JPG ☒	
18	02/12/14 11:40		General View											1		Load JPG ☒	
19	02/12/14 11:40		General View											1		Load JPG ☒	
20	02/12/14 11:40		General View											1		Load JPG ☒	
21	02/12/14 11:40		General View											1		Load JPG ☒	
22	02/12/14 11:40		General View											1		Load JPG ☒	
23	02/12/14 11:40		General View											1		Load JPG ☒	
24	02/12/14 11:40		General View											1		Load JPG ☒	
25	02/12/14 11:40		General View											1		Load JPG ☒	
26	02/12/14 11:40		General View											1		Load JPG ☒	
27	02/12/14 11:40		General View											1		Load JPG ☒	
28	02/12/14 11:40		General View											1		Load JPG ☒	
29	02/12/14 11:40		General View											1		Load JPG ☒	
30	02/12/14 11:40		General View											1		Load JPG ☒	
31	02/12/14 11:41		General View											1		Load JPG ☒	
32	02/12/14 11:41		General View											1		Load JPG ☒	
33	02/12/14 11:41		General View											1		Load JPG ☒	
34	02/12/14 11:41		General View											1		Load JPG ☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	02/12/14 11:41	General View	 Load JPG	☒
36	02/12/14 11:41	General View	 Load JPG	☒
37	02/12/14 11:41	General View	 Load JPG	☒
38	02/12/14 11:41	General View	 Load JPG	☒
39	02/12/14 11:41	General View	 Load JPG	☒
40	02/12/14 11:41	General View	 Load JPG	☒
41	02/12/14 11:41	General View	 Load JPG	☒
42	02/12/14 11:41	General View	 Load JPG	☒
43	02/12/14 11:41	General View	 Load JPG	☒
44	02/12/14 11:41	General View	 Load JPG	☒
45	02/12/14 11:41	General View	 Load JPG	☒
46	02/12/14 11:42	General View	 Load JPG	☒
47	02/12/14 11:42	General View	 Load JPG	☒
48	02/12/14 11:42	General View	 Load JPG	☒
49	02/12/14 11:42	General View	 Load JPG	☒
50	02/12/14 11:42	General View	 Load JPG	☒
51	02/12/14 11:42	General View	 Load JPG	☒
52	02/12/14 11:42	Chassis Number	 Load JPG	☒
53	02/12/14 11:42	General View	 Load JPG	☒
54	02/12/14 11:42	General View	 Load JPG	☒
55	02/12/14 11:42	General View	 Load JPG	☒
56	02/12/14 11:42	General View	 Load JPG	☒
57	02/12/14 11:42	General View	 Load JPG	☒
58	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
59	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
60	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
61	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
62	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
63	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
64	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
65	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
66	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
67	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
68	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
69	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
70	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
71	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
72	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
73	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
74	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
75	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
76	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
77	21/12/15 16:31	Reinspection Photo	 Load JPG	☒
78	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
79	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
80	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
81	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
82	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
83	21/12/15 16:33	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
85	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
86	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
87	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
88	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
89	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
90	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
91	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
92	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
93	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
94	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
95	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
96	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
97	21/12/15 16:33	Reinspection Photo	 Load JPG	☒
98	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
99	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
100	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
101	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
102	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
103	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
104	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
105	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
106	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
107	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
108	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
109	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
110	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
111	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
112	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
113	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
114	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
115	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
116	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
117	21/12/15 16:34	Reinspection Photo	 Load JPG	☒
118	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
119	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
120	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
121	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
122	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
123	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
124	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
125	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
126	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
127	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
128	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
129	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
130	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
131	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
132	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
133	21/12/15 16:36	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
135	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
136	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
137	21/12/15 16:36	Reinspection Photo	 Load JPG	☒
138	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
139	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
140	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
141	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
142	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
143	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
144	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
145	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
146	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
147	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
148	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
149	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
150	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
151	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
152	21/12/15 16:37	Reinspection Photo	 Load JPG	☒
153	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
154	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
155	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
156	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
157	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
158	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
159	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
160	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
161	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
162	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
163	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
164	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
165	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
166	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
167	21/12/15 16:39	Reinspection Photo	 Load JPG	☒
168	21/12/15 16:40	Reinspection Photo	 Load JPG	☒
169	21/12/15 16:40	Reinspection Photo	 Load JPG	☒
170	21/12/15 16:40	Reinspection Photo	 Load JPG	☒
171	21/12/15 16:40	Reinspection Photo	 Load JPG	☒
172	21/12/15 16:40	Reinspection Photo	 Load JPG	☒
173	21/12/15 16:40	Reinspection Photo	 Load JPG	☒
174	21/12/15 16:40	Reinspection Photo	 Load JPG	☒
175	21/12/15 16:40	Reinspection Photo	 Load JPG	☒
176	21/12/15 16:40	Reinspection Photo	 Load JPG	☒
177	21/12/15 16:40	Reinspection Photo	 Load JPG	☒
178	21/12/15 16:40	Reinspection Photo	 Load JPG	☒
179	21/12/15 16:41	Reinspection Photo	 Load JPG	☒
180	21/12/15 16:41	Reinspection Photo	 Load JPG	☒
181	21/12/15 16:41	Reinspection Photo	 Load JPG	☒
182	21/12/15 16:41	Reinspection Photo	 Load JPG	☒
183	21/12/15 16:41	Reinspection Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
184	21/12/15 16:41	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/14 14:29	TP ESTIMATE	 Load PDF	
2	27/11/14 14:29	TP GIA REPORT	 Load PDF	
3	21/07/15 16:15	TP Driving Licence	 Load PDF	
4	22/12/15 12:36	TP ESTIMATE - MARKED	 Load PDF	
5	23/12/15 11:36	RENTAL RECEIPT	 Load PDF	
6	23/12/15 11:36	LETTER TO OI	 Load PDF	
7	23/12/15 11:36	LTA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/11/14 16:47	OI GIA REPORT	 Load PDF	
2	08/12/14 13:41	CLEAR 8/12/14	 Load DOCX	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SJU6500E (Insd veh)	Model:	TOYOTA PREMIO 1.5 (A)
	SJP8484G (TP veh)		
Date of Accident:	24/11/2014		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No
Repair Estimate	:	\$	40,096.00
Final Repair Cost	:	\$	20,400.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	11 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	20,400.00

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 100 _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Em-1 Auto Pte Ltd	:	\$ 20,400.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

24 May
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG14022149/M1HA3

Date: 24/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100180424
Claimant Vehicle No : SJP8484G **Insured Vehicle No :** SJU6500E
 Date of Loss: 24/11/2014 Nature of Claim: TP Claim No: 7118537131SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJP8484G**
 Make & Model: TOYOTA PREMIO, 1.5 (A) Engine No: 1NZD293736
 Reg. Date: 14/04/2009 (Man. Year: 2008) Chassis No: NZT2603038056
 Colour: Grey Odometer: 119972 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16
 Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm
 Front Right Side: Continental 7 mm Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,592.90	17,737.92	12,854.98	42.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,880.00	5,180.00	1,700.00	24.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,472.90	22,917.92	14,554.98	38.84
Approved Total (Overridden) (S\$)		18,000.00		
(S\$)	37,472.90	18,000.00	19,472.90	51.97
+ GST 7.00/7.00% (S\$)	2,623.10	1,260.00	1,363.10	51.97
Nett Amount (S\$)	40,096.00	19,260.00	20,836.00	51.97
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)		1,177.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		20,442.35		
Global Sum Settlement (S\$)		20,400.00		

INSPECTION

Date of Assignment: 26/11/2014
 Date Inspected: 26/11/2014 Inspected At:

Em-1 Auto Pte Ltd (HQ)
Blk 8 Sin Ming Industrial Estate Sector C,
#01-68
Singapore 575643

Estimated Period of Repair: 14.0 days

Adjuster: MA CHIN FOOK

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	825.00 F	*825.00 FL
2	1		*BOOT LID BADGE	Necessary	62.00 F	*62.00 FL
3	1		*BOOT LID EMBLEM (PREMIO)	Necessary	62.00 F	*62.00 FL
4	1		*BOOT LID EMBLEM (F)	Necessary	58.00 F	*58.00 FL
5	1		*BOOT LID OUTER CHROME MOULDING	Distorted	272.80 F	*272.80 FL
6	1		*SET BOOT LID OUTER CHROME MOULDING CLIP	Necessary	30.00 F	*30.00 FL
7	2		*BOOT LID NO PLATE LAMP	Serviceable	170.00 F	*- FL
8	1		*BOOT LID OPENER SWITCH	Shorted	135.50 F	*135.50 FL
9	2		*BOOT LID LAMP	Cracked	642.00 F	*642.00 FL
10	2		*BOOT LID LAMP INNER SEALER	Necessary	60.00 F	*40.00 FL
11	2		*SET BOOT LID LAMP CLIP	Necessary	50.00 F	*30.00 FL
12	2		*BOOT LID STOPPER	Serviceable	36.00 F	*- FL
13	1		*BOOT LID INNER LOCK	Bent	395.00 F	*395.00 FL
14	1		*BOOT LID LOCK CABLE	Not Necessary	85.00 F	*- FL
15	1		*BOOT LID LOCK CATCH	Bent	46.20 F	*46.20 FL
16	1		*BOOT LID W/STRIP	Distorted	185.00 F	*185.00 FL
17	1		*BOOT LID INSULATOR	Distorted	429.80 F	*429.80 FL
18	1		*SET BOOT LID INSULATOR CLIP	Necessary	40.00 F	*40.00 FL
19	2		*BOOT LID HINGE	Repair	250.00 F	*- FL
20	2		*BOOT LID HINGE COVER	Serviceable	160.00 F	*- FL
21	2		*SET BOOT LID HINGE COVER CLIP	Not Necessary	40.00 F	*- FL
22	1		*REAR BUMPER	Deformed	1,431.60 F	*1,431.60 FL
23	2		*REAR BUMPER SIDE RETAINER	Distorted	190.00 F	*190.00 FL
24	1		*SET REAR BUMPER CLIP	Necessary	50.00 F	*40.00 FL
25	2		*REAR BUMPER DAMPER	Serviceable	164.00 F	*- FL
26	1		*END PANEL	Bent	565.00 F	*565.00 FL
27	1		*END PANEL TOP TRIM	Distorted	189.20 F	*189.20 FL
28	1		*SET END PANEL TOP TRIM CLIP	Necessary	30.00 F	*30.00 FL
29	1		*SPARE TYRE PANEL	Buckled	975.50 F	*975.50 FL
30	1		*SPARE TYRE PANEL TOP BOARD	Distorted	478.20 F	*478.20 FL
31	1		*SPARE TYRE TOP SPONGE TRAY	No such part	172.20 F	*- FL
32	1		*SPARE TYRE WHEEL NUT	Bent	56.20 F	*56.20 FL
33	2		*REAR CHASSIS FRAME MEMBER	Repair	1,374.40 F	*- FL
34	1		*REAR KEY ANTENNE SENSOR	Cracked	192.50 F	*192.50 FL
35	1		*REAR FENDER RH	Bent	1,100.00 F	*1,100.00 FL
36	2		*REAR FENDER INNER TRIM	Distorted	1,136.00 F	*1,136.00 FL
37	2		*SET REAR FENDER INNER TRIM CLIP	Necessary	60.00 F	*40.00 FL
38	2		*REAR FENDER INNER SHIELD	Serviceable	184.00 F	*- FL
39	2		*SET REAR FENDER INNER SHIELD CLIP	Serviceable	50.00 F	*- FL
40	1		*REAR W/SCREEN MOULDING	Necessary	175.00 F	*175.00 FL
41	1		*REAR W/SCREEN INNER SEAL	Necessary	50.00 F	*50.00 FL
42	1		*REAR EXHAUST SILENCER	Bent	950.00 F	*950.00 FL
43	2		*REAR EXHAUST MOUNTING	Serviceable	116.00 F	*- FL
44	1		*REAR EXHAUST GASKET	Necessary	46.20 F	*46.20 FL
45	1		*REAR EXHAUST HEAT PLATE	Serviceable	199.80 F	*- FL
46	1		*REAR DOOR RH	Bent	1,130.00 F	*1,130.00 FL
47	1		*REAR DOOR BLACK STICKER RH	Necessary	98.20 F	*98.20 FL
48	1		*REAR DOOR PROTECTOR RH	Necessary	145.80 F	*145.80 FL
49	1		*REAR DOOR W/STRIP RH	Serviceable	175.80 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*REAR DOOR INNER LOCK	Serviceable	475.00 F	*- FL
51	1		*BONNET	Dented	950.00 F	*950.00 FL
52	1		*BONNET CHROME MOULDING	Distorted	246.50 F	*246.50 FL
53	1		*BONNET INNER RUBBER	Necessary	48.00 F	*48.00 FL
54	1		*SET BONNET INSULATOR CLIP	Necessary	40.00 F	*40.00 FL
55	1		*BONNET INNER LOCK	Repair	95.60 F	*- FL
56	2		*HEAD LAMP	Cracked	1,996.00 F	*1,996.00 FL
57	2		*HEAD LAMP CLIP	Necessary	40.00 F	*40.00 FL
58	1		*FRONT GRILLE	Distorted / Cracked	425.00 F	*425.00 FL
59	1		*FRONT GRILLE BADGE	Necessary	78.00 F	*78.00 FL
60	1		*SET FRONT GRILLE CLIP	Necessary	30.00 F	*30.00 FL
61	1		*FRONT BUMPER	Deformed	1,365.00 F	*1,365.00 FL
62	2		*FRONT BUMPER SIDE RETAINER	Distorted	156.00 F	*156.00 FL
63	1		*SET FRONT BUMPER CLIP	Necessary	50.00 F	*40.00 FL
64	1		*FRONT BUMPER REINFORCEMENT	Bent	325.00 F	*325.00 FL
65	1		*FRONT BUMPER SPONGE	Distorted	118.50 F	*118.50 FL
66	1		*FRONT BUMPER LOWER GRILLE	Distorted	158.00 F	*158.00 FL
67	1		*FRONT BUMPER LOWER COVER	Distorted	95.00 F	*95.00 FL
68	1		*SET FRONT BUMPER LOWER COVER CLIP	Not Necessary	30.00 F	*- FL
69	1		*SUPPORT PANEL	Repair	1,005.50 F	*- FL
70	1		*BRACE PANEL	Bent	158.00 F	*158.00 FL
71	1		*SET HORN	Serviceable	120.00 F	*- FL
72	1		*AIR CON CONDENSER	Bent	1,689.00 F	*1,689.00 FL
73	2		*CONDENSER SIDE GARNISH	Not Necessary	138.00 F	*- FL
74	1		*SET CONDENSER SIDE GARNISH CLIP	Not Necessary	30.00 F	*- FL
75	1		*CONDENSER AIR CON PIPE	Not Necessary	276.50 F	*- FL
76	1		*CONDENSER SUCTION PIPE	Not Necessary	295.20 F	*- FL
77	1		*CONDENSER DISCHARGE PIPE	Not Necessary	286.30 F	*- FL
78	1		*RADIATOR	Bent	2,105.20 F	*2,105.20 FL
79	2		*RADIATOR TOP MOUNTING	Distorted	48.00 F	*48.00 FL
80	2		*RADIATOR TOP MOUNTING BRACKET	Serviceable	56.00 F	*- FL
81	1		*RADIATOR TOP GARNISH	Serviceable	139.20 F	*- FL
82	1		*RADIATOR FAN COWLING	Serviceable	192.50 F	*- FL
83	1		*RADIATOR FAN MOTOR	Serviceable	356.00 F	*- FL
84	1		*RADIATOR FAN BLADE	Serviceable	86.00 F	*- FL
85	1		*REAR NO PLATE W/COVER (SPECIAL)	Necessary	150.00 FS	*50.00 FS
86	1		*REVERSE CAMERA	Shorted	450.00 FS	*350.00 FS
87	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*220.00 FS
88	1		*REAR W/SCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
89	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*80.00 FS
90	1		*SET REAR FLOOR PANEL INSULATOR PAD	Necessary	150.00 FS	*120.00 FS
91	1		*RADIATOR COOLANT	Necessary	40.00 FS	*40.00 FS
92	1		*FRONT NO PLATE W/COVER (SPECIAL)	Necessary	150.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **30,592.90** **23,333.90**
 - List Item Discount on L Items 0.00/25.00% (S\$) **0.00** **5,595.98**

Total Parts (S\$) **30,592.90** **17,737.92**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	2,800.00	2,200.00
2	SPRAY PAINTING	New	2,400.00	1,800.00
3	ANTI RUST	New	180.00	100.00
4	CHECK WIRING	New	100.00	60.00
5	TOWING FEE	New	70.00	60.00
6	REMOVE AND INSTALL REAR W/SCREEN	New	140.00	120.00
7	REMOVE AND INSTALL CARPET AND SEAT	New	150.00	80.00
8	REMOVE AND INSTALL REVERSE SENSOR	New	150.00	80.00
9	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	60.00
10	REMOVE AND INSTALL REAR EXHAUST	New	120.00	80.00
11	REMOVE AND INSTALL PETROL TANK	New	120.00	80.00
12	REMOVE AND INSTALL AIR CON	New	150.00	120.00
13	TO JACK AND ALIGNMENT CHASSIS FRAME MEMBER	New	320.00	280.00
14	REMOVE AND INSTALL REAR DOOR PART	New	90.00	60.00
Gross Labour Cost (S\$)			6,880.00	5,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >