

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 1 - 6

TP/AIG

ESTIMATE

SJP 8484 G

Toyota Premio NZT260

1pc	Boot Lid	bat	✓	\$ 825.00
1pc	Boot Lid Badge	NEC	✓	\$ 62.00
1pc	Boot Lid Emblem (Premio)	NEC	✓	\$ 62.00
1pc	Boot Lid Emblem (F)	NEC	✓	\$ 58.00
1pc	Boot Lid Outer Chrome Moulding	dis	✓	\$ 272.80
1set	Boot Lid Outer Chrome Moulding clip	NEC	✓	\$ 30.00
2pc	Boot Lid N.O. plate Lamp	SSMC	X	\$ 170.00
1pc	Boot Lid Opener switch	short	✓	\$ 135.50
2pc	Boot Lid Lamp	avg @321	✓	\$ 642.00
2pc	Boot Lid Lamp Inner Sealer	NEC @30	✓	\$ 60.00
2set	Boot Lid Lamp clip	NEC @25	✓	\$ 50.00
2pc	Boot Lid Stopper	NEC @18	✓	\$ 36.00
1pc	Boot Lid Inner Lock	bat	✓	\$ 395.00
1pc	Boot Lid Lock Cable	N/A.	X	\$ 85.00
1pc	Boot Lid Lock Catch	bat	✓	\$ 46.20
1pc	Boot Lid w/strip	dis	✓	\$ 185.00
1pc	Boot Lid Insulator	dis	✓	\$ 429.80
1set	Boot Lid Insulator Clip	NEC	✓	\$ 40.00
2pc	Boot Lid Hinge	R @125	✓	\$ 250.00
2pc	Boot Lid Hinge Cover	NEC @80	X	\$ 160.00
2set	Boot Lid Hinge Cover clip	N/A @30	X	\$ 40.00
				\$
				\$
				\$
				\$

40
20

2

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 2 of 6

TOTAL

ESTIMATE

S\$8484 G

Toyota Premio NZT260

1pc	Rear Bumper	del	✓	\$1431.60	
2pc	Rear Bumper Side Retainer	dis @95	✓	\$190.00	
1set	Rear Bumper Clip	new	✓	\$50.00	40
2pc	Rear Bumper Dampers	@82	✓	\$164.00	2VC
1pc	End Panel	bt	✓	\$265.00	
1pc	End Panel Top Trim	dis	✓	\$189.20	
1set	End Panel Top Trim Clip	new	✓	\$30.00	
1pc	Spare Tyre Panel	new	✓	\$475.50	
1pc	Spare Tyre Panel Top Board	dis	✓	\$478.20	
1pc	Spare Tyre Top Sponge Tray	NOP	X	\$172.20	
1pc	Spare Tyre Wheel Nut	bt	✓	\$56.20	
2pc	Rear Chassis Frame Member	@687.20	X	\$1374.40	2
1pc	Rear Key Antenna sensor	cv9	✓	\$192.50	
1pc	Rear Fender Rt	bt	✓	\$1100.00	
2pc	Rear Fender Inner Trim	@568	✓	\$1136.00	dis
2set	Rear Fender Inner Trim Clip	@30	✓	\$60.00	40
2pc	Rear Fender Inner shield	@92	X	\$184.00	2VC
2set	Rear Fender Inner shield clip	@25	X	\$50.00	2VC
1pc	Rear Wiperein Moulding		✓	\$175.00	1VC
1pc	Rear Wiperein Inner seal		✓	\$50.00	1VC
				\$	
				\$	
				\$	
				\$	
				\$	

[illegible]

COMPANY / GST REG. NO: 201316380R

Page 5-6

SJP 8484 G

TRAG

ESTIMATE

Toyota Premio NZT200

[illegible]

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

Page 6-6

Not Authorized
HS Repair
After paint Photo
14 Wday S
26/11/2014 LK (WTH)

Tm AIG

SJP 8484 G

ESTIMATE

Special Net

Tyoto Premio N37260

1p	Rear No Plate w/cover (Special)	SU	\$ 150	350
1p	Reverse Camera	Shop	\$ 450	350!
1set	Reverse Sensor		\$ 250	220
1p	Rear w/screen Sealant		\$ 60	40
1set	Body Panel Joint Sealant		\$ 120	80
1set	Rear Floor Panel Insulator Pad	120	\$ 150	✓
1p	Radiator Coolant		\$ 40	-
1p	Front No Plate w/cover (Special)	SU	\$ 150	150
			\$	
	Labour		\$	
1	Panel Beating		\$ 2800	2200
2	Spray Painting		\$ 2400	1800
3	Anti Rust		\$ 180	100
4	Check Wiring		\$ 100	60
5	Towing Fee		\$ 70	60
6	Remove and Install Rear w/screen		\$ 140	120
7	Remove and Install Carpet and Seat		\$ 150	80
8	Remove and Install Reverse Camera		\$ 150	80
9	Remove and Install Reverse Sensor		\$ 90	60
10	Remove and Install Rear Exhaust		\$ 120	80
11	Remove and Install Petrol Tank		\$ 120	80?
12	Remove and Install Air Con		\$ 150	120
13	To Jack and Alignment Chassis Frame Member		\$ 320	280
14	Remove and Install Rear Door Part		\$ 90	60
			\$	