



SMRT Automotive Services Pte Ltd


60 Woodlands Industrial Park E4, Singapore 757705

Tel : 65 6362 3422 Fax : 65 6368 7420

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5353T
Ref. No : TAX/12/14/2142
Reg. Date : 30/06/2010
Vehicle Type : TAXI
Make : CHRYSLER
Model : C300
Name of Driver : SEAN LIM BOON KIANG
Type of Accident : OTHERS
Date / Time of Accident : 15/12/2014 09:55:00 AM
Accident Reported Date / Time : 15/12/2014 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time : 01/01/2000
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024066867
Special Instruction to ARC, if any :
GBC9140E
after repair photo
AIG
Prepared Date : 15/12/2014 01:27:50 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : 1C3C96CM4AY108634

Mileage : 0

Work Shop :

Repair Completed Date / Time : 01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	200.00
Total Spray Painting Charges	: 473.00	200.00
Total Material Charges	: 486.72	486.72
Other Charges	: 0.00	0.00
TOTAL	: 1,297.72	886.72
Lum Sum Total	: 1,300.00	900.00
No. of Repair Days	: 3.00	2.00
Prepared / Adjusted By	:	kalvin
Prepared / Adjusted Date	: 01/01/1900 12:00:00 AM	16/12/2014 10:55:28 AM



Prepared Date : 15/12/2014 05:07:18 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00	200.00
Total Labour	338.00	200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	473.00	200.00
Total Spray Painting & Panel Beating	473.00	200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
0480628 7AD	FRONT	FRONT BUMPER ASSY	1	1,830.00	100.00	0.00	Repair	Repair	No
	FRONT	MOULDING FRT BUMPER LH	1	650.00	100.00	0.00	Repair	Repair	No
8220985 2AB	COMMO N	FRONT BONNET GRILLE	1	676.00	10.00	608.40	Replace	Replace	No
TOTAL MATERIALS						486.72			