

TRANS-CAB AUTO SERVICES PTE LTD

NO 466-468 Tagore Industrial Avenue Singapore 787835
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G

SHB9939C - AXA**ROEL**

Not Authen
1.B.1
8 2277.16

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 9939C - ROEL
 VF1ABL15AUC273307
 RENAULT
 LATITUDE
 29.01.15
AXA

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>Bu</i> 807.32 ✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sm</i> 253.00 X
3	1	BUMPER BEAM FRT	\$	<i>R</i> 585.95 X
4	1	BUMPER RETAINER FRT LH	\$	<i>Dis</i> 97.06 ✓
5	1	BUMPER SUPPORT FRT LH	\$	<i>Sm</i> 15.31 X
6	1	BONNET	\$	<i>R</i> 1,244.63 X
7	1	AIR CLEANER LOWER	\$	<i>Sm</i> 226.05 X
8	1	STEERING PUMP ELECTRIC	\$	<i>Sm</i> 1,285.90 X
9	1	HEADLAMP LH	\$	<i>Sm</i> 759.25 X
10	1	FENDER PANEL FRT LH	\$	<i>By</i> 502.46 ✓
11	1	FENDER WHEELARCH FRT LH	\$	<i>Sm</i> 89.44 X
12	1	LOWER ARM LH	\$	<i>Sm</i> 439.59 X
13	1	KUNCKLE ARM LH	\$	<i>Sm</i> 542.94 X
14	1	ABSORBER FRT LH	\$	<i>Sm</i> 231.12 X
15	1	DOOR MIRROR LH	\$	<i>Sm</i> 950.90 X
16	1	DOOR PANEL FRT LH	\$	<i>R</i> 1,823.50 X
17	1	DOOR SEAL FRT LH	\$	<i>SK</i> 46.68 X

TOTAL	\$	9,901.10
10%	\$	990.11
	\$	8,910.99

Specical Nett

1SET	FRONT BUMPER CLIP	\$	<i>nu</i> 66.00 ✓
1SET	BUMPER RETAINER CLIP FRT LH	\$	<i>nu</i> 15.20 X
1SET	WHEELARCH CLIP (Necessary)LH	\$	<i>nu</i> 66.00 X
1	CAP HUB LH FRT	\$	<i>Sm</i> 35.00 X
1	RIM LH FRT	\$	<i>Sm</i> 385.00 X
1	TYRE LH FRT	\$	<i>Sm</i> 330.00 X
1	DOOR STICKER "Trans-cab"	\$	<i>nu</i> 80.00 X
1	DOOR STICKER "Classic"	\$	<i>nu</i> 30.00 X

TOTAL	\$	1,007.20
--------------	-----------	-----------------

TOTAL PARTS	\$	9,918.19
--------------------	-----------	-----------------

TRANS-CAB AUTO SERVICES PTE LTD

NO 466-468 Tagore Industrial Avenue Singapore 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHB9939C - AXA**ROEL**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	400/
To Check Electrical Lighting Concerned.	\$	170.00	15/
Putty and spray painting of the affected portion.	\$	3,000.00	440/
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	220.00	60/
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	~ 170.00 X
To rust-proofing of the affected areas.	\$	170.00	30/

TOTAL \$ 6,700.00**Over All Total \$ 16,618.19****(PARTS BY PARTS) Repair Days****~~10 DAYS~~***2 1/2 days*