

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5094K - EQ

ROEL

Not Authorized

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC 5094K - ROEL
 VF1ABL15AUC276050
 RENAULT
 LATITUDE
 03.02.2015
EQ

		PART		LIST
1	1	BUMPER COVER FRT	\$	Tn 807.32 ✓
2	1	BUMPER SPOILER FRT	\$	M1 116.51 ✓
3	1	BUMPER ABSORBER FRT	\$	CR 253.00 ✓
4	1	BUMPER BRACKET FRT LH	\$	N 97.06 X
5	1	BUMPER SUPPORT FRT LH	\$	Sm 15.31 X
6	1	BUMPER BRACKET FRT RH	\$	B1 96.65 ✓
7	1	BUMPER SUPPORT FRT RH	\$	M1 15.31 ✓
8	1	BUMPER UNDERTRAY FRT	\$	CR 303.09 ✓
9	1	BUMPER GRILLE LOWER FRT	\$	D1 171.03 ✓
10	1	BUMPER FOG LAMP GRILLE LH	\$	Sm 132.83 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	M1 132.83 ✓
12	1	BUMPER BEAM FRT	\$	B1 585.95 ✓
13	1	RADAI TOR GRILLE	\$	CR 1,094.73 ✓
14	1	RADAI TOR GRILLE BADGE 'RENAULT'	\$	M1 144.46 ✓
15	1	RADAI TOR GRILLE FRAME	\$	CR 867.79 ✓
16	1	FRAME FULL SUPPORT PANEL	\$	CR 394.81 ✓
17	1	FRAME FULL SUPPORT BRACKET	\$	57.56 ?
18	1	FRONT BRACE PANEL	\$	D1 113.60 ✓
19	1	SUBFRAME OUTER FRT	\$	B1 1,700.29 ✓
20	1	SUBFRAME INNER FRT	\$	1,464.62 ?
21	1	SUBFRAME SUPPORT INNER	\$	59.20 ?
22	1	SUBFRAME BRACKET OUTER LH	\$	59.20 ?
23	1	SUBFRAME BRACKET OUTER RH	\$	59.20 ?
24	1	SUBFRAME BRACKET INNER LH	\$	115.37 ?
25	1	SUBFRAME BRACKET INNER RH	\$	115.37 ?
26	1	LOWER ARM LH	\$	Sm 439.59 X
27	1	LOWER ARM RH	\$	B1 439.59 ✓
28	1	KUNCKLE ARM LH	\$	B1 542.94 X
29	1	KUNCKLE HUB+BEARING LH/RH	\$	M1 319.03 ✓
30	1	KUNCKLE ARM SHIELD LH	\$	84.25 ?
31	1	KUNCKLE ARM PLATE LH	\$	111.57 ?
32	1	BRAKE DISC FRT	\$	176.59 ?
33	1	KUNCKLE ARM RH	\$	B1 542.94 ✓
34	1	KUNCKLE HUB+BEARING LH/RH	\$	Sm 319.03 X
35	1	KUNCKLE ARM SHIELD RH	\$	84.25 ?
36	1	KUNCKLE ARM PLATE RH	\$	111.57 ?
37	1	BRAKE DISC FRT	\$	Sm 176.59 X
38	1	ABSORBER FRT LH	\$	Sm 231.12 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG

SHC 5094K**ROEL**

39	1	ABSORBER MOUNTING KIT LH	\$	Sm	282.47	X
40	1	ABSORBER DUST COVER	\$	Sm	146.61	X
41	1	ABSORBER FRT RH	\$	Bt	231.12	✓
42	1	ABSORBER MOUNTING KIT RH	\$		282.47	?
43	1	ABSORBER DUST COVER	\$		146.61	?
44	1	STABILIZER BAR FRT	\$		387.60	?
45	1	STABILIZER LINK FRT	\$		75.14	?
46	1	BRAKE CALIPER FRT LH	\$	Sm	421.12	X
47	1	BRAKE CALIPER BRACKET FRT LH	\$	Sm	355.84	X
48	1	ABS SENSOR FRT LH	\$	Sm	163.94	X
49	1	BRAKE PAD FRT	\$	Sm	159.52	X
50	1	BRAKE CALIPER FRT RH	\$		421.12	?
51	1	BRAKE CALIPER BRACKET FRT RH	\$		355.84	?
52	1	ABS SENSOR FRT RH	\$		163.94	?
53	1	BRAKE HOSE FRT LH	\$	Sm	80.58	X
54	1	BRAKE HOSE FRT RH	\$		80.58	?
55	1	DRIVESHAFT LH	\$	R	1,227.43	X
56	1	DRIVESHAFT RH	\$	Bt	1,120.16	✓
57	1	SEATBELT BUCKLE LH	\$		630.86	?
58	1	SEATBELT BUCKLE RH	\$		608.84	?
59	1	SEATBELT LH	\$	Ta	1,883.21	✓
60	1	SEATBELT RH	\$	Ta	1,875.24	✓
61	1	PASSENGER AIRBAG	\$	Bt	2,187.44	✓
62	1	PASSENGER AIRBAG COMPUTER	\$	Sm	807.58	✓
63	1	PASSENGER AIRBAG SENSOR	\$	Sm	464.51	✓
64	1	STEERING AIRBAG	\$	Bt	1,619.07	✓
65	1	STEERING AIRBAG SENSOR	\$	Sm	185.45	✓
66	1	STEERING AIRBAG COMPUTER	\$		807.58	?
67	1	ROTARY SWITCH	\$		803.28	?
68	1	DASHBOARD	\$	Ta	3,141.37	✓
69	1	GLOVE BOX	\$		666.53	?
70	1	GLOVE BOX FLAP	\$	Sm	819.85	✓
71	1	HEADLAMP LH	\$	ngt	759.25	✓
72	1	HEADLAMP HARNESS LH	\$		595.06	?
73	1	HEADLAMP PANEL FRT LH	\$		112.16	?
74	1	HEADLAMP RH	\$	Bt	759.25	✓
75	1	HEADLAMP HARNESS RH	\$		595.06	?
76	1	HEADLAMP PANEL FRT RH	\$	Bt	112.16	✓
77	1	HORN L70Y LH	\$	Sm	201.39	X
78	1	HORN L70Y RH	\$	Sm	201.39	X
79	1	HORN BRACKET	\$	R	25.93	X
80	1	BONNET	\$	Bt	1,244.63	✓
81	1	BONNET INSULATOR	\$	Sm	260.08	X
82	1	BONNET STRUT LH	\$	Pr	138.58	✓
83	1	BONNET STRUT RH	\$	Pr	138.58	✓
84	1	BONNET HINGE LH	\$	Bt	223.27	✓
85	1	BONNET HINGE RH	\$	Bt	223.27	✓
86	2	BAL HOOD	\$		63.00	?

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5094K - EQ**ROEL**

87	1	BONNET LOCK	\$
88	1	BONNET CABLE	\$
89	1	BONNET CABLE COVER	\$
90	1	BONNET SEAL OUTER	\$
91	1	FENDER PANEL FRT LH	\$
92	1	FENDER PANEL FRT RH	\$
93	1	WHEELARCH FRT LH	\$
94	1	WHEELARCH FRT RH	\$
95	1	FENDER INSULATOR LH	\$
96	1	FENDER INSULATOR RH	\$
97	1	FENDER PANEL BRACKET FRT RH	\$
98	1	FENDER PANEL BRACKET FRT LH	\$
99	1	CHASSIS PANEL FRT RH	\$
100	1	CHASSIS PANEL SUPPORT FRT RH (SIDE)	\$
101	1	WHEEL HOUSING PANEL FRT RH	\$
102	1	CHASSIS PANEL FRT LH	\$
103	1	CHASSIS PANEL SUPPORT FRT LH (SIDE)	\$
104	1	WHEEL HOUSING PANEL FRT LH	\$
105	1	RADIATOR	\$
106	1	RADIATOR MTG LOWER	\$
107	1	RADIATOR FAN COWLING	\$
108	1	RADIATOR FAN MOTOR LH	\$
109	1	RADIATOR FAN MOTOR RH	\$
110	1	RADIATOR TANK	\$
111	1	RADIATOR TANK CAP	\$
112	1	RADIATOR HOSE UPPER	\$
113	1	RADIATOR HOSE LOWER	\$
114	1	RADIATOR TANK HOSE	\$
115	1	WIPER RESERVOIR	\$
116	1	WIPER RESERVOIR NECK	\$
117	1	WIPER RESERVOIR MOTOR	\$
118	1	AIR CLEANER HOSE	\$
119	1	AIR CLEANER LOWER	\$
120	1	ENGINE UNDERTRAY	\$
121	1	A/C CONDENSER	\$
122	1	A/C CONDENSER GARNISH LH UPPER	\$
123	1	A/C CONDENSER GARNISH RH UPPER	\$
124	1	A/C CONDENSER GARNISH LH	\$
125	1	A/C CONDENSER GARNISH RH	\$
126	1	A/C PIPE CONDENSER TO COMPRESSOR	\$
127	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$
128	1	A/C PIPE COMPRESSOR	\$
129	1	A/C PIPE	\$
130	1	A/C COMPRESSOR	\$
131	1	TRANSMISSION COOLER	\$
132	1	AIR INTERCOOLER HOSE (LONG)	\$
133	1	ALTERNATOR	\$
134	1	DOOR PANEL FRT LH	\$

Bt	195.82	✓
Im	76.41	✓
	103.22	?
Cvt	59.20	✓
Per	502.46	✓
Bt	502.46	✓
San	89.44	X
CRA	178.74	✓
San	83.87	X
	83.87	?
	134.60	?
R	91.84	X
Bt	510.05	✓
	404.80	?
R	3,001.34	?
R	814.79	X
R	404.80	X
R	3,001.34	X
	770.64	?
	35.80	?
	525.99	?
	620.10	?
	948.37	?
	208.09	?
	31.63	?
Per	154.20	✓
Per	314.86	✓
	39.22	?
	159.14	?
	23.15	?
	84.12	?
	48.81	?
	259.96	?
CRA	362.17	✓
Bt	1,295.11	✓
	25.43	?
	25.43	?
	37.70	?
	38.20	?
	133.58	?
	422.26	?
	214.29	?
	422.26	?
Poll/hous CRA	1,720.91	✓
	710.55	?
	650.08	?
	1,688.65	?
R	1,823.50	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5094K - EQ**ROEL**

135	1	DOOR PANEL FRT RH	\$	1,823.50	✓
136	1	DOOR MIRROR RH	\$	950.90	✓
137	1	DOOR SEAL FRT RH	\$	42.44	✓
138	1	DOOR FINISHER FRT RH	\$	330.17	?
139	1	DOOR MOULDING FRT RH	\$	113.34	✓
140	1	DOOR HINGE UPPER RH	\$	167.49	✓
141	1	DOOR HINGE LOWER RH	\$	192.66	✓
142	1	ROCKER PANEL OUTER RH	\$	633.01	X
143	1	WINDSCREEN FRT	\$	1,106.12	✓
144	1	ROOF SIDE PANEL OUTER RH	\$	451.42	✓
145	1	"V" BELT	\$	158.13	?
146	1	INJECTION COMPUTER M9R839	\$	2,349.61	?
147	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	3,799.81	?
148	1	ENGINE HARNESS L70Y	\$	4,161.05	?
149	1	BATTERY	\$	352.68	?
150	1	BATTERY CONTROL BOX	\$	571.65	?
151	1	BASE BATTERY TRAY	\$	364.57	?
152	1	COVER BATTERY TRAY BASE	\$	18.09	?
153	1	SEN CURRENT	\$	457.17	?
154	1	STEERING PUMP ELECTRIC	\$	1,285.90	?
155	1	STEERING HOSE	\$	384.78	?
156	1	STEERING HOSE	\$	214.94	?
157	1	ENGINE COMPLETE	\$	32,589.94	X
158	1	ENGINE OIL SUMP	\$	310.68	X
159	1	AUTO GEARBOX	\$	26,347.17	X
160	1	STERING HOSE LOW PRESSURE LONG	\$	442.50	?
161	1	STERING HOSE LOW PRESSURE LONG	\$	247.18	?
162	1	ARMREST-SHIFT LEVER	\$	1,014.80	?
163	1	FASCIA-CONSOLE	\$	1,478.00	?

TOTAL	\$	147,200.95
10%	\$	14,720.10
	\$	132,480.86

Specical Nett

1SET	RADAITOR GRILLE FRAME CLIP	\$	52.00	✓
1	TOW COVER FRT	\$	14.50	✓
1SET	RADAITOR GRILLE SCREW	\$	16.00	✓
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	✓
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	✓
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	✓
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	✓
4	FRAME FULL SUPPORT PANEL SCREW	\$	80.00	✓
2	BONNET CABLE CLIP	\$	6.40	✓
1SET	WHEELARCH CLIP LH	\$	30.50	X
1SET	WHEELARCH CLIP RH	\$	29.40	✓
1SET	DOOR CASING CLIP	\$	6.40	?

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5094K - EQ**ROEL**

1SET	DOOR SEAL CLIP FRT RH	\$	18.50	✓
1	DOOR STICKER "TRANS-CAB" LH	\$	80.00	60.00 X
1	DOOR STICKER "CLASSIC" LH	\$	30.00	15.00 X
1	DOOR STICKER "TRANS-CAB" RH	\$	80.00	80.00
1	DOOR STICKER "CLASSIC" RH	\$	30.00	15.00
1SET	BUMPER RR CLIP	\$	60.00	X
1SET	BUMPER UNDERTRAY SCREW	\$	2.70	✓
2	Front windscreen sealant	\$	80.00	40.00 ✓
2	Front windscreen moulding	\$	100.00	✓
2	"E.R.P" Sticker	\$	65.00	26.00
1SET	NUMBER PLATE WITH HOLDER	\$	140.00	45.00
1	DASHBOARD SCREW	\$	55.55	?
1	CAP HUB RH FRT	\$	35.00	X
1	RIM RH FRT	\$	385.00	50.00
1	TYRE RH FRT	\$	330.00	70.00
1	CAP HUB LH FRT	\$	35.00	X
1	RIM LH FRT	\$	385.00	X
1	TYRE LH FRT	\$	330.00	X

TOTAL \$ 2,665.95**TOTAL PARTS \$ 135,146.81**

Towing Fees.	\$	120.00	60.00
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	16,800.00	2400.00
Putty and spray painting of the affected portion.	\$	18,000.00	1760.00
To rust-proofing of the affected areas.	\$	170.00	150.00
To vacuum, replace, refix and recharge Air - condenser	\$	380.00	100.00
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	50.00
To replace, refix and top up coolant for radiator	\$	170.00	50.00

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5094K - EQ**ROEL**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100%
To check steering geometry and computer wheel alignment	\$	220.00	60%
To transfer of tire, rim and on wheel balancing.	\$	170.00	20%
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	240%
To remove and renew engine and gear box mounting.	\$	380.00	} 300%
To dismantle and refit engine cross-member and engine mounting.	\$	380.00	
To lift-up engine with gear box and refit.	\$	440.00	
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	80%
To check ABS brake efficiency, final checking and testing.	\$	380.00	30%
To remove and refit ABS pump relay to enable repair.	\$	380.00	?
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	} 250%
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	60%
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	nn 380.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5094K - EQ**ROEL**

To vacuum, replace, refix and recharge air condenser	\$	<i>Replaced</i> 380.00 X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 <i>1200</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>400</i>
TOTAL	\$	41,390.00
Over All Total	\$	176,536.81

< parts by parts > Repair Days

60 DAYS*21 days*