



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SJY147K
Date of Accident : 29 January 2014

Messrs Excellence Electrical Trading

Date : 30 January 2015

Estimate To Repair YK3646M - Nissan Cabstar
Chassis No : JN1SF4F23Z0840312

S/No	Quantity	Description	Amount
01	1 pc	<u>LIST ITEMS</u> front bumper assy X Repair.	\$ 695.50
			\$ 695.50
		Less 25 %	\$ 173.88
			\$ 521.63
02	1 pc	<u>SPECIAL NETT ITEMS</u> front licence plate ✓ BT	\$ 40.00
			\$ 40.00
01		<u>LABOUR & MISC. CHARGES</u> Labour	\$ 300.00
			\$ 300.00
		Total	\$ 861.63

part by part.

After repair photos.

2 Days.

Guo Qiang. 82880282

Guo Qiang @ 11kkauto.com

11/2/15.