

# H C AUTO PTE LTD

Block 20 Sector A Sin Ming Ind. Est. # 01-20 Singapore 575678  
 Tel : 6457 0678 Fax : 6457 8287  
 Co. Reg. GST No. : 20082 0153N

Date : 25 / 02 / 2015

## ESTIMATE COSTS OF REPAIR

M/s Prime Car Rental & Taxi Services Pte. Ltd.

C/o Block 20 Sector A Sin Ming Ind. Est.

# 01-20

Singapore 575678

Dear Sir / Madam ,

Vehicle no. : SHD 2928 U - Toyota Vellfire 2.4 (A)  
 Accident date : 24 / 02 / 2015

- Not authorized*
- LKK Auto Consultants Pte Ltd
- Resurvey before/after Spray Painting.
  - Damaged parts to Display when Re-inspection.
  - Parts prices subject to confirmation.
  - Third Party Survey without prejudice.
  - No illegal modification is allowed.

*3 days*

Quantity	Descriptions	Amounts
----------	--------------	---------

1	1 pc	n/s head lamp	<i>Sec/Loc</i> \$ 1,277.90 ✓
2	1 pc	n/s head lamp centre garnish	\$ 111.60 ?
3	1 pc	front bumper fascia	<i>Bus</i> \$ 1,826.48 ✓
4	1 pc	n/s front bumper side retainer	<i>Dir</i> \$ 76.40 ✓
5	1 pc	n/s front bumper bracket	\$ 249.80 ?
6	1 pc	n/s front bumper fog lamp	\$ <i>Sm</i> 326.50 X
7	1 pc	n/s front bumper fog lamp bracket	\$ <i>Sm</i> 248.60 X
8	1 pc	n/s front bumper sensor	\$ <i>Dir</i> 378.00 ✓
9	1 set	front bumper sensor wiring	\$ 242.00 ?
10	1 pc	front bumper grille	\$ <i>Skat</i> 153.40 X
11	1 pc	front bumper lower garnish	\$ <i>Sm</i> 128.20 X
12	11 pcs	front bumper clips 1 @ 3.50	\$ <i>na</i> 39.05 ✓
13	1 pc	n/s front fender	\$ <i>R</i> 1,027.20 X
14	1 pc	n/s front fender inner garnish	\$ <i>Sm</i> 162.20 X
15	1 pc	n/s front wheel cap	\$ <i>Sm</i> 49.00 X
16	1 pc	n/s front wheel rim	<i>Del/Sec</i> \$ 1,645.10 ✓
17	1 pc	n/s front drive shaft	\$ <i>R</i> 1,543.80 X
18	1 pc	n/s front lower arm	\$ <i>Sm</i> 673.60 X
19	1 pc	n/s front kunckle arm	\$ 558.00 ?
20	1 pc	n/s front kunckle arm bearing	\$ 549.70 ?
21	1 pc	n/s front shock absorber	\$ <i>Sm</i> 421.90 X
22	1 pc	n/s front anti-roll bar side linkage	\$ <i>Sm</i> 136.00 X
			\$ 11,824.43
		Less 25%	\$ 2,956.11
		Balance C/FD	\$ 8,868.32

# H C AUTO PTE LTD

Block 20 Sector A Sin Ming Ind. Est. # 01-20 Singapore 575678

Tel : 6457 0678 Fax : 6457 8287

Co. Reg. GST No. : 20082 0153N

		Balance B/FD ( SHD 2928 U )	\$ 8,868.32
23	1 pc	n/s front wheel tyre	\$ <i>sn</i> 685.00 sn X
24	1 pc	n/s front " PRIME ROYAL LIMOUSINE"	\$ <i>na</i> 180.00 sn <i>10012</i>
25	1 pc	n/s front HYBRID emblem	\$ <i>na</i> 80.00 sn ✓
			\$ 9,813.32
		Labour charges	\$ 1,200.00 <i>500</i>
		To putty and spray painting	\$ 980.00 <i>560</i>
		To check wiring	\$ 160.00 <i>200</i>
		To re-seal anti rust	\$ <i>na</i> 250.00 X
		Remove and refix front bumper sensor	\$ 120.00 <i>500</i>
		Remove and refix front undercarriage	\$ 450.00 ?
		To check wheel alignment	\$ 80.00 <i>600</i>
			\$ 13,053.32
		Plus : 7% GST	\$ 913.73
		Grand total	\$ 13,967.06