

RICARDO AUTO CENTRE PTE LTD

BLK 20 SIN MING INDUSTRIAL ESTATE #01-30 SINGAPORE 575678
TEL: 6475 2112 FAX: 6475 4666 Email: <http://www.ricardo.com.sg>
GST:M2-0053787-4 RCB NO:198102182M



RICARDO

QUOTATION

M/S : MR MOHAMED ASBAT BIN MUNIR

BLK 3D UPPER BOON KENG ROAD #20-644

SINGAPORE 384003

H/P: 97858219

NO: WQT0800564

DATE: 26 Feb 2015

A/C CODE: C009337

YOUR REF: SKC309P

SALESMAN:

PAGE:1

Description	Quantity	Unit Price	%	Amount
		SS		SS

WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE.

DOA: 25/02/2015

ACCIDENT INVOLVING: SKC309P & SFU3331T, SJT5650S, YL5571B

CLAIM TYPE: 3RD PARTY CLAIM AGAINST SFU3331T (SFU3331T INSURED WITH AXA)

1	REAR FENDER RH ✓	1 PC	1,431.00	1,431.00
2	RH TAILLAMP ✓	1 PC	510.00	510.00
3	REAR BUMPER ✓	1 PC	937.00	937.00
4	REAR BUMPER REINFORCEMENT ✓	1 PC	589.00	589.00
5	REAR BUMPER SIDE RETAINER LH & RH ✓	2 PCS	20.00	40.00
6	REAR BUMPER CENTRE RETAINER ✓	1 PC	35.00	35.00
7	REAR BUMPER LOWER SKIRTING ✓	1 PC	600.00	600.00
8	REAR BUMPER CLIPS ✓	6 PC	4.00	24.00
9	REAR BUMPER SENSOR (4 PCS) NETT ITEM ✓	1 SET	320.00	160 320.00
10	BOOT LID ✓	1 PC	1,246.00	1,246.00
11	BOOT REFLECTOR RH ✓	1 PC	301.00	301.00
12	BOOT PLATE - CHERVOLET ✓	1 PC	28.00	28.00
13	BOOT PLATE - CRUZE LS ✓	1 PC	28.00	28.00
14	BOOT PLATE - SS ✓	1 PC	38.00	38.00
15	BOOT EMBLEM - LOGO ✓	1 PC	56.00	56.00
16	BOOT INNER TRIM ✓	1 PC	150.00	150.00
17	SPARE TYRE TRIM ?	1 PC	150.00	150.00
18	END PANEL GARNISH ?	1 PC	75.00	75.00
19	REAR END PANEL ?	1 PC	576.00	576.00
20	BOOT LOCK ✓	1 PC	248.00	248.00
21	BACK WEATHERSTRIP ✓	1 PC	180.00	180.00
22	BACK WINDSCREEN MOULDING ✓	1 PC	58.00	58.00
23	BOOT HINGE RH ✓	1 PC	48.00	48.00
24	TO CUT, WELDING & STRAIGHTEN BACK & REAR RH PARTION OF CAR CAUSED BY ACCIDENT. ADJUST & REPLACE DAMAGE PARTS.	1 SVC	1,600.00	1,600.00
25	TO TUFF COAT REPAIRED AREA.	1 SVC	100.00	100-120 60 100.00
26	TO REMOVE BACK WINDSCREEN GLASS & FIX SAME.	1 SVC	120.00	100 120.00
27	TO SUPPLY WINDSCREEN SEALANT.	1 SVC	40.00	✓ 40.00



RICARDO

RICARDO AUTO CENTRE PTE LTD

BLK 20 SIN MING INDUSTRIAL ESTATE #01-30 SINGAPORE 575678

TEL: 6475 2112 FAX: 6475 4666 Email: <http://www.ricardo.com.sg>

GST:M2-0053787-4 RCB NO:198102182M

QUOTATION

M/S : MR MOHAMED ASBAT BIN MUNIR

NO:

WQT0800564

DATE:

26 Feb 2015

PAGE:2

Description	Quantity	Unit Price	%	Amount
		S\$		S\$
WE SUBMIT HERewith OUR ESTIMATED COST OF REPAIR TO ABOVE MENTIONED VEHICLE.				
DOA: 25/02/2015				
ACCIDENT INVOLVING: SKC309P & SFU3331T, SJT5650S, YL5571B				
CLAIM TYPE: 3RD PARTY CLAIM AGAINST SFU3331T (SFU3331T INSURED WITH AXA)				
28 TO REMOVE FUEL TANK ENABLE TO REPLACE REAR FENDER & FIX SAME.	1 SVC	200.00	80.60	200.00
29 TO REMOVE CAR SEATS & ATTACHEMENT ENABLE TO REPLACE REAR FENDER & FIX SAME.	1 SVC	200.00	120.60	200.00
30 TO SPRAY PAINT ON REPAIRED AREA.	1 SVC	1,200.00	1000	1,200.00
31 SUPPLY BOWLING BALL (DURING ACCIDENT BOWLING BALL IN THE BOOT FOUND CRACK LINE) NETT ITEM.	1 PC	350.00	?	350.00
Total				S\$ 11,478.00
Add GST @ 7%				803.46
Grand Total				S\$ 12,281.46

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND TWO HUNDRED EIGHTY ONE AND CENTS FORTY SIX ONLY

MR MOHAMED ASBAT BIN MUNIR

For RICARDO AUTO CENTRE PTE LTD

CONFIRMED & ACCEPTED BY

AUTHORISED SIGNATURE

7-8 Days.

pat by pat. - before paint photos.

Guo Qiao. 82880282.

02/3 /15.