

INSURANCE OWNER: Johnson

CC 6 / III150 04746 / 63034

LKK:  
IDAC:

## ASSIGNMENT

Surveyor: X602DOI: 18.03-15Assg Date: 18.03-15

Pre-assign / CCU / FTE

Insured Vehicle No.: SHD 4515AClaim No.: MCT 15030642Name of Insured: CTPLPolicy No.: M Com 2016

Insured Tel No.: \_\_\_\_\_ HP: \_\_\_\_\_

Make / Model: HyundaiExcess Sec II :SS \_\_\_\_\_ D.O.A: 16.3-15Place of Accident: LOR 6 TOA Payoh > LorIs driver the owner? ( YES / NO ) \_\_\_\_\_ Nature of Accident: 1 X TOA PAYOH EASTIf NO, Driver Name / Age: Gov Brown Heng

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.: \_\_\_\_\_

(V/L: YES / NO Insured Liability: \_\_\_\_\_

% Final ? Yes / No

PA 7559P

INSRS:

WSP: Kevin Chiew

Tel: \_\_\_\_\_

Liability: \_\_\_\_\_

RMKS: \_\_\_\_\_

INSRS:

WSP: \_\_\_\_\_

Tel: \_\_\_\_\_

Liability: \_\_\_\_\_

RMKS: \_\_\_\_\_

INSRS:

WSP: \_\_\_\_\_

Tel: \_\_\_\_\_

Liability: \_\_\_\_\_

RMKS: \_\_\_\_\_

INSRS:

WSP: \_\_\_\_\_

Tel: \_\_\_\_\_

Liability: \_\_\_\_\_

RMKS: \_\_\_\_\_

Date/ Time

## FOR CSO ONLY:

Is driver the owner? ( YES / NO )

If NO, Driver Name / Age :

Driver's Own Vehicle Number: \_\_\_\_\_ Insurance Company: \_\_\_\_\_

## STAGE

DATE / PIC

Finalisation:

Email AJG for OI GIA:

Apt letter to OI:

Call OI:

After call ltr to OI:

Type Report:

Prepare Invoice:

Others:

Documentation Check List: Handler Typist

OI Apt Ltr:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

LTA / GIA :

Medical Bill:

Approval Email:

Payment Breakdown Form:

Others:

06/04/15 - OLD ROAD TRAFFIC LIGHT ON HIS PASSENGER  
SIDE REVERSED. OLD MAKING & EIGHT TURNS AT  
THE JUNCTION. TP GOING STRAIGHT.

6/4/15 - HAD CHECK IF CAN VIEW A CCTV.

20/4/15 - Called III for CCTV. No ans.

22/4/15 - email liability 100% to Johnson.

23/4/15 - II agreed to 100% per attached.

email liability clear to TP.

23/6/15 - Pass to X602 to finalise.

8/3/18 - email to III to temporary close

No est

RECEIVED 0 8 MAR 2010

COPY SENT  
8/3/18

## FINAL SETTLEMENT

Date :

Confirm with

OLD MAKING &amp; EIGHT TURNS

Repair Cost: \$S

Final Liability 100 % (Agreed / Assessed)

BOLA S/N No. : 5

Loss of Rental: \$S

( days)

If NO or B 28, Ass. Lia :

Loss of Use: \$S

(\$ x days)

Format Type: Temporary claim w/P

Disbursement: \$S

\$250.00

Total: \$S

Global Sum: \$S

Surveyor: Xhu.REF: III

4246/859's

**ASSIGNMENT**From: \_\_\_\_\_ Date: 18-3-15

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: PA 7559Pat Workshop m/s Kum Chew Motorof Blk 13 Sin Ming Ind Est Sec B H01-71Insured: SHD 4315A

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: PA7559P Yr Regn: 2008 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace c.c. 2494Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 483214 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KDH 2000081.905Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15CR: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. \_\_\_\_\_ D.O.I. 18-03-15Survey held at WIS 2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt & N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/3/18 confirm 4S \$2700.00 with 4 working days(AD-#6055-45 69.7)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\_\_\_\_ S + RS \_\_\_\_ SI

Photos

Others

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC6/III15004746/Gsa3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 18-03-2015		
		Code : III2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 4315A	Veh. Inspected	PA 7559P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/03/2015	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	16/03/2015	Inspection Date	18/03/2015	
Survey held at	KUM CHEW MOTOR WORKSHOP BLOCK 12 SIN MING IND. EST. SECTOR B #01-71 SINGAPORE 575656			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**KUM CHEW MOTOR WORKSHOP**

Blk 12 Sin Ming Industrial Estate Sector B

#01-71 Singapore 575656

Tel No. : 64536256/64563715 Fax No. : 64557754

E-Mail : kumchew1@singnet.com.sg

Tax Reg. No. : M90367665T Buss. Reg. No. : 52865130K

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET #04/#05

IOB BUILDING, SINGAPORE 049711

Attention : Motor Claim Department

Contact : 63476100 Fax No. : 62244174/62257743

Estimate : ES003727

Date : 08/09/2015

Vehicle Num. : PA 7559 P

Make/Model : TOYOTA HIACE

Chassis/Eng# :

Accident Date : 16/03/2015

Claim No. :

Reference : KC/TP7559/1503-04

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	FRT BONNET <i>X Repair</i>		<del>825.00</del> X
2.	1 PC	FRT BUMPER <i>Be</i>		446.20
3.	1 PC	FRT BUMPER BEAM <i>BT</i>		152.3 339.30
4.	1 PC	FRT BUMPER REINFORCEMENT <i>BT</i>		274.7 432.20
5.	1 PC	FRT BUMPER RETAINER <i>BT</i>		151.2 452.00
6.	1 PC	FRT HEADLAMP - LH <i>cut</i>		354.8 631.50
7.	1 PC	FRT HEADLAMP PANEL <i>X Repair</i>		X 325.50 X
8.	1 PC	FRT HEADLAMP CLIP - LH <i>Be</i>		5.00
9.	1 PC	TOW HOOK COVER <i>mis</i>		23 35.00
10.	1 PC	RADIATOR <i>X NN</i>		896 2,110.00 X
11.	1 PC	INTER COOLER <i>cut</i>		308.9 1,377.00
12.	1 PC	AIRCON CONDENSER <i>cut</i>		1,434.90
List Total S\$ :			2892.1	8,420.60
25.00% Discount S\$ :			21690.07	2,105.15
				6,315.45
NETT ITEMS :				
1.	1 PC	BODY LETTERING <i>Be</i>		150 200.00
2.	1 PC	COMPANY LOGO <i>X NN</i>		X 180.00
Nett Total S\$ :				380.00
LABOUR :				
TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.			400	780.00

CONTINUE / ...

From Mr. Kum Chew

To: Guo Qiang.

Thank

9/9/15

**KUM CHEW MOTOR WORKSHOP**

Blk 12 Sin Ming Industrial Estate Sector B

#01-71 Singapore 575656

Tel No. : 64536256/64563715 Fax No. : 64557754

E-Mail : kumchew1@singnet.com.sg

Tax Reg. No. : M90367665T Buss. Reg. No. : 52865130K

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET #04/#05

IOB BUILDING, SINGAPORE 049711

Attention : Motor Claim Department

Contact : 63476100 Fax No. : 62244174/62257743

**Estimate : ES003727**

Date : 08/09/2015

Vehicle Num. : PA 7559 P

Make/Model : TOYOTA HIACE

Chassis/Eng# :

Accident Date : 16/03/2015

Claim No. :

Reference : KC/TP7559/1503-04

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO SPRAY & PAINT ON ACCIDENT PORTION.	600	880.00
		TO TOP UP AIR CON GAS (R134A).	40	150.00
		TO DISMANTLE, FIX RADIATOR, AIRCON CONDENSER & INTER COOLER.	60	250.00
		Labour Total S\$ :	1100	2,060.00

3419.07

20% : 2700

4 Days.

SingDollars : Eight Thousand Seven Hundred Fifty-Five &amp; Cents Forty-Five Only

E. &amp; O.E.

Total S\$ :

8,755.45

for KUM CHEW MOTOR WORKSHOP



**Secured Message**

[Reply](#)

From: Johnson Chua - III <johnson@iii.com.sg>  
To: Meikwan@lkkauto.com  
CC: olivialau@lkkauto.com  
Date: April 3, 2015 11:28:44 PM  
Subject: III Ref: TBA; Accident involving SHD4315A (III) & PA7559P on 16.03.2015  
Attachments: [SAS-SHD4315A.pdfattachment3.txt](#)

Dear LKK,

Enclosed is a copy of our ID's report.

We agree on direct settlement.

Please proceed to handle this case under express settlement.

*Johnson Chua*

**Motor Claim Department**  
India International Insurance Pte Ltd  
64 Cecil Street #04-02 IOB Building  
Singapore 049711  
Tel: 6347 6128 Fax: 6224 4174

**INDIA**  
**INTERNATIONAL INSURANCE**  
(incorporated in Singapore)  
*Let's Grow Together*

[Reply](#)

## Sharon Yee

---

**From:** Johnson Chua - III <johnson@iii.com.sg>  
**Sent:** Monday, 27 April, 2015 11:00 AM  
**To:** Sharon Yee; Olivia Lau  
**Cc:** Mei Kwan (LKK Auto)  
**Subject:** RE: III Ref: MCT15030642/JC; Accident involving SHD4315A (III) & PA7559P on 16.03.2015

**Importance:** High

Dear Sharon,

Please proceed.

*Johnson Chua*

Motor Claim Department  
India International Insurance Pte Ltd  
64 Cecil Street #04-02 IOB Building  
Singapore 049711  
Tel: 6347 6128 Fax: 6224 4174



---

**From:** Sharon Yee [mailto:sharonyee@lkkauto.com]  
**Sent:** Tuesday, 21 April, 2015 9:58 AM  
**To:** Johnson Chua - III  
**Cc:** Mei Kwan (LKK Auto)  
**Subject:** FW: III Ref: TBA; Accident involving SHD4315A (III) & PA7559P on 16.03.2015

### PODS – Express Settlements

**PODS III Ref: PA 7559P LKK Ref: CC6/III15004746/Gsa3; Accident on 16.03.2015 involving SHD 4315A (India) and PA 7559P (TP) along LOR 6 TOA PAYOH**

Dear Johnson,

We advise liability as follows for Direct Settlement:

Liability : 100% (e.g. 50% or 100%)

Officer-In-Charge Mandate : \_\_\_\_\_ (e.g. agree or disagree)

Remarks : OID was making a right turn from Lor 6 Toa Payoh towards Toa Payoh East and collided with TP (PA 7559P) who was travelling along Lor 6 Toa Payoh. We are in the opinion that OID should exercise more cautious when turning. Therefore, BOLA 5 applies. Kindly provide CCTV from OID if possible.

Thank you

Best Regards,

**Sharon Yee** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [sharonyee@lkkauto.com](mailto:sharonyee@lkkauto.com) | fax: 6741-

4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Olivia Lau

**Sent:** Monday, 6 April, 2015 9:27 AM

**To:** Admin A

**Cc:** Sharon Yee

**Subject:** FW: III Ref: TBA; Accident involving SHD4315A (III) & PA7559P on 16.03.2015

Dear Admin Support,

Please refer to instructions in attachment.

Our ref: CC6/III15004746/Gsa3

Best Regards,

**Olivia Lau** | Admin Manager

**LKK Auto Consultants**

phone: 6256-3561 | email: [olivialau@lkkauto.com](mailto:olivialau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Johnson Chua - III [<mailto:johnson@iii.com.sg>]

**Sent:** Saturday, 4 April, 2015 7:29 AM

**To:** Mei Kwan (LKK Auto)

**Cc:** Olivia Lau

**Subject:** III Ref: TBA; Accident involving SHD4315A (III) & PA7559P on 16.03.2015

**You have received a secure message**

**Read your secure message by opening the attachment, [securedoc.html](#).** You will be prompted to open (view) the file or save (download) it to your computer. For best results, save the file first, then open it in a Web browser. To access from a mobile device, forward this message to [mobile@res.cisco.com](mailto:mobile@res.cisco.com) to receive a mobile login URL.

If you have concerns about the validity of this message, contact the sender directly.



**Vivian Lau (LKKAuto)**

**From:** Vivian Lau (LKKAuto)  
**Sent:** Thursday, 8 March, 2018 8:38 AM  
**To:** Gabriel Wee; 'motorclaim@iii.com.sg'  
**Cc:** Admin A  
**Subject:** RE: III Ref: MCT15030642/JC; Accident involving SHD4315A (III) & PA7559P on 16.03.2015

## **PODS – Express Settlements**

**PODS III Ref: PA 7559P LKK Ref: CC6/III15004746/Gsa3; Accident on 16.03.2015 involving SHD 4315A (India) and PA 7559P (TP) along LOR 6 TOA PAYOH**

Dear Sir/Madam,

We refer to the above matter.

Be informed that till date TP's repairer had finalised with our surveyor since 16/03/2015 after inspection.

TP's repairer did not submit the LOD until now. In view of no further development, we will proceed to temporary close the file and submit the report to your office.

If any new development in future, we will keep you informed for an update and follow up the matter accordingly

Thank you

Best Regards,

**Vivian Lau** Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-8625 | email: [Vivianlau@lkkauto.com](mailto:Vivianlau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Mei Kwan (LKKAuto)

**Sent:** Thursday, 8 March, 2018 8:31 AM

**To:** Vivian Lau (LKKAuto) <[vivianlau@lkkauto.com](mailto:vivianlau@lkkauto.com)>

**Subject:** FW: III Ref: MCT15030642/JC; Accident involving SHD4315A (III) & PA7559P on 16.03.2015

**Importance:** High

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Johnson Chua - III [<mailto:johnson@iii.com.sg>]

**Sent:** Monday, 27 April, 2015 11:00 AM

**To:** Sharon Yee <[sharonyee@lkkauto.com](mailto:sharonyee@lkkauto.com)>; Olivia Lau <[olivialau@lkkauto.com](mailto:olivialau@lkkauto.com)>

**Cc:** Mei Kwan (LKK Auto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>

**Subject:** RE: III Ref: MCT15030642/JC; Accident involving SHD4315A (III) & PA7559P on 16.03.2015

**Importance:** High

Dear Sharon,

Please proceed.

*Johnson Chua*

Motor Claim Department  
India International Insurance Pte Ltd  
64 Cecil Street #04-02 IOB Building  
Singapore 049711  
Tel: 6347 6128 Fax: 6224 4174

**INDIA**

INTERNATIONAL INSURANCE

*Let's Grow Together*

**From:** Sharon Yee [<mailto:sharonyee@lkkauto.com>]

**Sent:** Tuesday, 21 April, 2015 9:58 AM

**To:** Johnson Chua - III

**Cc:** Mei Kwan (LKK Auto)

**Subject:** FW: III Ref: TBA; Accident involving SHD4315A (III) & PA7559P on 16.03.2015

### PODS – Express Settlements

**PODS III Ref: PA 7559P LKK Ref: CC6/III15004746/Gsa3; Accident on 16.03.2015 involving SHD 4315A (India) and PA 7559P (TP) along LOR 6 TOA PAYOH**

Dear Johnson,

We advise liability as follows for Direct Settlement:

Liability : 100% (e.g. 50% or 100%)

Officer-In-Charge Mandate :                      (e.g. agree or disagree)

Remarks : OID was making a right turn from Lor 6 Toa Payoh towards Toa Payoh East and collided with TP (PA 7559P) who was travelling along Lor 6 Toa Payoh. We are in the opinion that

OID should exercise more cautious when turning. Therefore , BOLA 5 applies. Kindly provide CCTV from OID if possible.

Thank you

Best Regards,

**Sharon Yee** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749-4274 | email: [sharonyee@lkkauto.com](mailto:sharonyee@lkkauto.com) | fax: 6741-

4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Olivia Lau

**Sent:** Monday, 6 April, 2015 9:27 AM

**To:** Admin A

**Cc:** Sharon Yee

**Subject:** FW: III Ref: TBA; Accident involving SHD4315A (III) & PA7559P on 16.03.2015

Dear Admin Support,

Please refer to instructions in attachment.

Our ref: CC6/III15004746/Gsa3

Best Regards,

**Olivia Lau** | Admin Manager

**LKK Auto Consultants**

phone: 6256-3561 | email: [olivialau@lkkauto.com](mailto:olivialau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Johnson Chua - III [<mailto:johnson@iii.com.sg>]

**Sent:** Saturday, 4 April, 2015 7:29 AM

**To:** Mei Kwan (LKK Auto)

**Cc:** Olivia Lau

**Subject:** III Ref: TBA; Accident involving SHD4315A (III) & PA7559P on 16.03.2015

**You have received a secure message**

**Read your secure message by opening the attachment, securedoc.html.** You will be prompted to open (view) the file or save (download) it to your computer. For best results, save the file first, then open it in a Web browser. To access from a mobile device, forward this message to [mobile@res.cisco.com](mailto:mobile@res.cisco.com) to receive a mobile login URL.

If you have concerns about the validity of this message, contact the sender directly.

**First time users** - will need to register after opening the attachment. For more information, click the following Help link.

**Help** - <https://res.cisco.com/websafe/help?topic=RegEnvelope>

**About Cisco Registered Email Service** - <https://res.cisco.com/websafe/about>

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.


Registration No. 198703792-K

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC6/III15004746/Gwa3q2	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 09-03-2018	
		Code : III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHD 4315A	Veh. Inspected	PA 7559P
Policy No.	MCOM0016	Coverage (\$)	0.00
Claim No.	MCT15030642/JC	Excess (\$)	0.00
Assign From		Assign Date	18/03/2015
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA HIACE	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	KDH2000081905	Colour	SILVER
Odometer	483214	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195 R15C	ACHILLES	6 mm
L/H Front Tyre	195 R15C	ACHILLES	6 mm
R/H Rear Tyre	195 R15C	ACHILLES	6 mm
L/H Rear Tyre	195 R15C	ACHILLES	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	18/03/2015	Inspection Date	18/03/2015
Survey held at	KUM CHEW MOTOR WORKSHOP BLOCK 12 SIN MING IND. EST. SECTOR B #01-71 SINGAPORE 575656		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 7559P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRT BONNET	TO REPAIR SEE LABOUR	835.00	-
1	FRT BUMPER	DEFORMED	446.20	446.20
1	FRT BUMPER BEAM	BENT	339.30	152.30
1	FRT BUMPER REINFORCEMENT	BENT	432.20	274.70
1	FRT BUMPER RETAINER	DEFORMED	452.00	151.20
1	FRT HEADLAMP -LH	CUT	631.50	554.80
1	FRT HEADLAMP PANEL	TO REPAIR SEE LABOUR	325.50	-
1	FRT HEADLAMP CLIP -LH	NECESSARY	5.00	5.00
1	TOW HOOK COVER	MISSING	35.00	23.00
1	RADIATOR	NOT NECESSARY	2,110.00	-
1	INTER COOLER	CUT	1,377.00	896.00
1	AIRCON CONDENSER	CUT	1,431.90	388.90
	LESS 25% DISCOUNT		-2,105.15	-723.03
			6,315.45	2,169.07
<b>SPECIAL NETT ITEMS</b>				
1	BODY LETTERING (SN)	NECESSARY	200.00	150.00
1	COMPANY LOGO (SN)	NOT NECESSARY	180.00	-
			380.00	150.00
<b>LABOUR</b>				
	TO PULL ,KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.INCLUSIVE OF THE REPAIR OF FRT BONNET AND FRT HEADLAMP PANEL .		780.00	400.00
	TO SPRAY & PAINT ON ACCIDENT PORTION.		880.00	600.00
	TO TOP UP AIR CON GAS (R134A).		150.00	40.00
	TO DISMANTLE ,FIX RADIATOR ,AIRCON CONDENSER & INTER COOLER.		250.00	60.00
			2,060.00	1,100.00
<b>GRAND TOTAL</b>			<b>8,755.45</b>	<b>3,419.07</b>

Report Ref No. CC6/III15004746/Gwa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00
---	--	--	----------

Report Ref No. CC6/III15004746/Gwa3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.